

Photo Album for Newbrook, VT

Job # 29192

W/O # 19352537

April 22, 2016

This week the chassis continued on the chassis prep line and cab electrical content began installation. The lower body modules finished body assembly and the water tank continued with the paint process. Next week the chassis should continue on the chassis prep line.

The pump house will begin assembly, the body modules should remain in staging and the water tank should finish the paint process.

Pierce		QUALITY SYSTEM FORM		QSF10-0836
Title: Window Sheet		Effective Date: 12/01/14 Page 1 of 1		
PWO #:	19352537	Job #:	29192	
Chassis Color:	*90 Red	Top Color:	(Two Tone)	
VIN #:	1FVHCYCYXGHHF9473			
Customer:	Newbrook FD			
Contract Manager:	Christina Mori			
RFP Date:	5/9/16			
Rework Number:				
<u>CONFIGURATION</u>				
☐	PUMPER			
☒	TANKER			
☐	RESPONDER			
☐	RESCUE			
☐	BRUSH TRUCK			
☐	OTHER:			

DSC06601




DSC06602



DSC06603



DSC06604



DSC06605



DSC06606



DSC06607



DSC06608



DSC06609



DSC06610



DSC06611



DSC06612



DSC06614




DSC06615



DSC06616



DSC06617



DSC06618



DSC06619



DSC06620




DSC06621



DSC06622



DSC06624



DSC06626



DSC06627



DSC06628



DSC06630



DSC06631



DSC06632



DSC06633



DSC06636



DSC06637



DSC06638



DSC06832



DSC06833



DSC06834



DSC06835



DSC06836



DSC06837



DSC06838



DSC06839



DSC06840



DSC06841



DSC06842



DSC06843