

Photo Album for Newbrook, VT

Job # 29192

W/O # 19352537

April 29, 2016

This week the chassis continued on the chassis prep line and is nearing completion. The pump house began assembly, while the body modules remained in staging and the water tank continued with the paint process. Next week your truck should begin final assembly after having the pump house, body modules and water tank mounted on the chassis.

QUALITY SYSTEM FORM		QSF10-0836
Title: Window Sticker		Effective Date: 12/01/14
		Page 1 of 1
PWO #: <u>19352537</u>	Job #: <u>29192</u>	
Chassis Color: <u>*90 Red</u>	Top Color: (Two Tones)	
VIN #: <u>1FVHCYCYXGHHF9473</u>		
Customer: <u>Newbrook FD</u>		
Contract Manager: <u>Christina Mori</u>		
RFP Date: <u>5/9/16</u>		
Rework Number: _____		
<u>CONFIGURATION</u>		
☐ PUMPER ☒ TANKER ☐ RESPONDER ☐ RESCUE ☐ BRUSH TRUCK ☐ OTHER: _____		

DSC06592



DSC06593



DSC06594



DSC06595



DSC06596



DSC06597



DSC06598



DSC06599



DSC06600



DSC06601




DSC06602



DSC06603



DSC06604



DSC06605



DSC06606



DSC06607



DSC06608



DSC06609



DSC06610



DSC06611



DSC06612



DSC06613




DSC06614



DSC06615



DSC06616



DSC06617



DSC07055



DSC07056



DSC07057




DSC07058



DSC07059




DSC07060



DSC07061



DSC07062



DSC07141



DSC07142



DSC07143



DSC07144



DSC07145



DSC06267



DSC06268



DSC06269