

Photo Album for Newbrook, VT

Job # 29192

W/O # 19352537

May 6, 2016

This week your truck began final assembly after having the pump house mounted on the chassis. The lower body modules are set to be mounted on the chassis, along with the water tank. Next week your truck should continue with final assembly after the body and water tank are joined with the chassis. Additional option content should be added.

QUALITY SYSTEM FORM QSF10-0836
Title: Window Sheet Effective Date: 12/01/14 Page 1 of 1

PWO #: 19352537 Job #: 29192
Chassis Color: *90 Red Top Color: (Two Tone)
VIN #: 1FVHCYCYXGHHF9473
Customer: Newbrook FD
Contract Manager: Christina Mori
RFP Date: 5/9/16
Rework Number: _____

CONFIGURATION

☐ PUMPER
☒ TANKER
☐ RESPONDER
☐ RESCUE
☐ BRUSH TRUCK
☐ OTHER: _____

DSC06899



DSC06900



DSC06901



DSC06902



DSC06903



DSC06904



DSC06905



DSC06906



DSC06907




DSC06908



DSC06909



DSC06911



DSC06912




DSC06913



DSC06914



DSC06915



DSC06916



DSC06917



DSC06918



DSC06919



DSC06920



DSC06921



DSC06922



DSC06923




DSC06924



DSC06925



DSC06926




DSC06927



DSC06928




DSC06929



DSC06930



DSC06931



DSC06999



DSC07000



DSC07001



DSC07002



DSC07003



DSC07015



DSC07016



DSC07017



DSC07018



DSC07019