

Photo Album for Newbrook, VT

Job # 29192

W/O # 19352537

May 13, 2016

This week your truck continued with final assembly. The water tank and lower body modules were mounted on the chassis. Additional option content is in the process of being installed. Next week it should finish with assembly and could be released to begin initial and third party pump testing.

| QUALITY SYSTEM FORM | | QSF10-0836 |
|--|-----------------------|--------------------------|
| Title: Window Sheet | | Effective Date: 12/01/14 |
| Page 1 of 1 | | |
| PWO #: <u>19352537</u> | Job #: <u>29192</u> | |
| Chassis Color: <u>*90 Red</u> | Top Color: (Two Tone) | |
| VIN #: <u>1FVHCYCYXGHHF9473</u> | | |
| Customer: <u>Newbrook FD</u> | | |
| Contract Manager: <u>Christina Mori</u> | | |
| RFP Date: <u>5/9/16</u> | | |
| Rework Number: | | |
| <u>CONFIGURATION</u> | | |
| <input type="checkbox"/> PUMPER <input checked="" type="checkbox"/> TANKER <input type="checkbox"/> RESPONDER <input type="checkbox"/> RESCUE <input type="checkbox"/> BRUSH TRUCK | | |

DSC06486



DSC06487



DSC06488



DSC06489



DSC06490



DSC06491



DSC06492



DSC06493



DSC06494



DSC06495



DSC06496



DSC06497



DSC06498



DSC06499



DSC06500



DSC06501



DSC06502



DSC06503



DSC06504



DSC06505



DSC06506



DSC06507



DSC06508