

Photo Album for Newbrook, VT

Job # 29192

W/O # 19352537

May 20, 2016

This week your truck finished assembly and was released to begin initial and third party pump testing. Next week it should continue with testing and could begin final product evaluation, which is part of the quality process.

QUALITY SYSTEM FORM		CSE18-0836
Title: Worksheet		Effective Date: 12/01/14
Page: 1 of 3		
PWO #: <u>19552537</u>	Job #: <u>29192</u>	
Chassis Color: <u>990 Red</u>	Top Color: <u>(Tan/White)</u>	
VIN #: <u>1FVHCYCYXGHHF9473</u>		
Customer: <u>Newbrook FD</u>		
Contract Manager: <u>Christina Mori</u>		
RFP Date: <u>5/9/16</u>		
Rework Number:		
<u>CONFIGURATION</u>		
☐ PUMPER ☒ TANKER ☐ RESPONDER ☐ RESCUE ☐ BRUSH TRUCK ☐ OTHER:		
Customer's 192-1-1000 Chassis?	Yes	☒
Customer's 192-1-1000 Chassis?	Yes	☒

DSC07381



DSC07382



DSC07383



DSC07384



DSC07385



DSC07386



DSC07387



DSC07388



DSC07389



DSC07390



DSC07391



DSC07392



DSC07393



DSC07394



DSC07395



DSC07396



DSC07397



DSC07398



DSC07399



DSC07400



DSC07401



DSC07402



DSC07403



DSC07404



DSC07405



DSC07406



DSC07407



DSC07408



DSC07409



DSC07410



DSC07411



DSC07412



DSC07413



DSC07414



DSC07415



DSC07416




DSC07417




DSC07418



DSC07419



DSC07420



DSC07421



DSC07422



DSC07423



DSC07424



DSC07425



DSC07426



DSC07427



DSC07428



DSC07429



DSC07430



DSC07431



DSC07432



DSC07433



DSC07434



DSC07435



DSC07436



DSC07437



DSC07438



DSC07439



DSC07440