

Photo Album for Newton, NH

Job # 29228

W/O # 19380244

February 26, 2016

This week the chassis remained in staging. The pump house structure was fabricated and the main fire pump arrived. The lower body modules remained staged for paint. Next week chassis should remain in staging, the pump house could begin initial assembly and the lower body modules may begin the paint process.

PWC #: 19380244 Job #: 29228
 Chassis Color: 90RED Top Color: (Two Tons) 101 BLACK
 VIN #: GJ124212
 Customer: Newton F.D.
 Contract Manager: Genet Schaner
 RFP Date: 4/6
 Rework Number: —

paint
 BLACK
 at
 Pierce

CONFIGURATION
☐ PUMPER
☒ TANKER
☐ RESPONDER
☐ RESCUE
☐ BRUSH TRUCK
☐ OTHER: _____

Customer Supplied Chassis? Yes ☐ No ☒

DSC06107



DSC06108



DSC06109



DSC06110



DSC06111




DSC06112



DSC06113




DSC06114



DSC06167



DSC06168



DSC06272



DSC06273



DSC06274



DSC06275



DSC06829



DSC06830



DSC06831