

Photo Album for Newton, NH

Job # 29228

W/O # 19380244

March 18, 2016

This week the chassis continued on the chassis prep line and cab electrical content began installation. The pump house was painted and began pump final assembly, while the lower body modules began having trim and wiring harnesses installed. Next week the chassis should continue on the chassis prep line, the pump house should continue with pump final assembly and the lower body should finish with body assembly.

QUALITY SYSTEM FORM

PWO #: 19380244 Job #: 29228

Chassis Color: 90RED Top Color: 101BLACK

VIN #: GJ124212

Customer: Newton F.D.

Contract Manager: Genet Schaner

RFP Date: 4/6

Rework Number: — paint BLACK at Pierce

CONFIGURATION

☐ PUMPER

☒ TANKER

☐ RESPONDER

☐ RESCUE

☐ BRUSH TRUCK

☐ OTHER: —

Customer Supplied Chassis? Yes ☐ No ☒

Engine for EXPORT only? Yes ☐ No ☒

DSC06370



DSC06371



DSC06372



DSC06373




DSC06374



DSC06375



DSC06376



DSC06377



DSC06378



DSC06379



DSC06380



DSC06381



DSC06382



DSC06383



DSC06384



DSC06385



DSC06386




DSC06387



DSC06388



DSC06389



DSC06390



DSC06391



DSC06392



DSC06393



DSC06394



DSC06395



DSC06396



DSC06397



DSC06644




DSC06645



DSC06646




DSC06647




DSC06648



DSC06649



DSC06650



DSC07002



DSC07003



DSC07004



DSC07005



DSC07006



DSC07007



DSC07008



DSC07009