

Photo Album for Newton, NH

Job # 29228

W/O # 19380244

March 25, 2016

This week your truck advanced to the final assembly line and the pump house was in the process of being mounted on the chassis. The lower body modules finished with body assembly and the water tank is set to be mounted on the chassis. Next week it should continue with final assembly after having the lower body modules and water tank mounted on the chassis.

QUALITY SYSTEM FORM
Title: Window Sticker
QSF 10-0836
Effective Date: 12/01/14
Page 1 of 1

PWO #: 19380244 Job #: 29228
Chassis Color: 90RED Top Color: (Two Tone) 101BLACK
VIN #: GJ124212
Customer: Newton F.D.
Contract Manager: Genet Schaner
REP Date: 4/6
Rework Number: —

CONFIGURATION
☐ PUMPER
☒ TANKER
☐ RESPONDER
☐ RESCUE
☐ BRUSH TRUCK
☐ OTHER: _____

Customer Supplied Chassis? Yes ☐ No ☒

Paint BLACK at Pierce

DSC06885



DSC06886



DSC06887



DSC06888



DSC06889



DSC06890



DSC06891



DSC06893



DSC06894



DSC06895



DSC06896




DSC06897



DSC06898



DSC06899




DSC06900



DSC06901



DSC06903



DSC06904



DSC06905



DSC06906




DSC06907



DSC06908



DSC06909



DSC06910



DSC06920



DSC06921



DSC06922



DSC06923



DSC06924



DSC06925



DSC06926



DSC06927



DSC06928




DSC06929




DSC06930



DSC06931



DSC06932



DSC06933



DSC06934



DSC06935