


Photo Album for Newton, NH

Job # 29228

W/O # 19380244

April 15, 2016

This week your new Pierce tanker finished the testing process and began post-test and final product evaluation. Next week any remaining option content should be installed ahead of release for final inspection and customer acceptance. This is your last scheduled weekly progress report.



DSC06143



DSC06144



DSC06145



DSC06146



DSC06147



DSC06148



DSC06149



DSC06150



DSC06151



DSC06152



DSC06153



DSC06154



DSC06155



DSC06156



DSC06157



DSC06158



DSC06159



DSC06160



DSC06161



DSC06162



DSC06163



DSC06164



DSC06165



DSC06166



DSC06167



DSC06169



DSC06170



DSC06171



DSC06172



DSC06173



DSC06174



DSC06175



DSC06176



DSC06177



DSC06178



DSC06179



DSC06180



DSC06181



DSC06182



DSC06183



DSC06184



DSC06185



DSC06186



DSC06187



DSC06188



DSC06189



DSC06190




DSC06191



DSC06192



DSC06193



DSC06194



DSC06196



DSC06198



DSC06199



DSC06200



DSC06201



DSC06202



DSC06203