




Photo Album for Poland, ME Job 30560 February 3, 2017

This week the cab finished in paint. The chassis began assembly. The pump house began the paint process. Body panels were joined in fabrication. Next week the cab is scheduled to begin on the cab line where cab related content is added while the chassis continues assembly. The pump house may have trim added. The body should begin the paint process.



DSC04113



DSC04114



DSC04115



DSC04116




DSC04117



DSC04118



DSC04119



DSC00590



DSC00591



DSC00592



DSC00593



DSC00594



DSC00595



DSC00596



DSC00597



DSC00598



DSC00599



DSC00600



DSC00601



DSC07177



DSC07178



DSC07179



DSC07180



DSC07181



DSC00498



DSC00499



DSC00500



DSC00501



DSC00502