




Photo Album for Skowhegan, ME Job 29582 June 24, 2016

This week the cab finished on the cab line and has been merged with the chassis along with the pump while the aerial device pedestal began assembly. The plumbing module was painted. The body finished in paint and was having harnessing and trim added. Next week the chassis is scheduled to begin on the main assembly line where it is merged with the body modules and water tank.



DSC02112



DSC02113



DSC02114



DSC02115



DSC02116



DSC02117



DSC02118



DSC02119



DSC02120



DSC02121



DSC02122



DSC02123



DSC02124



DSC02125



DSC02126



DSC02127



DSC02128



DSC02129



DSC02130



DSC02131



DSC02132



DSC02133



DSC02134



DSC02135



DSC02136



DSC02137




DSC02138




DSC02139



DSC02140



DSC02141



DSC02142



DSC02143



DSC02144



DSC02145



DSC02146



DSC02147




DSC02148



DSC02149



DSC02150



DSC02151



DSC02152



DSC02153



DSC02154



DSC02155




DSC02156



DSC02157



DSC02158



DSC02159



DSC02160




DSC02161



DSC02162



DSC02163



DSC02164



DSC02165



DSC02166



DSC00423



DSC00423a



DSC00424



DSC00425



DSC00426



DSC02049



DSC02050



DSC02051



DSC02052



DSC07085



DSC07086



DSC07087



DSC07088



DSC07089