


Photo Album for Somerset, MA

Job # 29680

W/O # 19937788

April 15, 2016

This week the cab finished with paint and was placed in staging. The chassis frame arrived from Appleton, the pump house structure was fabricated and the body began weld-up and fabrication. Next week the cab could begin having cab content installed on the cab line. The chassis frame should remain in staging, the pump may have valves and plumbing added and the body should finish the paint process.



DSC06175



DSC06176



DSC06177



DSC06178



DSC06179



DSC06180



DSC06181



DSC06204



DSC06205



DSC06206



DSC06207



DSC06208



DSC06209



DSC06210



DSC06211



DSC06212



DSC06213



DSC06214



DSC06215



DSC06216



DSC06217



DSC06218



DSC06219



DSC06220



DSC06221



DSC06222



DSC06223



DSC06224



DSC06225



DSC06226