

Photo Album for Somerset, MA

Job # 29680

W/O # 19937788

May 6, 2016

This week the cab continued on the cab line and is set to be mounted on the chassis. The chassis frame began chassis assembly. The pump house completed initial assembly and is staged to begin the paint process, while the body began having trim and wiring harnesses added. Next week the cab and chassis should be joined together as assembly continues. The pump house should be painted and begin pump final assembly, while the body continues with body assembly.

QUALITY SYSTEM FORM		QSF10-0836
Title: Window Sheet		Effective Date: 12/01/14
Page 1 of 1		
PWO #: <u>19937788</u> Job #: <u>29680</u> Chassis Color: <u>90RED</u> Top Color: (Two Tone) <u>90RED</u> VIN #: <u>GA016657</u> Customer: <u>Somerset F.D.</u> Contract Manager: <u>Rob Wilkey</u> RFP Date: <u>5/24/16</u> Rework Number: <u>19938884</u>		
<u>CONFIGURATION</u>		
☒ PUMPER ☐ TANKER ☐ RESPONDER ☐ RESCUE ☐ BRUSH TRUCK		

DSC06550



DSC06551



DSC06552



DSC06553



DSC06554



DSC06555



DSC06556



DSC06557



DSC06558



DSC06559



DSC06560



DSC06561



DSC06562



DSC06563



DSC06564



DSC06565



DSC06566




DSC06567



DSC06568



DSC06569




DSC06570



DSC06571



DSC06572



DSC06573



DSC06574



DSC06576



DSC06578



DSC06579



DSC06580



DSC06581



DSC06582



DSC06583



DSC06584



DSC06585



DSC06586



DSC06587



DSC06588




DSC06589



DSC06611



DSC06612



DSC06613



DSC06614




DSC06615



DSC06616



DSC06617



DSC06618



DSC06619



DSC06620



DSC06621



DSC06622



DSC06623



DSC06624




DSC06625



DSC06626



DSC06627



DSC07010



DSC07011



DSC07012



DSC07013



DSC07014



DSC07015