

Photo Album for Somerset, MA

Job # 29680

W/O # 19937788

May 13, 2016

This week the cab was joined with the chassis as assembly continues. The pump house was painted and began pump final assembly, while the body continued on the body assembly line. Next week the pump house could be mounted on the chassis as your truck begins final assembly. The body should finish with body assembly and be staged for mounting on the chassis.

VO #: 19937788 Job #: 29680
 Chassis Color: 90RED Top Color: (Two Tone) 90RED
 VIN #: GA016657
 Customer: Somerset F.D.
 Contract Manager: Rob Wilkey
 RFP Date: 5/24/16
 Rework Number: 19938884

CONFIGURATION

☒ PUMPER
☐ TANKER
☐ RESPONDER
☐ RES

DSC06316




DSC06317



DSC06318



DSC06319



DSC06320



DSC06321



DSC06322



DSC06323



DSC06324



DSC06325



DSC06326




DSC06327



DSC06328



DSC06329




DSC06330




DSC06331



DSC06332



DSC06333



DSC06334



DSC06335



DSC06336



DSC06337




DSC06338



DSC06340



DSC06341



DSC06342



DSC06343



DSC06344



DSC06582



DSC06583



DSC06584



DSC06585



DSC06586



DSC06587



DSC06588



DSC06589



DSC06590



DSC06591



DSC06592




DSC06593




DSC06594



DSC06595



DSC06596



DSC06607



DSC06608



DSC06609



DSC06610



DSC06611



DSC06612



DSC06613



DSC06614



DSC06615



DSC06616



DSC06617



DSC06618



DSC06619



DSC06620



DSC06621



DSC06622



DSC06623



DSC06624



DSC06625



DSC06626