





Photo Album for Tewksbury, MA Job 30270 September 16, 2016

This week the cab was staged for assembly while the chassis began assembly. The plumbing module finished in paint. The body panels began fabrication. Next week the cab is scheduled to begin on the cab line where cab related content is added while the chassis continues assembly. The plumbing module may have trim added. The body panels should be joined in fabrication.



DSC04219



DSC04220



DSC04221



DSC04222



DSC04223



DSC04224




DSC04225



DSC02814



DSC02815



DSC02816



DSC02817



DSC02818



DSC02819




DSC02820



DSC02821



DSC02822



DSC02823



DSC02824



DSC02825



DSC02826



DSC02827




DSC02828



DSC02829



DSC02830




DSC02831



DSC02832



DSC02833



DSC02834



DSC02835



DSC02836



DSC02837



DSC07238



DSC07239



DSC07240



DSC07241



DSC07242



DSC07243



DSC07244



DSC07137



DSC07138



DSC07139



DSC07140



DSC07141