





Photo Album for Tewksbury, MA Job 30270 September 23, 2016

This week the cab and chassis were nearing completion in assembly. The plumbing module continued assembly. The body was fabricated and began the paint process. Next week the cab is scheduled to be merged with the chassis. The body should finish in paint.



DSC04031



DSC04032



DSC04033



DSC04034



DSC04035



DSC04036



DSC04037



DSC04038



DSC04039



DSC04040



DSC04041



DSC04042



DSC04043



DSC04044



DSC04045



DSC04046



DSC04047



DSC04048



DSC04049



DSC04050



DSC04051



DSC04052



DSC04053



DSC04054



DSC04055



DSC04056




DSC04057



DSC04058



DSC04059



DSC04060




DSC04061



DSC04062




DSC04063



DSC04427



DSC04428




DSC04429



DSC04430




DSC04431



DSC04432



DSC04433



DSC04434



DSC04435



DSC04436



DSC04437



DSC04438



DSC04439




DSC04440




DSC04441



DSC04442



DSC04443



DSC04444



DSC04445



DSC04446



DSC04447



DSC04448



DSC04449



DSC04450



DSC04451




DSC04452



DSC04453



DSC04454



DSC04455



DSC04456



DSC04457



DSC07149



DSC07150




DSC07151



DSC07152



DSC07153



DSC00231



DSC00232



DSC00233



DSC00234



DSC00235