





Photo Album for West Springfield MA Job 30587 February 10, 2017

This week the cab began on the cab line where cab related content is added while the chassis began assembly. The pump house had trim added. The body began the paint process. Next week the cab is scheduled to be merged with the chassis and pump house. The body may have harnessing and trim added.



DSC04021



DSC04022



DSC04023



DSC04024



DSC04025



DSC04026



DSC04027



DSC04028



DSC04029



DSC04030



DSC04031



DSC04032



DSC04033



DSC04034



DSC04035



DSC04036



DSC04037




DSC04038



DSC04039



DSC04040



DSC04041



DSC04042



DSC04043



DSC04044



DSC04045



DSC04046



DSC04047



DSC04048



DSC04049




DSC04050



DSC00185




DSC00186



DSC00187



DSC00188



DSC00189



DSC00190



DSC00191



DSC00192



DSC00193




DSC00194



DSC00195



DSC00196



DSC00197



DSC00198



DSC00199



DSC08358



DSC08359



DSC08360



DSC08361



DSC08362



DSC00375



DSC00376



DSC00377



DSC00378



DSC00379