





Photo Album for West Springfield MA Job 30587 February 17, 2017

This week the cab finished on the cab line and has been merged with the chassis along with the pump house. The body finished in paint and was on the line where harnessing and trim are added. Next week the chassis is scheduled to begin on the main assembly line where the body and water tank should be merged with the chassis.



DSC02103



DSC02104



DSC02105



DSC02106



DSC02107



DSC02108



DSC02109



DSC02110



DSC02111



DSC02112



DSC02113



DSC02114



DSC02115



DSC02116



DSC02117



DSC02118



DSC02119



DSC02120



DSC02121



DSC02122



DSC02123



DSC02124



DSC02125



DSC02126



DSC02127



DSC02128



DSC02129



DSC02130



DSC02131



DSC02132




DSC02133



DSC02134



DSC02135



DSC02136



DSC02137



DSC02138



DSC02139




DSC02140



DSC02141



DSC02142



DSC02143



DSC02144



DSC02145



DSC02146



DSC02147



DSC02148



DSC02149



DSC02150



DSC02151



DSC02152



DSC02153



DSC02154



DSC02155



DSC02156



DSC02157



DSC02158



DSC02159



DSC02160



DSC00171



DSC00172



DSC00173



DSC00174



DSC00175