


Photo Album for West Springfield MA Job 30587 March 3, 2017

This week the body and water tank were merged with the chassis on the main assembly line where a majority of the components will be added. Next week your apparatus should continue on the main assembly line.



DSC05777



DSC05778



DSC05779



DSC05780



DSC05781



DSC05782




DSC05783




DSC05784



DSC05785



DSC05786



DSC05787



DSC05788



DSC05789



DSC05790



DSC05791



DSC05792




DSC05793




DSC05794



DSC05795



DSC05796



DSC05797



DSC05798



DSC05799



DSC05800



DSC05801



DSC05802



DSC05803



DSC05804




DSC05805



DSC05806



DSC05807



DSC05808



DSC05809



DSC05810



DSC05811



DSC05812



DSC05813