





Photo Album for Town of Windham, ME

Job # 29796

W/O # 20100431

May 20, 2016

This week the cab began the paint process, while the chassis frame remained in staging. The pump house structure was fabricated and the main fire pump arrived. Next week the cab should continue with the paint process. The chassis frame pump and pump house should remain staging. The body panels should begin weld-up and fabrication.



DSC06644



DSC06645



DSC06646



DSC06647



DSC06648



DSC06649



DSC06650



DSC06651



DSC06900



DSC06901



DSC06902



DSC06903



DSC06904



DSC06905



DSC06906



DSC06907