




Photo Album for Town of Windham, ME

Job # 29796

W/O # 20100431

June 17, 2016

This week the cab was joined with the chassis as chassis assembly began. The pump house began initial pump assembly and the body continued with the paint process. Next week the chassis should continue with chassis assembly. The pump house should be painted and could begin pump final assembly. The body should finish the paint process and may begin having trim and wiring harnesses installed.

Pierce
Florida Division

QUALITY SYSTEM FORM QSF10-083

Title: Window Sheet Effective Date: 12/01/10 Page 1 of 1

PWO #: 20100431 Job #: 29796

Chassis Color: 9DRED Top Color: (Two Tone) 10white

VIN #: GA016792

Customer: Windham F.D.

Contract Manager: Genet Schaner

RFP Date: 7/12/16

Rework Number: 20104246

CONFIGURATION

☒ PUMPER
☐ TANKER
☐ RESPONDER
☐ RESCUE
☐ BRUSH TRUCK
☐ OTHER: FR

Customer Supplied Chassis? ☐ YES ☒ NO
 Engine for EXPORT only? ☐ YES ☒ NO

DSC06429



DSC06430



DSC06431



DSC06432




DSC06433



DSC06434



DSC06436




DSC06437




DSC06438



DSC06439




DSC06440



DSC06441



DSC06442



DSC06443



DSC06444



DSC06445




DSC06446



DSC06447



DSC06448



DSC06715



DSC06716



DSC06717



DSC06718



DSC06719



DSC06720



DSC06721




DSC06722



DSC06723



DSC06724




DSC06725



DSC06726



DSC06727



DSC07200



DSC07201



DSC07202



DSC07203



DSC07204



DSC07205



DSC07206