





Photo Album for Town of Windham, ME

Job # 29796

W/O # 20100431

June 24, 2016

This week the chassis continued having trim and contented added on the chassis assembly line. The pump house was painted and began pump final assembly, while the body began having trim and wiring harnesses added on the body assembly line. Next week the pump house should be mounted on the chassis as assembly continues. The body should finish with body assembly and be staged for mounting on the chassis.



DSC06852



DSC06853



DSC06854



DSC06855



DSC06856



DSC06857



DSC06858



DSC06859



DSC06860



DSC06861



DSC06862



DSC06863



DSC06864



DSC06866



DSC06867



DSC06868



DSC06869



DSC06870



DSC06871




DSC06872



DSC06873



DSC06874



DSC06875



DSC06876



DSC06877



DSC06878




DSC06879



DSC06880




DSC06881



DSC06882



DSC06883



DSC06884



DSC06885



DSC06886



DSC06887



DSC06888



DSC06889



DSC06890



DSC06891



DSC06892




DSC06893




DSC06894



DSC06895



DSC06896



DSC06897



DSC06898



DSC06899



DSC06900



DSC06901



DSC06902



DSC06903



DSC06904



DSC06905



DSC06906



DSC06907