




Photo Album for Town of Windham, ME

Job # 29796

W/O # 20100431

July 1, 2016

This week your truck advanced to the final assembly line after having the pump house mounted on the chassis. The body finished with body assembly and at the time of this report it was being mounted on the chassis. In the next report your truck should continue on the final assembly line as additional option content is added.

Due to the Pierce 4th of July shut down, your next schedule report will be on July 15, 2016

QUALITY SYSTEM FORM		QSF10-0836
Title: Window Sheet		Effective Date: 12/01/14
		Page 1 of 1
PWO #:	20100431	Job #: 29796
Chassis Color:	90RED	Top Color: (Two Tone) 10white
VIN #:	GA016792	
Customer:	Windham F.D.	
Contract Manager:	Genet Schaner	
RFP Date:	7/12/16	
Rework Number:	20104246	
<u>CONFIGURATION</u>		
☒	PUMPER	
☐	TANKER	
☐	RESPONDER	
☐	RESCUE	

DSC06573



DSC06574



DSC06575




DSC06576



DSC06577



DSC06579



DSC06580



DSC06581



DSC06582



DSC06583



DSC06584



DSC06585



DSC06586



DSC06587



DSC06589



DSC06590



DSC06591



DSC06592




DSC06593



DSC06594



DSC06595



DSC06596



DSC06597



DSC06598



DSC06599



DSC06600



DSC06601



DSC06602



DSC06603



DSC06604



DSC06605



DSC06606



DSC06807



DSC06808



DSC06809



DSC06810



DSC06811



DSC06812



DSC06813



DSC06814



DSC06815



DSC06816



DSC06817



DSC06818




DSC06819



DSC06820



DSC06821



DSC06822



DSC06823