


Photo Album for Windsor, VT

Job # 29797

W/O # 20100454

July 15, 2016


Your new Pierce apparatus is now in production at the Bradenton, FL facility. This week chassis arrived and began the cab painting process. The body began weld-up and fabrication. Next week the chassis should finish with cab painting and should be staged to begin preparations for fire service use. The body should finish fabrication and could begin the paint process.



DSC06164



DSC06165



DSC06166



DSC06167



DSC06168



DSC06169



DSC06170



DSC06171



DSC06172



DSC06173



DSC06174




DSC06175



DSC06176



DSC06177



DSC6307



DSC6308



DSC6309



DSC6310



DSC6311



DSC6312



DSC6313