


Photo Album for Windsor, VT

Job # 29797

W/O # 20100454

August 19, 2016

This week the chassis continued on the chassis prep line and cab electrical content began installation. The body finished with paint and began having trim and wiring harnesses added. Next week the chassis should continue with chassis prep and the body could be mounted on the chassis.



DSC06773



DSC06774



DSC06776



DSC06777



DSC06778



DSC06779



DSC06780



DSC06781



DSC06782



DSC06783



DSC06784




DSC06785




DSC06786



DSC06787



DSC06788



DSC07057



DSC07058



DSC07059



DSC07060



DSC07061



DSC07062



DSC07063



DSC07065



DSC07066



DSC07067



DSC07068



DSC07069



DSC07070



DSC07071