


Photo Album for Windsor, VT

Job # 29797


W/O # 20100454

September 2, 2016

This week your truck continued having content and the skid unit pump installed on the final assembly line. Next week it should finish assembly and could begin initial testing.



DSC06385



DSC06386



DSC06387



DSC06388



DSC06389




DSC06390



DSC06391




DSC06392



DSC06393



DSC06394



DSC06395



DSC06396



DSC06397



DSC06398



DSC06399



DSC06400



DSC06401



DSC06402



DSC06403



DSC06404



DSC06405



DSC06406



DSC06407



DSC06408



DSC06409



DSC06410



DSC06411



DSC06412



DSC06413



DSC06414



DSC06415



DSC06416



DSC06417



DSC06418



DSC06419



DSC06420



DSC06421



DSC06422



DSC06423



DSC06424



DSC06425