


Photo Album for Woburn, MA

Job 29129

December 18, 2015

This week the cab finished on the cab line and has been merged with the chassis along with the plumbing/chassis cooling structure. The body finished in paint and completed the body line where harnessing and trim were added. Next week the chassis is scheduled to begin on the main assembly line where the body and water tank should be merged with the chassis.



DSC00058



DSC00059



DSC00060



DSC00061



DSC00062



DSC00063



DSC00064



DSC00065



DSC00066



DSC00067



DSC00068



DSC00069



DSC00070



DSC00071



DSC00072



DSC00073



DSC00074



DSC00075



DSC00076



DSC00077



DSC00078



DSC00079




DSC00080



DSC00081



DSC00082



DSC00083



DSC00084



DSC00085



DSC00086



DSC00087



DSC00088



DSC00089



DSC00090



DSC00091



DSC00092



DSC00093



DSC00094



DSC00252



DSC00253



DSC00254



DSC00255



DSC00256