
## Photo Album for Yarmouth, MA Job 28904 November 20, 2015

This week the body was merged with the chassis at the Pierce rescue facility where your apparatus will remain until complete. Wire harnessing continued to be installed along with generator access. In the next report work should continue on installation of body components.

Due to the Pierce Plant Holiday shut down, your next report is scheduled for December 4, 2015.



DSC04313



DSC04315



DSC04314



DSC04316



DSC04317



DSC04319



DSC04318



DSC04320





DSC04321



DSC04323



DSC04322



DSC04324





DSC04325



DSC04327



DSC04326



DSC04328





DSC04329



DSC04331



DSC04330



DSC04332









DSC04334

