PROPERTY LOCATED AT: **27 Bartol Island Road, Freeport, ME 04032**

PROPERTY DISCLOSURE

Under Maine Law, certain information must be made available to buyers prior to or during preparation of an offer. This statement has been prepared to assist prospective buyers in evaluating this property. This disclosure is not a warranty of the condition of the property and is not part of any contract between Seller and any Buyer. Seller authorizes the disclosure of the information in this statement to real estate licensees and to prospective buyers of this property. The Seller agrees to provide prompt notice of any changes in the information and this form will be appropriately changed with an amendment date. Inspections are highly recommended.

DO NOT LEAVE ANY QUESTIONS BLANK. STRIKE, WRITE N/A OR UNKNOWN IF NEEDED.

SECTION I – WATER SUPPLY

TYPE OF SYSTEM: ☐ Public ☐ Private ☐ Seasonal _____ ☐ Unknown
☒ Drilled ☐ Dug ☐ Other _____

MALFUNCTIONS: Are you aware of or have you experienced any malfunctions with the (public/private/other) water system?

Pump (if any): ..... ☐ N/A ☐ Yes ☒ No ☐ Unknown
Quantity: ..... ☐ Yes ☒ No ☐ Unknown
Quality: ..... ☐ Yes ☒ No ☐ Unknown

If Yes to any question, please explain in the comment section below or with attachment.

WATER TEST: Have you had the water tested? ..... ☒ Yes ☐ No
If Yes, Date of most recent test: **08/03/2023** Are test results available? .. ☒ Yes ☐ No
To your knowledge, have any test results ever been reported as unsatisfactory or satisfactory with notation? ..... ☐ Yes ☒ No
If Yes, are test results available? ..... ☒ Yes ☐ No
What steps were taken to remedy the problem? **None needed**

IF PRIVATE: (Strike Section if Not Applicable):

INSTALLATION: Location: **Left of the shed at tree line (by Rhododendron)**
Installed by: **Brunswick Artisan**
Date of Installation: **1984**

USE: Number of persons currently using system: **4+**
Does system supply water for more than one household? ☐ Yes ☒ No ☐ Unknown

Comments: **Seller had Critical Plumbing Inc. run a water test including Radon - Results available.**

Source of Section I information: **Seller / Previous property disclosure**

LandVest, Inc., 36 Danforth Street Portland ME 04101 Phone: 2077768352 Fax: 2077745845 27 Bartol Island - Karen Reiche
Produced with Lone Wolf Transactions (zipForm Edition) 717 N Harwood St, Suite 2200, Dallas, TX 75201 www.lwolf.com

SECTION II – WASTE WATER DISPOSAL

TYPE OF SYSTEM: ☐ Public ☒ Private ☐ Quasi-Public _____ ☐ Unknown

IF PUBLIC OR QUASI-PUBLIC (Strike Section if Not Applicable):
Have you had the sewer line inspected? ..... ☐ Yes ☐ No
If Yes, what results: _____
Have you experienced any problems such as line or other malfunctions? ..... ☐ Yes ☐ No
What steps were taken to remedy the problem? _____

IF PRIVATE (Strike Section if Not Applicable):
Tank: ☒ Septic Tank ☐ Holding Tank ☐ Cesspool ☐ Other: _____
Tank Size: ☐ 500 Gallon ☒ 1000 Gallon ☐ Unknown ☐ Other: _____
Tank Type: ☒ Concrete ☐ Metal ☐ Unknown ☐ Other: _____
Location: **Behind garage by trees** OR ☐ Unknown
Date installed: **unk** Date last pumped: **2021** Name of pumping company: **Gabriel**
Have you experienced any malfunctions? ..... ☐ Yes ☒ No
If Yes, give the date and describe the problem: _____

Date of last servicing of tank: **2021** Name of company servicing tank: **Gabriel**
Leach Field: ..... ☒ Yes ☐ No ☐ Unknown
If Yes, Location: **end of driveway left of house**
Date of installation of leach field: **1983** Installed by: **Dallas Excavation**
Date of last servicing of leach field: none Company servicing leach field: **GGH Stanford Inc**
Have you experienced any malfunctions? ..... ☐ Yes ☒ No
If Yes, give the date and describe the problem and what steps were taken to remedy: _____

Do you have records of the design indicating the # of bedrooms the system was designed for? ☒ Yes ☐ No
If Yes, are they available? ..... ☒ Yes ☐ No
Is System located in a Shoreland Zone? ..... ☐ Yes ☒ No ☐ Unknown
Comments: **See listing broker for septic design on file for expansion**
Source of Section II information: **Seller**

Produced with Lone Wolf Transactions (zipForm Edition) 717 N Harwood St, Suite 2200, Dallas, TX 75201 www.lwolf.com

SECTION III – HEATING SYSTEM(S)/HEATING SOURCES(S)

Heating System(s) or Source(s)	SYSTEM 1	SYSTEM 2	SYSTEM 3	SYSTEM 4
TYPE(S)	FHW/Propane	Woodstove	Gas FP	Space heaters
Age of system(s) or source(s)	2019	2003	2015	propane/2015
Name of company that services system(s) or source(s)	Gabriel	N/a		
Date of most recent service call	annually	cleaned		
Annual consumption per system or source (i.e., gallons, kilowatt hours, cords)	TBD	unk		
Malfunction per system(s) or source(s) within past 2 years	none known	none known		none
Other pertinent information	Veissman Boiler Nest thermostats	Tghelkachel		Space heaters in barn space

Are there fuel supply lines? ..... [X] Yes [ ] No [ ] Unknown
Are any buried? ..... [ ] Yes [X] No [ ] Unknown
Are all sleeved? ..... [X] Yes [ ] No [ ] Unknown
Chimney(s): ..... [X] Yes [ ] No
If Yes, are they lined: ..... [ ] Yes [ ] No [X] Unknown
Is more than one heat source vented through one flue? ..... [ ] Yes [X] No [ ] Unknown
Had a chimney fire: ..... [ ] Yes [X] No [ ] Unknown
Has chimney(s) been inspected? ..... [ ] Yes [X] No [ ] Unknown
If Yes, date: _____
Date chimney(s) last cleaned: **in last few years**
Direct/Power Vent(s): ..... [ ] Yes [X] No [ ] Unknown
Has vent(s) been inspected? ..... [ ] Yes [ ] No [ ] Unknown
If Yes, date: _____
Comments: **none**
Source of Section III information: **Seller**

SECTION IV – HAZARDOUS MATERIAL

The licensee is disclosing that the Seller is making representations contained herein.

A. UNDERGROUND STORAGE TANKS - Are there now, or have there ever been, any underground storage tanks on the property? ..... [ ] Yes [X] No [ ] Unknown
If Yes, are tanks in current use? ..... [ ] Yes [ ] No [ ] Unknown
If no longer in use, how long have they been out of service? _____
If tanks are no longer in use, have tanks been abandoned according to DEP? [ ] Yes [ ] No [ ] Unknown
Are tanks registered with DEP? ..... [ ] Yes [ ] No [ ] Unknown
Age of tank(s): _____ Size of tank(s): _____
Location: _____

What materials are, or were, stored in the tank(s)? _____

Have you experienced any problems such as leakage: ..... ☐ Yes ☐ No ☐ Unknown

Comments: **None**

Source of information: **Seller**

B. ASBESTOS – Is there now or has there been asbestos:

As insulation on the heating system pipes or duct work? ..... ☐ Yes ☐ No ☒ Unknown

In the ceilings? ..... ☐ Yes ☐ No ☒ Unknown

In the siding? ..... ☐ Yes ☐ No ☒ Unknown

In the roofing shingles? ..... ☐ Yes ☐ No ☒ Unknown

In flooring tiles? ..... ☐ Yes ☐ No ☒ Unknown

Other: _____ ☐ Yes ☐ No ☒ Unknown

Comments: **None**

Source of information: **Seller**

C. RADON/AIR - Current or previously existing:

Has the property been tested? ..... ☒ Yes ☐ No ☐ Unknown

If Yes: Date: **unk** By: _____

Results: _____

If applicable, what remedial steps were taken? **air mitigation system installed**

Has the property been tested since remedial steps? ..... ☐ Yes ☐ No ☐ Unknown

Are test results available? ..... ☐ Yes ☒ No

Results/Comments: **None**

Source of information: **Seller**

D. RADON/WATER - Current or previously existing:

Has the property been tested? ..... ☒ Yes ☐ No ☐ Unknown

If Yes: Date: **08/03/2023** By: **Critical Plumbing Inc.**

Results: **Below Maine's "Desireable" levels of 4,000 pCi/L -**

If applicable, what remedial steps were taken? **None**

Has the property been tested since remedial steps? ..... ☐ Yes ☒ No ☐ Unknown

Are test results available? ..... ☒ Yes ☐ No

Results/Comments: **None**

Source of information: **Seller**

E. METHAMPHETAMINE - Current or previously existing: ☐ Yes ☒ No ☐ Unknown

Comments: **none**

Source of information: **Seller**

F. LEAD-BASED PAINT/PAINT HAZARDS – *(Note: Lead-based paint is most commonly found in homes constructed prior to 1978)*

Is there now or has there ever been lead-based paint and/or lead-based paint hazards on the property? ..... ☐ Yes ☒ No ☐ Unknown ☐ Unknown (but possible due to age)

If Yes, describe location and basis for determination: _____

Do you know of any records/reports pertaining to such lead-based paint/lead-based paint hazards: ☐ Yes ☐ No

If Yes, describe: _____

Are you aware of any cracking, peeling or flaking paint? ..... ☐ Yes ☐ No

Comments: **none**

Source of information: **Seller**

G. OTHER HAZARDOUS MATERIALS - Current or previously existing:

TOXIC MATERIAL: ..... ☐ Yes ☐ No ☒ Unknown

LAND FILL: ..... ☐ Yes ☐ No ☒ Unknown

RADIOACTIVE MATERIAL: ..... ☐ Yes ☐ No ☒ Unknown

Other: **none known**

Source of information: **Seller**

Buyers are encouraged to seek information from professionals regarding any specific issue or concern.

SECTION V – GENERAL INFORMATION

Is the property subject to or have the benefit of any encroachments, easements, rights-of-way, leases, rights of first refusal, life estates, private ways, trails, homeowner associations (including condominiums and PUD's) or restrictive covenants? ..... ☒ Yes ☐ No ☐ Unknown

If Yes, explain: **Conservation easement, Right of Way**

Source of information: **Seller, deed**

Is access by means of a way owned and maintained by the State, a county, or a municipality over which the public has a right to pass? ..... ☒ Yes ☐ No ☐ Unknown

If No, who is responsible for maintenance? _____

Road Association Name (if known): _____

Are there any tax exemptions or reductions for this property for any reason including but not limited to: Tree Growth, Open Space and Farmland, Veteran's, Homestead Exemption, Blind, Working Waterfront?..... ..... ☒ Yes ☐ No ☐ Unknown

If Yes, explain: **Open Space**

Is a Forest Management and Harvest Plan available?..... ☐ Yes ☒ No ☐ Unknown

Is house now covered by flood insurance policy (not a determination of flood zone) ☐ Yes ☒ No ☐ Unknown

Equipment leased or not owned (including but not limited to, propane tank, hot water heater, satellite dish, water filtration system, photovoltaics, wind turbines): Type: **propane tank**

Year Principal Structure Built: **1984/Barn 2105**

What year did Seller acquire property? **2017**

Roof: Year Shingles/Other Installed: **2003**

Water, moisture or leakage: **none**

Comments: **Insulation added, blown in by Rook Energy**

Foundation/Basement:

Is there a Sump Pump? ..... ☐ Yes ☒ No ☐ Unknown

Water, moisture or leakage since you owned the property: ..... ☐ Yes ☒ No ☐ Unknown

Prior water, moisture or leakage? ..... ☐ Yes ☒ No ☐ Unknown

Comments: **None**

Mold: Has the property ever been tested for mold? ..... ☐ Yes ☒ No ☐ Unknown

If Yes, are test results available? ..... ☐ Yes ☐ No

Comments: **none**

Electrical: ☐ Fuses ☒ Circuit Breaker ☐ Other: _____ ☐ Unknown

Comments: **none**

Has all or a portion of the property been surveyed? ..... ☒ Yes ☐ No ☐ Unknown

If Yes, is the survey available? ..... ☒ Yes ☐ No ☐ Unknown

Manufactured Housing – Is the residence a:

Mobile Home ..... ☐ Yes ☐ No ☐ Unknown

Modular ..... ☐ Yes ☐ No ☐ Unknown

Known defects or hazardous materials caused by insect or animal infestation inside or on the residential structure ..... ☐ Yes ☐ No ☐ Unknown

Comments:

KNOWN MATERIAL DEFECTS about Physical Condition and/or value of Property, including those that may have an adverse impact on health/safety: **When first owned, ran out of oil, freeze-up, pipes burst when**

Continued... See Addendum Known material defects 1

Comments: **Corrected**

Source of Section V information: **Seller**

SECTION VI – ADDITIONAL INFORMATION

Insulation added to house, and to first floor of barn. Primary bath remodeled in 2015, gas FP added 2015.

ATTACHMENTS EXPLAINING CURRENT PROBLEMS, PAST REPAIRS OR ADDITIONAL INFORMATION IN ANY SECTION IN DISCLOSURE: ..... ☐ Yes ☒ No

Seller shall be responsible and liable for any failure to provide known information regarding known material defects to the Buyer.

Neither Seller nor any Broker makes any representations as to the applicability of, or compliance with, any codes of any sort, whether state, municipal, federal or any other, including but not limited to fire, life safety, building, electrical or plumbing.

As Sellers, we have provided the above information and represent that all information is correct. To the best of our knowledge, all systems and equipment, unless otherwise noted on this form, are in operational condition.

SELLER DATE **Alexander K Buck**	SELLER DATE **Allison A Buck**
SELLER DATE	SELLER DATE

I/We have read and received a copy of this disclosure, the arsenic in wood fact sheet, the arsenic in water brochure, and understand that I/we should seek information from qualified professionals if I/we have questions or concerns.

BUYER DATE	BUYER DATE
BUYER DATE	BUYER DATE

Maine Association of REALTORS®/Copyright © 2023.
All Rights Reserved. Revised 2022.

EQUAL HOUSING OPPORTUNITY

Produced with Lone Wolf Transactions (zipForm Edition) 717 N Harwood St, Suite 2200, Dallas, TX 75201 www.lwolf.com

ADDENDUM

PROPERTY: **27 Bartol Island Road, Freeport, ME 04032**

1) Known material defects
away. CHICKEN COOP IN DISREPAIR, DO NOT ENTER, BEING SOLD "AS IS". GRANDFATHERED FOOTPRINT TO BUILD.

Date: _____ Date: _____

_____ _____
Signature Signature

Date: _____ Date: _____

_____ _____
Signature Signature

LandVest, Inc., 36 Danforth Street Portland ME 04101 Phone: **2077768352** Fax: **2077745845** **27 Bartol Island -**
Karen Reiche
Produced with Lone Wolf Transactions (zipForm Edition) 717 N Harwood St, Suite 2200, Dallas, TX 75201 www.lwolf.com