




MANHATTAN  
COMFORT

# Park 1.8

Model: 81461, 81484, 81436, 81423, 81462



Part	Description	Quantity
1	PANEL	1
2	CENTRAL PANEL	1
3	LOWER PANEL	1
4	MDF BOTTOM PIECE	2
5	SHELF	1
6	SMALLER SUPPORT	3
7	LARGER SUPPORT	2
8	ASSEMBLY SUPPORT	2
9	CENTRAL SUPPORT	1



# Hardware:




Grommet




2014



3933



4573



4654



4505



3527



0162



3557




0329



2088

# 1


## A



### 21

0162

## B




### 30

3557


2014





# 2

## A




## B




**C****D**


3





**B**





C





D







**E****F**

**G****H**

I





J



**L**

**Note:** Use the screw that is indicated with the TV manufacturer.



**M**

