

Sample Company Realty

Attention: Jane Doe

This survey was generated after our scheduled visit on 07-03-2021.
During the survey we documented the following exterior lighting findings for your review.

Locations:

5700-5750 Campbell & 9500-9618 Tidwell

@ 5700-5750 Campbell bldg.

- (5) soffit lights out
- (2) wallpacks out

@ 9500 Tidwell bldg.

- (1) soffit light out

@ 9618 Tidwell bldg.

- (4) soffit lights out

7110 – 7240 Brittmoore

@ 7110 bldg.

- (3) soffit lights out

@ 7120 bldg.

- (6) soffit lights out
- (2) wallpacks out

@ 7190 bldg.

- (15) soffit lights out
- (1) wallpack out

@ Common Area (in front of) 7110 & 7190 bldgs.

- (8) ground-mounted lights out

@ 7240 bldg.

- (20) soffit lights out
- (3) pole lights out

5805 – 5849 Westview Dr.

** GOOD **

8844, 8846, 8848, 8850 N. Sam Houston Parkway

@ 8844 bldg.

** GOOD **

@ 8846 bldg.

** GOOD **

@ 8848 bldg.

** GOOD **

@ 8850 bldg.

** GOOD **

If you wish to proceed with repairs, please let us know and we'll prioritize and service accordingly.

Sincerely,



Logan Tinsley
Production Assistant