

Engine Inspection/Condition Report

CUSTOMER:	IDOT		WORK ORDER NO:	FS42104		
CUSTOMER PH:	217-785-3275		ENGINE MODEL:	PT6A-60A		
AIRCRAFT REG. NO:	N961LL		ENGINE S/N:	PCE-PK0269		
AIRCRAFT TT:	5608:48		AIRCRAFT TC:	8687		
REASON FOR INSPECTION:			Pre-Buy			
INSTALLED ON AIRCRAFT S/N:			FL-264			
INSPECTION DATE:	6/18/2015	ENGINE POSITION:		L/H		
TSN:	5606:37	CSN:		8677		
TSO	1644	cso		N/A		
ISSUED BY:	John Turner					

Page 1 Report Issue date: 7/2/2015

NOTE: Given the nature of borescope instrumentation it is often not possible to make observations and examine all areas of an individual engine as part of an inspection. Based on this limitation,

NOTE: Given the nature of borescope instrumentation it is often not possible to make observations and examine all areas of an individual engine as part of an inspection. Based on this limitation, Dallas Airmotive, Inc. cannot and does not warrant its findings for borescope inspections (pre-purchase and otherwise) against the possibility that hidden damage may exist that was not observable and reported by our inspector at the time of the inspection.

Engine Inspection Report Engine Model: Serial Number: PT6A-60A PCE-PK0269 **Dallas**Airmotive Engine Time: 5608:37 Engine Cycle: 8677

Data Plate

1st. Stage compressor , No defects noted





1st. Stage compressor, No defects noted

CT Blades, No defects





CT Blades, No defects noted

CT Blades, No defects noted





Page 2

Report Issue date: 7/2/2015

NOTE: Given the nature of borescope instrumentation it is often not possible to make observations and examine all areas of an individual engine as part of an inspection. Based on this limitation, Dallas Airmotive, Inc. cannot and does not warrant its findings for borescope inspections (pre-purchase and otherwise) against the possibility that hidden damage may exist that was not observable and reported by our inspector at the time of the inspection.

Engine Inspection Report Engine Model: PT6A-60A Serial Number: PCE-PK0269 Engine Time: 5608:37 Engine Cycle: 8677

• CT Blades , No defects noted

CT Blades, No defects noted





• 2nd Stage PT blades , No defects noted

 2^{nd} Stage PT blades , No defects noted






Combustion Liner, No defects noted

Combustion Liner, No defects noted





Page 3 Report Issue date: 7/2/2015

NOTE: Given the nature of borescope instrumentation it is often not possible to make observations and examine all areas of an individual engine as part of an inspection. Based on this limitation, Dallas Airmotive, Inc. cannot and does not warrant its findings for borescope inspections (pre-purchase and otherwise) against the possibility that hidden damage may exist that was not observable and reported by our inspector at the time of the inspection.

Engine Inspection Report							
	Engine Model:	PT6A-60A	Serial Number:	PCE-PK0269			
Dallas Airmotive A BBA Aviation company	Engine Time:	5608:37	Engine Cycle:	8677			

Combustion Liner, No defects noted

Combustion Liner, No defects noted





Engine appears normal for time in service no defects noted, Engine OK to continue service.