

Completion Form

Property Address: 104 Grand
City, State, Zip: East Alton, IL 62024

Date Completed: 3/25/2008

Work Performed:

finished scraping and painting the rest of the windows to finish the abatement/interim control on the property.



Responsive Nationwide Services with Superior Quality, Integrity and Customer Service

MEMO/FAX/EMAIL CORRESPONDENCE

TO: [REDACTED]
FROM: [REDACTED]
DATE: April 12, 2008
PAGES: 1
RE:
104 Grand Ave.
East Alton, IL 62024
Lead-Based Paint Abatement Clearance Results

As requested, sampling and testing of post lead-based paint (LBP) abatement conditions were conducted at the above property and conditions were determined acceptable as evidenced by the attached clearance report provided by

Based on the attached, no further abatement of LBP conditions at the subject property is warranted at this time.

[REDACTED] carries General and Professional Liability and Mold-specific insurance coverage. If you should have any questions please do not hesitate to contact [REDACTED] Thank you.

CLEARANCE PHOTOGRAPH SHEET

104 Grand Avenue
East Alton, IL 62024
April 1, 2008

REMARKS



Exterior Side A



Stabilized Window Case/Sash

REMARKS



**Interior
Stabilized Window Case/Sash**