



55 Wellhouse Road

55 Wellhouse Road
Newton Aycliffe
DL5 4FF

Inspected by: hartlepool@thecastledenegroup.com

Date of Inspection: 27/04/2016

Table of Contents

Meters	1
Keys	2
Spaces	3
Entrance Door	3
Entrance Hall	5
Storage Cupboard	9
Living Room	10
Kitchen	14
G/Floor WC	20
Stairwell	24
First Floor Landing	25
Master Bedroom	27
En Suite Bath/Shower Room	31
Bedroom 2	35
Bedroom 3	38
Main Bath/Shower Room	41
Property Exterior	46
Back Garden	47
Cupboard	48
Right Side	49
Photo Index	50
Declaration	72

METERS

Gas



Reading One: 0

0.0 °, 0.0 °


Electric



Reading One: 0

0.0 °, 0.0 °

KEYS



Key



0.0 ° , 0.0 °

SPACES


Entrance Door




0.0 ° , 0.0 °

Item	Description
Entrance Door	 0.0 ° , 0.0 °
Glass Panel	 0.0 ° , 0.0 °
Door Handle	 0.0 ° , 0.0 °


Entrance Door (continued)

Item	Description
Lock	 0.0 ° , 0.0 °
Mortise Lock	 0.0 ° , 0.0 °
Letter Box Plate	 0.0 ° , 0.0 °
Viewer/Spy Hole	 0.0 ° , 0.0 °

Entrance Hall




0.0 ° , 0.0 °



0.0 ° , 0.0 °

Notes:




New cream carpets, fitted with no marks. Cream walls, no marks. White doors and fitted entrance doormat.

Item	Description
Return Entrance Door	 29/04/2016 0.0 ° , 0.0 °
Return Door Handle	 29/04/2016 0.0 ° , 0.0 °
Night Latch Lock	 29/04/2016 0.0 ° , 0.0 °

Entrance Hall (continued)

Item	Description
Letter Box Flap	 29/04/2016 0.0 ° , 0.0 °
Ceiling	 29/04/2016 0.0 ° , 0.0 °
Walls	 29/04/2016 0.0 ° , 0.0 °  29/04/2016 0.0 ° , 0.0 °  29/04/2016 0.0 ° , 0.0 °  29/04/2016 0.0 ° , 0.0 °


Entrance Hall (continued)

Item	Description
Floor	 29/04/2016 0.0 ° , 0.0 °  29/04/2016 0.0 ° , 0.0 °  29/04/2016 0.0 ° , 0.0 °  29/04/2016 0.0 ° , 0.0 °
Sockets	 29/04/2016 0.0 ° , 0.0 °
Switches	 29/04/2016 0.0 ° , 0.0 °  29/04/2016 0.0 ° , 0.0 °  29/04/2016 0.0 ° , 0.0 °





Entrance Hall (continued)

Item	Description
Lighting	  0.0 ° , 0.0 ° 0.0 ° , 0.0 °
Radiator	 0.0 ° , 0.0 °
Smoke Detector/ Alarm	 0.0 ° , 0.0 °
Thermostat	 0.0 ° , 0.0 °

Storage Cupboard




0.0 °, 0.0 °

Item	Description	
Floors	 29/04/2016 0.0 °, 0.0 °	
Walls	 29/04/2016 0.0 °, 0.0 °	 29/04/2016 0.0 °, 0.0 °
Doors	 29/04/2016 0.0 °, 0.0 °	 29/04/2016 0.0 °, 0.0 °

Storage Cupboard (continued)

Item	Description
Door Handle	 0.0 ° , 0.0 ° 0.0 ° , 0.0 °
Switches	 0.0 ° , 0.0 °





Living Room








0.0 ° , 0.0 °

Notes:

Newly fitted cream carpets, newly painted cream walls, white ceiling, white doors, all clean, no marks.

Item	Description		
Floors			
	29/04/2016	29/04/2016	29/04/2016
	0.0 °, 0.0 °	0.0 °, 0.0 °	0.0 °, 0.0 °
			
	29/04/2016	29/04/2016	
	0.0 °, 0.0 °	0.0 °, 0.0 °	
Walls			
	29/04/2016	29/04/2016	29/04/2016
	0.0 °, 0.0 °	0.0 °, 0.0 °	0.0 °, 0.0 °
			
	29/04/2016	29/04/2016	
	0.0 °, 0.0 °	0.0 °, 0.0 °	

Living Room (continued)

Item	Description		
Ceiling	 29/04/2016 0.0 ° , 0.0 °	 29/04/2016 0.0 ° , 0.0 °	 29/04/2016 0.0 ° , 0.0 °
Doors	 29/04/2016 0.0 ° , 0.0 °	 29/04/2016 0.0 ° , 0.0 °	 29/04/2016 0.0 ° , 0.0 °
Door Handle	 29/04/2016 0.0 ° , 0.0 °	 29/04/2016 0.0 ° , 0.0 °	
Sockets	 29/04/2016 0.0 ° , 0.0 °	 29/04/2016 0.0 ° , 0.0 °	 29/04/2016 0.0 ° , 0.0 °

Living Room (continued)

Item	Description
Sockets (continued)	 0.0 ° , 0.0 °
Switches	   0.0 ° , 0.0 ° 0.0 ° , 0.0 ° 0.0 ° , 0.0 °
Lights & Fixtures	 0.0 ° , 0.0 °
Radiator	 0.0 ° , 0.0 °

Kitchen








29/04/2016





0.0 ° , 0.0 °

Notes:



White cabinet, black and grey bench; shiny hob, black; padded wood-effect floor, all cream walls, no marks, no scuffs, clean and tidy.

Item	Description	
Door	 29/04/2016 0.0 ° , 0.0 °	 29/04/2016 0.0 ° , 0.0 °
Door Handle	 29/04/2016 0.0 ° , 0.0 °	 29/04/2016 0.0 ° , 0.0 °
Ceiling	 29/04/2016 0.0 ° , 0.0 °	 29/04/2016 0.0 ° , 0.0 °




Kitchen (continued)

Item	Description		
Walls	 29/04/2016 0.0 ° , 0.0 °	 29/04/2016 0.0 ° , 0.0 °	 29/04/2016 0.0 ° , 0.0 °
	 29/04/2016 0.0 ° , 0.0 °		
Floor	 29/04/2016 0.0 ° , 0.0 °	 29/04/2016 0.0 ° , 0.0 °	 29/04/2016 0.0 ° , 0.0 °
Sockets	 29/04/2016 0.0 ° , 0.0 °	 29/04/2016 0.0 ° , 0.0 °	 29/04/2016 0.0 ° , 0.0 °

Kitchen (continued)

Item	Description	
Sockets (continued)	 0.0 ° , 0.0 °	 0.0 ° , 0.0 °
Switches	 0.0 ° , 0.0 °	 0.0 ° , 0.0 °
Lighting	 0.0 ° , 0.0 °	
Radiator	 0.0 ° , 0.0 °	




Kitchen (continued)

Item	Description
Window	  29/04/2016 0.0 ° , 0.0 °
Eye Level Cabinets	   29/04/2016 0.0 ° , 0.0 °  29/04/2016 0.0 ° , 0.0 °
Floor Standing Cabinets	   29/04/2016 0.0 ° , 0.0 °

Kitchen (continued)

Item	Description
Floor Standing Cabinets (continued)	 0.0 ° , 0.0 °
Draw Unit	  0.0 ° , 0.0 ° 0.0 ° , 0.0 °
Work Tops	   0.0 ° , 0.0 ° 0.0 ° , 0.0 ° 0.0 ° , 0.0 °
Sink Unit	   0.0 ° , 0.0 ° 0.0 ° , 0.0 ° 0.0 ° , 0.0 °


Kitchen (continued)

Item	Description		
Sink Taps	 0.0 ° , 0.0 °	 0.0 ° , 0.0 °	
Hob	 0.0 ° , 0.0 °		
Illuminated Extractor Hood	 0.0 ° , 0.0 °	 0.0 ° , 0.0 °	 0.0 ° , 0.0 °
Hob/Oven	 0.0 ° , 0.0 °	 0.0 ° , 0.0 °	 0.0 ° , 0.0 °

Kitchen (continued)

Item	Description
Boiler	 
	29/04/2016 0.0 ° , 0.0 ° 29/04/2016 0.0 ° , 0.0 °

G/Floor WC




0.0 ° , 0.0 °

Notes:

Wood-effect pattern floor, no chips; cream walls, 1 window, small radiator, tiles around the little sink.

Item	Description
Floors	 
	29/04/2016 0.0 ° , 0.0 ° 29/04/2016 0.0 ° , 0.0 °




G/Floor WC (continued)

Item	Description
Walls	   0.0 ° , 0.0 ° 0.0 ° , 0.0 ° 0.0 ° , 0.0 °
Ceiling	  0.0 ° , 0.0 ° 0.0 ° , 0.0 °
Windows	 0.0 ° , 0.0 °
Doors	  0.0 ° , 0.0 ° 0.0 ° , 0.0 °


G/Floor WC (continued)

Item	Description
Door Handle	  0.0 ° , 0.0 ° 0.0 ° , 0.0 °
Lights & Fixtures	   0.0 ° , 0.0 ° 0.0 ° , 0.0 ° 0.0 ° , 0.0 °  0.0 ° , 0.0 °
Hand Basin	 0.0 ° , 0.0 °

G/Floor WC (continued)

Item	Description
Basin Tap	 0.0 ° , 0.0 °
Basin Plug/ Waste	 0.0 ° , 0.0 °
Toilet	   0.0 ° , 0.0 ° 0.0 ° , 0.0 ° 0.0 ° , 0.0 °
Radiator	 0.0 ° , 0.0 °





Stairwell




0.0 ° , 0.0 °

Notes:

Banister and handrail, all white, freshly painted. Cream walls, no marks. Freshly fitted cream carpet.

Item	Description
Balusters/ Spindles	 29/04/2016 0.0 ° , 0.0 °  29/04/2016 0.0 ° , 0.0 °
Hand Rail	 29/04/2016 0.0 ° , 0.0 °
Walls	 29/04/2016 0.0 ° , 0.0 °  29/04/2016 0.0 ° , 0.0 °  29/04/2016 0.0 ° , 0.0 °

First Floor Landing



0.0 ° , 0.0 °

Notes:
Landing has freshly fitted cream carpet, cream walls, all white doors, a white loft hatch, and a smoke alarm which works.

Item	Description	
Ceiling	 0.0 ° , 0.0 °	
Walls	 0.0 ° , 0.0 °	 0.0 ° , 0.0 °
Switches	 0.0 ° , 0.0 °	 0.0 ° , 0.0 °

First Floor Landing (continued)

Item	Description
Lights & Fixtures	 0.0 ° , 0.0 °
Loft Hatch	 0.0 ° , 0.0 °
Smoke Detector	 0.0 ° , 0.0 °
Radiator	 0.0 ° , 0.0 °

First Floor Landing (continued)

Item	Description
Sockets	 0.0 ° , 0.0 °


Master Bedroom







0.0 ° , 0.0 °

Notes:





Freshly painted cream walls, freshly fitted cream carpet, white doors, white ceiling.

Item	Description
Floors	 0.0 ° , 0.0 °  0.0 ° , 0.0 °  0.0 ° , 0.0 °



Master Bedroom (continued)

Item	Description		
Walls			
			
Ceiling			
Windows			

Master Bedroom (continued)

Item	Description		
Doors	 29/04/2016 0.0 ° , 0.0 °	 29/04/2016 0.0 ° , 0.0 °	
Door Handle	 29/04/2016 0.0 ° , 0.0 °	 29/04/2016 0.0 ° , 0.0 °	
Sockets	 29/04/2016 0.0 ° , 0.0 °	 29/04/2016 0.0 ° , 0.0 °	 29/04/2016 0.0 ° , 0.0 °
Switches	 29/04/2016 0.0 ° , 0.0 °	 29/04/2016 0.0 ° , 0.0 °	

Master Bedroom (continued)

Item	Description
Lights & Fixtures	 0.0 ° , 0.0 °
Radiator	 0.0 ° , 0.0 °
Thermostat	 0.0 ° , 0.0 °
Doorstops	 0.0 ° , 0.0 °







En Suite Bath/Shower Room







0.0 ° , 0.0 °

Notes:



Padded tile-effect floor, white sink and toilet, tiles behind the sink, the shower has cream tiles head to toe, all clean, and the walls are cream.

Item	Description		
Floors	 0.0 ° , 0.0 °	 0.0 ° , 0.0 °	
Walls	 0.0 ° , 0.0 °	 0.0 ° , 0.0 °	 0.0 ° , 0.0 °
Ceiling	 0.0 ° , 0.0 °	 0.0 ° , 0.0 °	 0.0 ° , 0.0 °



En Suite Bath/Shower Room (continued)

Item	Description
Windows	 0.0 ° , 0.0 °
Doors	 0.0 ° , 0.0 °  0.0 ° , 0.0 °
Door Handle	 0.0 ° , 0.0 °  0.0 ° , 0.0 °
Lights & Fixtures	 0.0 ° , 0.0 °


En Suite Bath/Shower Room (continued)

Item	Description
Extractor Fan	 29/04/2016 0.0 ° , 0.0 °
Shower Attachment	 29/04/2016 0.0 ° , 0.0 °  29/04/2016 0.0 ° , 0.0 °  29/04/2016 0.0 ° , 0.0 °  29/04/2016 0.0 ° , 0.0 °  29/04/2016 0.0 ° , 0.0 °  29/04/2016 0.0 ° , 0.0 °
Hand Basin	 29/04/2016 0.0 ° , 0.0 °

En Suite Bath/Shower Room (continued)

Item	Description
Basin Tap	 29/04/2016 0.0 ° , 0.0 °
Basin Plug/ Waste	 29/04/2016 0.0 ° , 0.0 °
Toilet	 29/04/2016 0.0 ° , 0.0 °  29/04/2016 0.0 ° , 0.0 °  29/04/2016 0.0 ° , 0.0 °
Radiator	 29/04/2016 0.0 ° , 0.0 °



Bedroom 2









0.0 ° , 0.0 °

Notes:



Freshly fitted cream carpet, freshly painted cream walls, 1 window, no marks, no scuffs.

Item	Description		
Floors	 29/04/2016	 29/04/2016	 29/04/2016
	0.0 ° , 0.0 °	0.0 ° , 0.0 °	0.0 ° , 0.0 °
Walls	 29/04/2016	 29/04/2016	 29/04/2016
	0.0 ° , 0.0 °	0.0 ° , 0.0 °	0.0 ° , 0.0 °
	 29/04/2016		
	0.0 ° , 0.0 °		

Bedroom 2 (continued)

Item	Description	
Ceiling	 29/04/2016 0.0 ° , 0.0 °	 29/04/2016 0.0 ° , 0.0 °
Windows	 29/04/2016 0.0 ° , 0.0 °	 29/04/2016 0.0 ° , 0.0 °
Doors	 29/04/2016 0.0 ° , 0.0 °	 29/04/2016 0.0 ° , 0.0 °
Door Handle	 29/04/2016 0.0 ° , 0.0 °	 29/04/2016 0.0 ° , 0.0 °


Bedroom 2 (continued)

Item	Description
Sockets	   0.0 ° , 0.0 ° 0.0 ° , 0.0 ° 0.0 ° , 0.0 °
Switches	 0.0 ° , 0.0 °
Lights & Fixtures	 0.0 ° , 0.0 °
Radiator	 0.0 ° , 0.0 °

Bedroom 2 (continued)

Item	Description
Doorstops	 0.0 ° , 0.0 °


Bedroom 3










0.0 ° , 0.0 °

Notes:





Freshly fitted cream carpet, freshly painted cream walls, 1 window, white ceiling, no marks.

Item	Description
Floors	 0.0 ° , 0.0 °  0.0 ° , 0.0 °


Bedroom 3 (continued)

Item	Description		
Walls			
	29/04/2016	29/04/2016	29/04/2016
	0.0 ° , 0.0 °	0.0 ° , 0.0 °	0.0 ° , 0.0 °
			
	29/04/2016		
	0.0 ° , 0.0 °		
Ceiling			
	29/04/2016	29/04/2016	29/04/2016
	0.0 ° , 0.0 °	0.0 ° , 0.0 °	0.0 ° , 0.0 °
Windows			
	29/04/2016	29/04/2016	
	0.0 ° , 0.0 °	0.0 ° , 0.0 °	

Bedroom 3 (continued)

Item	Description	
Doors	 0.0 ° , 0.0 °	 0.0 ° , 0.0 °
Door Handle	 0.0 ° , 0.0 °	 0.0 ° , 0.0 °
Sockets	 0.0 ° , 0.0 °	 0.0 ° , 0.0 °
Switches	 0.0 ° , 0.0 °	

Bedroom 3 (continued)

Item	Description
Lights & Fixtures	 0.0 ° , 0.0 °
Radiator	 0.0 ° , 0.0 °
Doorstops	 0.0 ° , 0.0 °









Main Bath/Shower Room








0.0 ° , 0.0 °

Notes:


Bathroom has cream freshly painted walls, white ceiling, light fixture, there are tiles around the sink and tiles around the bath, all fine, clean and tidy.

Item	Description		
Floors			
	29/04/2016 0.0 °, 0.0 °	29/04/2016 0.0 °, 0.0 °	
Walls			
	29/04/2016 0.0 °, 0.0 °	29/04/2016 0.0 °, 0.0 °	29/04/2016 0.0 °, 0.0 °
			
	29/04/2016 0.0 °, 0.0 °	29/04/2016 0.0 °, 0.0 °	
Ceiling			
	29/04/2016 0.0 °, 0.0 °	29/04/2016 0.0 °, 0.0 °	29/04/2016 0.0 °, 0.0 °

Main Bath/Shower Room (continued)

Item	Description
Windows	 0.0 ° , 0.0 °
Doors	  0.0 ° , 0.0 ° 0.0 ° , 0.0 °
Door Handle	  0.0 ° , 0.0 ° 0.0 ° , 0.0 °
Lights & Fixtures	 0.0 ° , 0.0 °

Main Bath/Shower Room (continued)

Item	Description
Extractor Fan	 29/04/2016 0.0 ° , 0.0 °
Bath	 29/04/2016 0.0 ° , 0.0 °  29/04/2016 0.0 ° , 0.0 °
Bath Tap	 29/04/2016 0.0 ° , 0.0 °
Bath Plug/ Waste	 29/04/2016 0.0 ° , 0.0 °

Main Bath/Shower Room (continued)

Item	Description
Hand Basin	 29/04/2016 0.0 ° , 0.0 °
Basin Tap	 29/04/2016 0.0 ° , 0.0 °
Basin Plug/ Waste	 29/04/2016 0.0 ° , 0.0 °
Toilet	 29/04/2016 0.0 ° , 0.0 °  29/04/2016 0.0 ° , 0.0 °  29/04/2016 0.0 ° , 0.0 °

Main Bath/Shower Room (continued)

Item	Description
Radiator	 0.0 ° , 0.0 °

Property Exterior




0.0 ° , 0.0 °

Item	Description
House Numbers	 0.0 ° , 0.0 °


Property Exterior (continued)

Item	Description
Windows	 0.0 ° , 0.0 °
Light	 0.0 ° , 0.0 °


Back Garden



0.0 ° , 0.0 °


Item	Description
Fence	   0.0 ° , 0.0 ° 0.0 ° , 0.0 ° 0.0 ° , 0.0 °

Cupboard

 0.0 ° , 0.0 °	 0.0 ° , 0.0 °	 0.0 ° , 0.0 °
---	---	--

Notes:

Cupboard at the top of the stairs: all painted cream and white, clean, tidy, no marks, white door.

Item	Description
Inside	 0.0 ° , 0.0 °

Right Side



0.0 °, 0.0 °

Item	Description
Gate	 0.0 °, 0.0 °

PHOTO INDEX

Keys, Meters, and Certificates



0.0°, 0.0°




0.0°, 0.0°



0.0°, 0.0°



0.0°, 0.0°




0.0°, 0.0°



0.0°, 0.0°



0.0°, 0.0°



0.0°, 0.0°


Entrance Door



0.0°, 0.0°



0.0°, 0.0°



0.0°, 0.0°




0.0°, 0.0°

Entrance Door (continued)



29/04/2016

0.0°, 0.0°



29/04/2016

0.0°, 0.0°



29/04/2016


0.0°, 0.0°



29/04/2016


0.0°, 0.0°

Entrance Hall



29/04/2016

0.0°, 0.0°




29/04/2016

0.0°, 0.0°



29/04/2016

0.0°, 0.0°



29/04/2016

0.0°, 0.0°




29/04/2016

0.0°, 0.0°



29/04/2016

0.0°, 0.0°




29/04/2016

0.0°, 0.0°




29/04/2016

0.0°, 0.0°




29/04/2016

0.0°, 0.0°




29/04/2016

0.0°, 0.0°



29/04/2016


0.0°, 0.0°



29/04/2016

0.0°, 0.0°

Entrance Hall (continued)



29/04/2016

0.0°, 0.0°



29/04/2016

0.0°, 0.0°



29/04/2016

0.0°, 0.0°



29/04/2016

0.0°, 0.0°



29/04/2016

0.0°, 0.0°



29/04/2016

0.0°, 0.0°



29/04/2016

0.0°, 0.0°



29/04/2016

0.0°, 0.0°



29/04/2016

0.0°, 0.0°



29/04/2016

0.0°, 0.0°



29/04/2016


0.0°, 0.0°



29/04/2016

0.0°, 0.0°

Storage Cupboard




29/04/2016

0.0°, 0.0°




29/04/2016

0.0°, 0.0°



29/04/2016

0.0°, 0.0°



29/04/2016


0.0°, 0.0°

Storage Cupboard (continued)




29/04/2016

0.0°, 0.0°




29/04/2016

0.0°, 0.0°



29/04/2016

0.0°, 0.0°



29/04/2016


0.0°, 0.0°



29/04/2016

0.0°, 0.0°

Living Room



29/04/2016

0.0°, 0.0°




29/04/2016

0.0°, 0.0°




29/04/2016

0.0°, 0.0°




29/04/2016

0.0°, 0.0°



29/04/2016

0.0°, 0.0°




29/04/2016

0.0°, 0.0°



29/04/2016

0.0°, 0.0°



29/04/2016

0.0°, 0.0°

Living Room (continued)



29/04/2016

0.0 ° , 0.0 °



29/04/2016

0.0 ° , 0.0 °




29/04/2016

0.0 ° , 0.0 °




29/04/2016

0.0 ° , 0.0 °



29/04/2016

0.0 ° , 0.0 °




29/04/2016

0.0 ° , 0.0 °




29/04/2016

0.0 ° , 0.0 °




29/04/2016

0.0 ° , 0.0 °




29/04/2016

0.0 ° , 0.0 °



29/04/2016

0.0 ° , 0.0 °



29/04/2016

0.0 ° , 0.0 °



29/04/2016

0.0 ° , 0.0 °



29/04/2016

0.0 ° , 0.0 °



29/04/2016

0.0 ° , 0.0 °



29/04/2016

0.0 ° , 0.0 °



29/04/2016

0.0 ° , 0.0 °

Living Room (continued)



29/04/2016

0.0°, 0.0°



29/04/2016

0.0°, 0.0°



29/04/2016


0.0°, 0.0°



29/04/2016


0.0°, 0.0°

Kitchen




29/04/2016

0.0°, 0.0°




29/04/2016

0.0°, 0.0°



29/04/2016

0.0°, 0.0°



29/04/2016

0.0°, 0.0°




29/04/2016

0.0°, 0.0°



29/04/2016

0.0°, 0.0°




29/04/2016

0.0°, 0.0°




29/04/2016

0.0°, 0.0°




29/04/2016

0.0°, 0.0°




29/04/2016

0.0°, 0.0°



29/04/2016

0.0°, 0.0°



29/04/2016

0.0°, 0.0°

Kitchen (continued)



29/04/2016

0.0°, 0.0°



29/04/2016

0.0°, 0.0°



29/04/2016

0.0°, 0.0°



29/04/2016

0.0°, 0.0°



29/04/2016

0.0°, 0.0°



29/04/2016

0.0°, 0.0°



29/04/2016

0.0°, 0.0°




29/04/2016

0.0°, 0.0°



29/04/2016

0.0°, 0.0°




29/04/2016

0.0°, 0.0°




29/04/2016

0.0°, 0.0°




29/04/2016

0.0°, 0.0°




29/04/2016

0.0°, 0.0°




29/04/2016

0.0°, 0.0°



29/04/2016

0.0°, 0.0°



29/04/2016

0.0°, 0.0°

Kitchen (continued)



29/04/2016

0.0°, 0.0°



29/04/2016

0.0°, 0.0°



29/04/2016

0.0°, 0.0°



29/04/2016

0.0°, 0.0°



29/04/2016

0.0°, 0.0°



29/04/2016

0.0°, 0.0°



29/04/2016

0.0°, 0.0°



29/04/2016

0.0°, 0.0°




29/04/2016

0.0°, 0.0°



29/04/2016

0.0°, 0.0°



29/04/2016

0.0°, 0.0°



29/04/2016

0.0°, 0.0°




29/04/2016

0.0°, 0.0°



29/04/2016

0.0°, 0.0°



29/04/2016

0.0°, 0.0°



29/04/2016

0.0°, 0.0°

Kitchen (continued)



29/04/2016

0.0°, 0.0°



29/04/2016

0.0°, 0.0°



29/04/2016

0.0°, 0.0°



29/04/2016

0.0°, 0.0°



29/04/2016

0.0°, 0.0°



29/04/2016

0.0°, 0.0°



29/04/2016


0.0°, 0.0°



29/04/2016


0.0°, 0.0°

G/Floor WC




29/04/2016

0.0°, 0.0°




29/04/2016

0.0°, 0.0°




29/04/2016

0.0°, 0.0°




29/04/2016

0.0°, 0.0°




29/04/2016

0.0°, 0.0°



29/04/2016

0.0°, 0.0°



29/04/2016

0.0°, 0.0°



29/04/2016

0.0°, 0.0°

G/Floor WC (continued)



29/04/2016

0.0 °, 0.0 °




29/04/2016

0.0 °, 0.0 °



29/04/2016

0.0 °, 0.0 °



29/04/2016

0.0 °, 0.0 °



29/04/2016

0.0 °, 0.0 °



29/04/2016

0.0 °, 0.0 °



29/04/2016

0.0 °, 0.0 °



29/04/2016

0.0 °, 0.0 °



29/04/2016

0.0 °, 0.0 °



29/04/2016

0.0 °, 0.0 °




29/04/2016

0.0 °, 0.0 °



29/04/2016

0.0 °, 0.0 °



29/04/2016

0.0 °, 0.0 °



29/04/2016

0.0 °, 0.0 °



29/04/2016

0.0 °, 0.0 °



29/04/2016


0.0 °, 0.0 °

Stairwell




29/04/2016

0.0°, 0.0°




29/04/2016

0.0°, 0.0°




29/04/2016

0.0°, 0.0°




29/04/2016

0.0°, 0.0°




29/04/2016

0.0°, 0.0°



29/04/2016


0.0°, 0.0°



29/04/2016


0.0°, 0.0°

First Floor Landing



29/04/2016

0.0°, 0.0°




29/04/2016

0.0°, 0.0°



29/04/2016

0.0°, 0.0°



29/04/2016

0.0°, 0.0°



29/04/2016

0.0°, 0.0°




29/04/2016

0.0°, 0.0°



29/04/2016

0.0°, 0.0°



29/04/2016

0.0°, 0.0°

First Floor Landing (continued)



29/04/2016

0.0 ° , 0.0 °



29/04/2016


0.0 ° , 0.0 °



29/04/2016

0.0 ° , 0.0 °

Master Bedroom



29/04/2016

0.0 ° , 0.0 °




29/04/2016

0.0 ° , 0.0 °



29/04/2016

0.0 ° , 0.0 °



29/04/2016

0.0 ° , 0.0 °



29/04/2016

0.0 ° , 0.0 °




29/04/2016

0.0 ° , 0.0 °




29/04/2016

0.0 ° , 0.0 °




29/04/2016

0.0 ° , 0.0 °




29/04/2016

0.0 ° , 0.0 °




29/04/2016

0.0 ° , 0.0 °



29/04/2016

0.0 ° , 0.0 °



29/04/2016

0.0 ° , 0.0 °

Master Bedroom (continued)



0.0 ° , 0.0 °




0.0 ° , 0.0 °




0.0 ° , 0.0 °



0.0 ° , 0.0 °



0.0 ° , 0.0 °



0.0 ° , 0.0 °



0.0 ° , 0.0 °



0.0 ° , 0.0 °



0.0 ° , 0.0 °




0.0 ° , 0.0 °




0.0 ° , 0.0 °




0.0 ° , 0.0 °



0.0 ° , 0.0 °



0.0 ° , 0.0 °




0.0 ° , 0.0 °

En Suite Bath/Shower Room




29/04/2016

0.0°, 0.0°




29/04/2016

0.0°, 0.0°




29/04/2016

0.0°, 0.0°




29/04/2016

0.0°, 0.0°




29/04/2016

0.0°, 0.0°



29/04/2016

0.0°, 0.0°




29/04/2016

0.0°, 0.0°




29/04/2016

0.0°, 0.0°




29/04/2016

0.0°, 0.0°




29/04/2016

0.0°, 0.0°




29/04/2016

0.0°, 0.0°




29/04/2016

0.0°, 0.0°




29/04/2016

0.0°, 0.0°



29/04/2016

0.0°, 0.0°



29/04/2016

0.0°, 0.0°



29/04/2016

0.0°, 0.0°

En Suite Bath/Shower Room (continued)



29/04/2016

0.0 ° , 0.0 °



29/04/2016

0.0 ° , 0.0 °



29/04/2016

0.0 ° , 0.0 °



29/04/2016

0.0 ° , 0.0 °



29/04/2016

0.0 ° , 0.0 °



29/04/2016

0.0 ° , 0.0 °



29/04/2016

0.0 ° , 0.0 °




29/04/2016

0.0 ° , 0.0 °



29/04/2016

0.0 ° , 0.0 °



29/04/2016

0.0 ° , 0.0 °



29/04/2016

0.0 ° , 0.0 °



29/04/2016

0.0 ° , 0.0 °



29/04/2016

0.0 ° , 0.0 °

Bedroom 2



29/04/2016

0.0°, 0.0°



29/04/2016

0.0°, 0.0°




29/04/2016

0.0°, 0.0°




29/04/2016

0.0°, 0.0°




29/04/2016

0.0°, 0.0°




29/04/2016

0.0°, 0.0°



29/04/2016

0.0°, 0.0°



29/04/2016

0.0°, 0.0°



29/04/2016

0.0°, 0.0°




29/04/2016

0.0°, 0.0°



29/04/2016

0.0°, 0.0°




29/04/2016

0.0°, 0.0°




29/04/2016

0.0°, 0.0°




29/04/2016

0.0°, 0.0°



29/04/2016

0.0°, 0.0°



29/04/2016

0.0°, 0.0°

Bedroom 2 (continued)



29/04/2016

0.0°, 0.0°



29/04/2016

0.0°, 0.0°



29/04/2016

0.0°, 0.0°



29/04/2016

0.0°, 0.0°




29/04/2016

0.0°, 0.0°



29/04/2016


0.0°, 0.0°



29/04/2016


0.0°, 0.0°

Bedroom 3




29/04/2016

0.0°, 0.0°




29/04/2016

0.0°, 0.0°




29/04/2016

0.0°, 0.0°




29/04/2016

0.0°, 0.0°




29/04/2016

0.0°, 0.0°




29/04/2016

0.0°, 0.0°



29/04/2016

0.0°, 0.0°



29/04/2016

0.0°, 0.0°

Bedroom 3 (continued)



29/04/2016

0.0°, 0.0°



29/04/2016

0.0°, 0.0°




29/04/2016

0.0°, 0.0°




29/04/2016

0.0°, 0.0°




29/04/2016

0.0°, 0.0°




29/04/2016

0.0°, 0.0°



29/04/2016

0.0°, 0.0°



29/04/2016

0.0°, 0.0°



29/04/2016

0.0°, 0.0°



29/04/2016

0.0°, 0.0°



29/04/2016

0.0°, 0.0°



29/04/2016

0.0°, 0.0°



29/04/2016

0.0°, 0.0°



29/04/2016


0.0°, 0.0°

Main Bath/Shower Room




29/04/2016

0.0°, 0.0°



29/04/2016

0.0°, 0.0°




29/04/2016

0.0°, 0.0°




29/04/2016

0.0°, 0.0°




29/04/2016

0.0°, 0.0°




29/04/2016

0.0°, 0.0°




29/04/2016

0.0°, 0.0°




29/04/2016

0.0°, 0.0°




29/04/2016

0.0°, 0.0°



29/04/2016

0.0°, 0.0°




29/04/2016

0.0°, 0.0°




29/04/2016

0.0°, 0.0°




29/04/2016

0.0°, 0.0°




29/04/2016

0.0°, 0.0°



29/04/2016

0.0°, 0.0°



29/04/2016

0.0°, 0.0°

Main Bath/Shower Room (continued)



29/04/2016

0.0 °, 0.0 °



29/04/2016

0.0 °, 0.0 °



29/04/2016

0.0 °, 0.0 °



29/04/2016

0.0 °, 0.0 °



29/04/2016

0.0 °, 0.0 °



29/04/2016

0.0 °, 0.0 °



29/04/2016

0.0 °, 0.0 °



29/04/2016

0.0 °, 0.0 °



29/04/2016

0.0 °, 0.0 °



29/04/2016

0.0 °, 0.0 °



29/04/2016

0.0 °, 0.0 °



29/04/2016

0.0 °, 0.0 °



29/04/2016

0.0 °, 0.0 °

Property Exterior



0.0°, 0.0°



0.0°, 0.0°



0.0°, 0.0°



0.0°, 0.0°

Back Garden



0.0°, 0.0°



0.0°, 0.0°




0.0°, 0.0°



0.0°, 0.0°


Cupboard




0.0°, 0.0°



0.0°, 0.0°



0.0°, 0.0°



0.0°, 0.0°

Right Side



29/04/2016

0.0 ° , 0.0 °



29/04/2016

0.0 ° , 0.0 °

DECLARATION

Whilst every care has been taken to ensure the accuracy of this schedule, accuracy cannot be guaranteed by the preparer.

The Landlord and the Tenant(s) are reminded that it is their responsibility to check the accuracy of this schedule and are advised to sign it in confirmation.

This inventory relates only to the furniture, furnishings and all Landlord's equipment and contents in the property. It is no guarantee of, or report on, the adequacy of, or safety of any such equipment or contents, merely a record that such items exist in the property at the date of the inventory and the superficial content of same.

This is to certify that we the undersigned have carefully checked the foregoing inventory and subject to the marginal notes, consider this to be a fair and correct schedule of condition of the contents therein.

The tenant/landlord has 7 days from receipt of this inventory to notify the agent/landlord/inventory company of any discrepancies.

Signature:

Title _____

Signature _____

Print Name _____

Date _____

Signature:

Title _____

Signature _____

Print Name _____

Date _____

Signature:

Title _____

Signature _____

Print Name _____

Date _____