



Frank's Collision Repair
5703 Southampton Drive
Murphy, TX 75081
1-8585478697

01/14/2020, 10:05 AM

TEST DRIVE COPILOT DRIVE REPORT

RO Number: 124546

Invoice Number: 1098

Year: 2019

Insurance: AAA

Make: Jeep

Fleet:

Model: Laredo

VIN: 137474778884488884838

Road Test Type: Collision Repair, Non-ADAS

Technicians: Frank Fender

Start Time: 10:05 AM

Start Mileage: 75,834.0 miles

End Time: 10:32 AM

End Mileage: 75,858.1 miles

Total Time: 0.45 hrs

Total Mileage: 24.1 miles

Highest Speed: 84.0 mph


Weather:

Lowest Speed: 1.0 mph

Average Speed: 42.5 mph

Video Link: <https://testdriveshop48.s3.us-west-1.wasabisys.com/124546-2019-Jeep-Laredo-1-14-2020-10-05.mp4>

Test Drive Speed (this represents the vehicle's speed during the actual test drive):



Test Drive Map (this represents drive path taken during the actual test drive):



Test Drive Recommendations

Non-ADAS Test Drive Checklist

- Verify steering wheel is straight
- Verify vehicle steers straight on street and highway
- Verify there are no unusual noises, vibrations, rough idling, etc..
- Verify transmissions shifts smoothly
- Verify vehicle accelerates and decelerates properly
- Verify cruise control operates properly at different speeds (if equipped)
- Verify vehicle does not pull to either side when braking
- Verify parking brake is operational
- Verify all electrical accessories operate properly

- Verify warning/indicator lights, gauges and horn operates properly
- Verify windshield wipers and washers operate properly
- Verify TPMS system is operational
- Verify Turn signals are operational
- Verify power windows are operational
- Verify power locks are operational
- Verify trunk opens and closes properly
- Verify radio operates properly and previous radio stations are selectable

Verify heating and air conditioning are operational at different speeds