



Side view of entry elevation



Partial view of library elevation. Red Ankara stone infill



View from corridor into lecture hall



View to reading room corridor opening to court. Wooden grilles - kafes



*Turkish Historical Society, Ankara, Turkey*



*Turkish Historical Society, Ankara, Turkey*





Structural skeleton of reinforced concrete



Side entry. Painted concrete column stands on Ankara stone steps



Detail of stair construction and finish



