




Frequent floods in the past caused damage and unsanitary conditions.
Improved drainage now minimizes such problems.



Improved pathways encouraged private landscaping



Improved pathways encouraged private landscaping



Kampung Kebalen Improvement, Surabaya, Indonesia



Entrance to footpath from larger street before improvement



Entrance to foot path from larger street after improvement



Kampung Kebalen Improvement, Surabaya, Indonesia



Kampung Kebalen Improvement, Surabaya, Indonesia



Kampung Kebalen Improvement, Surabaya, Indonesia



Kampung Kebalen Improvement, Surabaya, Indonesia



Improved footpath adjacent to mosque used for additional prayer space



Aerial view of Kampung area



Foothpath and drainage system: before



Foothpath and drainage system: after



Foothpath and drainage system: before



Foothpath and drainage system: after



Typical Kampung street: before



Typical Kampung street: after