

## WEEKLY REPORT




# CATALYST

Project Name : St. Pauls Onalaska

Full Address : 1201 Main St. Onalaska 54650

Date : 12/21/23

### *Project Photos*



### *Construction Activities*

#### Weeks Activities

Exterior sheathing lobby  
Painting in commons  
Insulation commons stage, ramp, storage room floor  
Install tile lower level gang baths  
Exterior, Interior framing lobby  
Begin install lobby stair  
Painting upper and lower  
Casework and Tops  
Build Fire Suppression riser  
Pull in wire feeds from new transformer to main gear.  
Permanent Electric meter set and permanent power to new building.  
Pull wiring from new main gear to existing school.

## WEEKLY REPORT

# CATALYST



Complete the form below

Project Name : St. Pauls Onalaska

Full Address : 1201 Main St. Onalaska 54650

Date : 12/21/23

### Project Photos



### Upcoming Activities

Ceiling grid and ceiling tile continue  
 Window sills  
 Bath casework & tops  
 Complete lobby stair  
 Complete exterior parapets  
 Lower lobby membrane roof  
 Lobby window frames  
 Doors and Hardware  
 LVT flooring upper level  
 Bath Partitions  
 Tile classroom baths and locker room  
 Grout tile all baths  
 Decking and stairs at stage  
 Complete drywall commoms