

## WEEKLY REPORT




# CATALYST

Project Name : St. Pauls Onalaska

Full Address : 1201 Main St. Onalaska 54650

Date : 2/29/24

### Project Photos



### Construction Activities

#### Weeks Activities

Lobby painting  
Gym floor lines, 1st coat final seal coat  
Ceiling grid/tiles upper and lower levels  
Electrical finishes  
Fire alarm devices  
Plumbing finishes  
Flooring Grand Stair  
Robotics Room Epoxy finish begins  
Pre Cleaning upper level  
Wall base  
Concession casework ,tops, sinks  
Grab bars, bath accessories  
Painting hollow metal doors

## WEEKLY REPORT

# CATALYST



Complete the form below

Project Name : St. Pauls Onalaska

Full Address : 1201 Main St. Onalaska 54650

Date : 2/29/24

### Project Photos



### Upcoming Activities

- Electrical finishes
- Door hardware
- Lobby lighting
- Lobby flooring
- Painting lobby areas
- Complete epoxy painting robotics room floor
- Gym floor finishes, base, thresholds
- Locker room lockers
- Door access controls wiring
- Fire alarm devices and testing
- Retaining wall
- Lobby exterior finishes
- Final inspections

