

Online Permit and Complaint Tracking

Permit Details Report

Report Date: 6/7/2011 11:12:17 AM

Application Number: 20101195369
 Form Number: 8

Address(es): 3574 / 023 / 0 3248 18TH ST
 3574 / 023 / 0 3246 18TH ST

Description: Repair fire damage for both levels. correction for complaint notices; (1) 199812862; (2) 200790102 & (3) 200992004. Gypsum board. to be repaired, broken glasses to be replaced; restaurant kitchen to be rebuilt & timber to be replaced if they are burned.

Cost: \$170,000.00
 Occupancy Code: B,R-3
 Building Use: 05 - FOOD/BEVERAGE HNDLNG

Disposition / Stage:

Action Date	Stage	Comments
11/19/2010	TRIAGE	
11/19/2010	FILING	
11/19/2010	FILED	
6/6/2011	APPROVED	
6/6/2011	ISSUED	

Contact Details:

Contractor Details:

License Number: OWNER
 Name: OWNER
 Company Name: OWNER
 Address: OWNER * OWNER CA 00000-0000
 Phone:

Addenda Details:

Description:

Step	Station	Arrive	Start	In Hold	Out Hold	Finish	Checked By	Hold Description
1	BID-INSP	11/19/10	11/19/10			11/19/10	O'RIORDAN PATRICK	
2	HIS	11/15/10	11/15/10			11/15/10	GOGNA DAVID	
3	INTAKE	11/19/10	11/19/10			11/19/10	VALLE JAIME	
4	CP-ZOC	3/9/11	3/9/11			4/13/11	MCCORMICK JIM	
5	BLDG	3/9/11	3/9/11			3/9/11	VALLE JAIME	
6	PAD-STR	6/6/11	6/6/11			6/6/11	PANG DAVID	needs full seismic upgrade.
7	MECH	6/6/11	6/6/11			6/6/11	SHAIKH MOHSIN	Approved, etc
8	CPB	6/6/11	6/6/11			6/6/11	YIP JANET	

This permit has been issued. For information pertaining to this permit, please call 415-558-6096.

Appointments:

Appointment Date	Appointment AM/PM	Appointment Code	Appointment Type	Description	Time Slots
------------------	-------------------	------------------	------------------	-------------	------------

Inspections:

Activity Date	Inspector	Inspection Description	Inspection Status
---------------	-----------	------------------------	-------------------

Special Inspections:

Addenda No.	Completed Date	Inspected By	Inspection Code	Description	Remarks
-------------	----------------	--------------	-----------------	-------------	---------

For information, or to schedule an inspection, call 558-6570 between 8:30 am and 3:00 pm.

Online Permit and Complaint Tracking

COMPLAINT DATA SHEET

Complaint Number: 201131301
Owner/Agent: OWNER DATA SUPPRESSED
Owner's Phone: --
Contact Name: --
Contact Phone: --
Complainant: COMPLAINANT DATA SUPPRESSED
Date Filed: 05/11/2011
Location: 3246 18TH ST
Block: 3574
Lot: 023
Site:
Rating:
Occupancy Code: R-3
Received By: Bernedette Perez
Division: HIS
Complainant's Phone:
Complaint Source: 311 INTERNET REFERRAL
Assigned to Division: HIS
Description: Blighted property-vacant unsafe wooden boards with nails sticking out & graffiti
Instructions: 870689- 311 Service Request

INSPECTOR INFORMATION

DIVISION	INSPECTOR	ID	DISTRICT	PRIORITY
HIS	LOPEZ	6241	16	

REFFERAL INFORMATION

COMPLAINT STATUS AND COMMENTS

DATE	TYPE	DIV	INSPECTOR	STATUS	COMMENT
05/11/11	CASE OPENED	HIS	Lopez	CASE RECEIVED	
05/12/11	GENERAL MAINTENANCE	HIS	Davison	TELEPHONE CALLS	Spoke to BID regarding blight issue.

COMPLAINT ACTION BY DIVISION

NOV (HIS):

NOV (BID):

Inspector Contact Information

[Online Permit and Complaint Tracking home page.](#)

Technical Support for Online Services

If you need help or have a question about this service, please visit our FAQ area.