West Coast Tank Recovery

Oil Tank Detection | Oil Tank Removal | Contaminated Soil Removal

Letter of Compliance

October 22, 2014

Isobel Jones
3434 St. Georges Avenue
North Vancouver, BC
V7N 1V8

Dear Ms. Jones:

We have performed a TW6 M-2 scope metal detection scan for an underground storage tank at the above address.

Due to the result of the scan which may have included probing and exploratory digging we are confident that there is no underground storage tank buried on the property.

Martin Wouters

Disclaimer

As with any technical equipment or precision devices, results are rarely 100% conclusive.
West Coast Tank Recovery Incorporated will not except any lawsuits and or court actions in any way for the future discovery of underground storage tanks especially ones found under the original structure, additions added to the original structure, under storage sheds or detached buildings, under swimming pools, concreted walkways, driveways or slabs which contain rebar or any other metal construction materials or under larger trees, plants or shrubs, decks or patios with minimal clearance.