

Work Order Tracking (Tr)

Find Work Order

Select Action



- List
- Work Order**
- Plans
- Actuals
- Activities
- Measurements
- Axle Configuration
- Related Records
- Safety Plan
- Log

Work Order: 2542355

VEHICLE METRO MOW WEEKLY TRACK INSPECTION

Classification: MTA \ METRO

Classification Description: MTA - METRO

Asset:

Alias:

Location: CHAIN_MARK Metro Chain Markers

Work Location:

Work Type: PM

Status: WSCH

Status Date: 08/17/16 04:17:22 AM

Reported By: MTACRON

Phone:

Reported Date: 08/17/16 04:17:21 AM

On Behalf Of:

Consist:

Asset Details

Year:

Manufacturer:

Model:

Serial #:

Type:

Status:

Asset Condition:

Address Information

Service Address: 1206 6301 Wabash Ave Reisterstown Plaza Baltimore

Formatted Address:

Street Address: 6301 Wabash Ave

Multiple Assets.Locations and Cls Filter

0 - 0 of 0

VEHICLE TRACK INSPECTION REPORTING FORM

Name R. Rogosa Daniel Byrd Date Sept 2 Page 1 of 1
 (Please Print)

Inspected From _____ om _____ To _____ jh _____ ML # _____ 1 WO # **2542355**

Item	Exception Chain Marker No.		Track No.	Rail N/S	Switch No.	Codes		Status S/Y/R	Repair Y/N	W. O. #
	From	To				Comp.	Defect			
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										
13.										
14.										
15.										
16.										
17.										
18.										
19.										
20.										

Item	COMMENTS
1	036+00 COVER BOARD
2	TRASH IN TRACK (LET)
3	596+00 COVER BOARD
4	1690 COVER BOARD
5	Rail THROUGH OUT TRACK Needs To Pick UP

R. Rogosa / Daniel Byrd
Trackwalkers Signature

[Signature]
Supervisory Certification

Work Order Tracking (Tr)

Find Work Order

Select Action

- List
- Work Order**
- Plans
- Actuals
- Activities
- Measurements
- Axle Configuration
- Related Records
- Safety Plan
- Log

Work Order: 2542355

VEHICLE METRO MOW WEEKLY TRACK INSPECTION

Classification: MTA \ METRO

Classification Description: MTA - METRO

Asset:

Alias:

Location: CHAIN_MARK Metro Chain Markers

Work Location:

Work Type: PM

Status: WSCH

Status Date: 08/17/16 04:17:22 AM

Reported By: MTACRON

Phone:

Reported Date: 08/17/16 04:17:21 AM

On Behalf Of:

Consist:

Asset Details

Year:

Manufacturer:

Model:

Serial #:

Type:

Status:

Asset Condition:

Address Information

Service Address: 1206

6301 Wabash Ave Reisterstown Plaza Baltimore

Formatted Address:

Street Address: 6301 Wabash Ave

Multiple Assets.Locations and Cls Filter

0 - 0 of 0

VEHICLE TRACK INSPECTION REPORTING FORM

Name _____ Date 9-2 Page 1 of 1
 (Please Print)

Inspected From _____ om To _____ jh ML # 2 WO # 2542355

Item	Exception Chain Marker No.		Track No.	Rail N/S	Switch No.	Codes		Status S/Y/R	Repair Y/N	W. O. #
	From	To				Comp.	Defect			
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										
13.										
14.										
15.										
16.										
17.										
18.										
19.										
20.										

Item	COMMENTS
	Tunnel Lighting Needs to be fix Remove old Rail on Track Two from Milford Mills to Charles Center

[Handwritten Signature]
 Trackwalkers Signature

[Handwritten Signature]
 Supervisory Certification

Work Order Tracking (Tr)

Find Work Order



Select Action



List

Work Order

Plans

Actuals

Activities

Measurements

Axle Configuration

Related Records

Safety Plan

Log

Work Order: 2585518

(1JH-RA) METRO MOW WEEKLY TRACK INSPECTION W/

Classification: MTA \ METRO

Classification Description: MTA - METRO

Asset:

Alias:

Location: CHAIN_MARK Metro Chain Markers

Work Location:

Work Type: PM

Status: WSCH

Status Date: 09/02/16 04:19:05 AM

Reported By: MTACRON

Phone:

Reported Date: 09/02/16 04:19:04 AM

On Behalf Of:

Consist:

Asset Details

Year:

Manufacturer:

Model:

Serial #:

Type:

Status:

Asset Condition:

Address Information

Service Address: 1206 6301 Wabash Ave Reisterstown Plaza Baltimore

Formatted Address:

Street Address: 6301 Wabash Ave

Multiple Assets, Locations and CIs Filter

0 - 0 of 0



Maryland Department of Transportation
 Maryland Transit Administration
 Right Of Way Inspectors Report

Site: METRO
 Workgroup: MTA472
 START_CHAIN_MARKER: 0
 END_CHAIN_MARKER: 333
 Include History: N

TME1 (TRACK METRO EAST 1) - Workgroup: MTA472

Work Order	Problem	Priority	Position	Reported Defect	Work Type	Component	Quantity	START CHAIN MARKER	CM START OFFSET	END CHAIN MARKER	CM END OFFSET	Report Date
<u>2469281</u> (APPR)	MOW-R00	4	BOTH	MOW-003	CM	MOW-T06	0	7	0	7	0	7/1/16
1 JHRA frog point battered 1A	RAIL			BATTERED		FROG						
<u>2015100</u> (APPR)	MOW-M00	1	THIRD RAIL	MOW-046	CM	MOW-C02	0	36	65	36	65	7/22/15
1 JHRA Coverboard Broken / Bracket Missing 036+65E	TRACK MISCELLANEOUS			MISSING		COVERBOARD						
<u>2033296</u> (MONITOR)	MOW-R00	2	SOUTH	MOW-013	CM	MOW-T02	0	67	60	67	60	8/5/15
1 JHRA Curve Closure Rail Chipped 067+60E JH 1B	RAIL			CHIPPED / PITTED		LEAD OR CLOSURE RAIL						
<u>2013865</u> (APPR)	MOW-M00	1	NORTH	MOW-044	CM	MOW-R08	0	67	70	67	70	7/21/15
1 JHRA Restraining Rail IJ Bolts Loose 067+70E	TRACK MISCELLANEOUS			LOOSE / SLACK		INSULATED JOINT						
Number of Records:							4					



Maryland Department of Transportation
 Maryland Transit Administration
 Right Of Way Inspectors Report



Site: METRO
 Workgroup: MTA472
 START_CHAIN_MARKER: 0
 END_CHAIN_MARKER: 333
 Include History: N

TMEX (TRACK METRO EAST CROSSOVERS) - Workgroup: MTA472												
Work Order	Problem	Priority	Position	Reported Defect	Work Type	Component	Quantity	START CHAIN MARKER	CM START OFFSET	END CHAIN MARKER	CM END OFFSET	Report Date
<u>2552817</u> (APPR)	MOW-R00	3	BOTH	MOW-003	CM	MOW-T06	0	65	0	65	0	8/25/16
1 JHRA diamond frog mushroomed RAIL over 65+00												
<u>2493058</u> (APPR)	MOW-R00	4	BOTH	MOW-003	CM	MOW-T06	0	67	0	67	0	7/21/16
1 JHRA frog point 1b pitted/battered RAIL												
<u>2083379</u> (APPR)	MOW-M00	1	BOTH	MOW-044	CM	MOW-T11	0	68	40	68	40	9/12/15
2 RAJH Frog Bolt Loose West Diamond 068+40E												
<u>2449051</u> (APPR)	MOW-R00	3	BOTH	MOW-013	CM	MOW-T06	0	68	40	68	40	6/15/16
2 RAJH frog point chipped 3A												
<u>2449070</u> (APPR)	MOW-R00	4	BOTH	CHIPPED / PITTED	CM	MOW-T06	0	69	0	69	0	6/15/16
2 RAJH frog point battered 1A												
<u>2254506</u> (APPR)	MOW-M00	1	BOTH	MOW-003	CM	MOW-T06	0	69	25	69	25	1/16/16
2 RAJH Frog Bolts Loose (2) JH 1A 069+25E												
<u>2043020</u> (MONITOR)	MOW-R00	2	RIGHT	MOW-069	CM	MOW-T01	0	70	0	70	0	8/12/15
2 RAJH RH Stock Rail Side Worn (25 Deg) JH 1A												
<u>2059899</u> (COMP)	MOW-M00	2	BOTH	MOW-016	CM	MOW-T09	0	70	0	70	0	8/26/15
1 JHRA Frog Riser Cracked JH 3B												
<u>2493055</u> (APPR)	MOW-R00	3	BOTH	CRACKED / SPLIT	CM	MOW-T06	0	70	6	70	6	7/21/16
1 JHRA JH 3B frog point battered												
<u>2014923</u> (APPR)	MOW-M00	1	LEFT	MOW-003	CM	MOW-T12	0	70	20	70	30	7/22/15
2 RAJH LH Switch Point Fastener Blocks Loose (4) JH 1A												
Number of Records:											10	



Maryland Department of Transportation
 Maryland Transit Administration
 Right Of Way Inspectors Report



Site: METRO
 Workgroup: MTA472
 START_CHAIN_MARKER: 0
 END_CHAIN_MARKER: 333
 Include History: N

TMW1 (TRACK METRO WEST 1) - Workgroup: MTA472

Work Order	Problem	Priority	Position	Reported Defect	Work Type	Component	Quantity	START CHAIN MARKER	CM START OFFSET	END CHAIN MARKER	CM END OFFSET	Report Date
<u>2043305</u> (INPRG) 1 JHRA Two Block Tie Deteriorating (N) 013+85W	MOW-X00 TIES	2	BOTH	MOW-022 DETERIORATING	CM	MOW-X00 TIES	0	13	85	13	85	8/12/15
<u>2043299</u> (INPRG) 1 JHRA Two Block Tie Deteriorating (N) 015+75W	MOW-X00 TIES	2	BOTH	MOW-022 DETERIORATING	CM	MOW-X00 TIES	0	15	75	15	75	8/12/15
<u>2013812</u> (HOLD) 1 JHRA Fastener Pad Cracked/Broken (6) 018+60W	MOW-G00 GROUT PADS	2	BOTH	MOW-016 CRACKED / SPLIT	CM	MOW-X08 CONCRETE G10 PAD	0	18	60	18	60	7/21/15
<u>2469642</u> (APPR) 1 JHRA	MOW-X00 TIES	2	BOTH	MOW-016 CRACKED / SPLIT	CM	MOW-X00 TIES	0	18	85	18	85	7/1/16
<u>2106086</u> (APPR) 1 JHRA Drain Clogged/Fouled (600') 053W-059W	MOW-L00 LEAKS	1	BOTH	MOW-004 BLOCKAGE	CM	MOW-B01 TUNNEL DRAIN	0	53	0	59	0	9/30/15
<u>2080337</u> (APPR) 1 JHRA 3rd Rail Severely Corroded 068+70 - 068+90	MOW-C00 CONTACT RAIL	3	THIRD RAIL	MOW-014 CORRODED	CM	MOW-C05 THIRD RAIL	0	68	70	68	90	9/10/15
<u>2030720</u> (APPR) 1 JHRA IJ Battered BH 1B 069+35W	MOW-R00 RAIL	1	NORTH	MOW-003 BATTERED	CM	MOW-R08 INSULATED JOINT	0	69	35	69	35	8/3/15
<u>2468951</u> (APPR) 1 JHRA Third rail corrosion	MOW-C00 CONTACT RAIL	2	THIRD RAIL	MOW-014 CORRODED	CM	MOW-C05 THIRD RAIL	0	73	0	73	0	7/1/16
<u>2106102</u> (APPR) 1 JHRA Coverboard Bracket Broken 107+15	MOW-M00 TRACK MISCELLANEOUS	1	THIRD RAIL	MOW-017 DAMAGED HARDWARE	CM	MOW-C03 COVER BOARD BRACKET	0	107	15	107	15	9/30/15
<u>2014921</u> (APPR) 1 JHRA Insulator Cup Burnt (4) 140+70 -140+90	MOW-M00 TRACK MISCELLANEOUS	3	THIRD RAIL	MOW-010 BURNT (LUMBER)	CM	MOW-C01 INSULATOR	0	140	70	140	90	7/22/15

3 / 8



Maryland Department of Transportation
 Maryland Transit Administration
 Right Of Way Inspectors Report

Site: METRO
 Workgroup: MTA472
 START_CHAIN_MARKER: 0
 END_CHAIN_MARKER: 333
 Include History: N



TMW1 (TRACK METRO WEST 1) - Workgroup: MTA472												
Work Order	Problem	Priority	Position	Reported Defect	Work Type	Component	Quantity	START CHAIN MARKER	CM START OFFSET	END CHAIN MARKER	CM END OFFSET	Report Date
<u>2015378</u> (APPR)	MOW-R00	1	SOUTH	MOW-014	CM	MOW-R01	0	141	0	141	0	7/22/15
1 JHRA Rail Web/Base Deteriorated (S) 141+00	RAIL			CORRODED		RUNNING RAIL						
<u>2015388</u> (APPR)	MOW-R00	1	THIRD RAIL	MOW-014	CM	MOW-C05	0	141	0	141	0	7/22/15
1 JHRA 3rd Rail Corroded 141+00	RAIL			CORRODED		THIRD RAIL						
<u>2106112</u> (APPR)	MOW-C00	1	THIRD RAIL	MOW-061	CM	MOW-C05	0	148	0	148	0	9/30/15
1 JHRA 3rd Rail Unseated/Out of Insulator Cups 148+00	CONTACT RAIL			POOR SUPPORT		THIRD RAIL						
<u>2106126</u> (APPR)	MOW-R00	2	NORTH	MOW-014	CM	MOW-R00	0	154	0	165	0	9/30/15
1 JHRA Rail Web/Base Corroded (N) 154-165	RAIL			CORRODED		RAIL						
<u>2051473</u> (MONITOR)	MOW-C00	2	THIRD RAIL	MOW-014	CM	MOW-C05	0	158	0	166	0	8/19/15
1 JHRA 3rd Rail Deteriorated 158-166+00	CONTACT RAIL			CORRODED		THIRD RAIL						
<u>2208896</u> (APPR)	MOW-X00	2	BOTH	MOW-016	CM	MOW-X17	0	158	40	158	40	12/10/15
1 JHRA Two Block Tie Broken 158+40W	TIES			CRACKED / SPLIT		CONCRETE TIE RAIL SEAT PAD						
<u>2208897</u> (APPR)	MOW-M00	1	SOUTH	MOW-044	CM	MOW-M01	0	160	0	160	0	12/10/15
1 JHRA Chain Marker Sign 160NW Loose/Hanging	TRACK MISCELLANEOUS			LOOSE / SLACK		CHAIN MARKER						
<u>2212343</u> (APPR)	MOW-F00	3	BOTH	MOW-022	CM	MOW-F05	0	160	0	170	0	12/12/15
1 JHRA Pandrol Clips Broken/Deteriorating 160W-170W	FASTENERS			DETERIORATING		CLIP						
<u>2106138</u> (APPR)	MOW-X00	1	BOTH	MOW-016	CM	MOW-X00	0	161	25	161	25	9/30/15
1 JHRA Two Block Tie Broken 161+25	TIES			CRACKED / SPLIT		TIES						
<u>2015101</u> (APPR)	MOW-M00	1	THIRD RAIL	MOW-046	CM	MOW-C03	0	194	90	195	25	7/22/15
1 JHRA Coverboard Brackets Missing 194+90 & 195+25	TRACK MISCELLANEOUS			MISSING		COVER BOARD BRACKET						



Maryland Department of Transportation
 Maryland Transit Administration
 Right Of Way Inspectors Report

Site: METRO

Workgroup: MTA472

START_CHAIN_MARKER: 0

END_CHAIN_MARKER: 333

Include History: N

TMW1 (TRACK METRO WEST 1) - Workgroup: MTA472

Work Order	Problem	Priority	Position	Reported Defect	Work Type	Component	Quantity	START CHAIN MARKER	CM START OFFSET	END CHAIN MARKER	CM END OFFSET	Report Date
<u>2043013</u> (MONITOR)	MOW-R00	2	NORTH	MOW-015	CM	MOW-R01	0	202	0	214	0	8/12/15
1 JHRA Rail Corrugation (N) 202 - RAIL 214+00				CORRUGATED		RUNNING RAIL						
<u>2013741</u> (APPR)	MOW-P00	1	BOTH	MOW-044	CM	MOW-P00	0	237	50	237	50	7/21/15
1 JHRA Shim Plate Loose 237+50	PLATES			LOOSE / SLACK		PLATES						
<u>2017722</u> (APPR)	MOW-P00	2	BOTH	MOW-018	CM	MOW-P00	0	238	0	268	0	7/24/15
1 JHRA LB Foster Plates Deteriorating 238 - 268	PLATES			DEFECTIVE - NO LONGER FUNCTIONING		PLATES						
<u>2030745</u> (APPR)	MOW-P00	1	SOUTH	MOW-046	CM	MOW-P00	0	248	10	248	10	8/3/15
1 JHRA Shim Plate Missing 248+10W	PLATES			MISSING		PLATES						
<u>2549815</u> (APPR)	MOW-M00	3	SOUTH	MOW-044	PM	MOW-C02	0	262	0	272	0	8/23/16
1 JHRA coverboard bent 262-272	TRACK MISCELLANEOUS			LOOSE / SLACK		COVERBOARD						
<u>2014064</u> (APPR)	MOW-M00	1	THIRD RAIL	MOW-017	CM	MOW-C03	0	267	50	272	0	7/21/15
1 JHRA Coverboard Brackets Bent 267+50 - 272	TRACK MISCELLANEOUS			DAMAGED HARDWARE		COVER BOARD BRACKET						
<u>2030747</u> (MONITOR)	MOW-R00	2	SOUTH		CM	MOW-R01	0	274	0	274	0	8/3/15
1 JHRA Rail Side Worm (22 Deg) 274+00	RAIL					RUNNING RAIL						
Number of Records:												

5 / 8



Maryland Department of Transportation
 Maryland Transit Administration
 Right Of Way Inspectors Report



Workgroup: MTA472
 Site: METRO
 START_CHAIN_MARKER: 0
 END_CHAIN_MARKER: 333
 Include History: N

TAWX (TRACK METRO WEST CROSSOVERS) - Workgroup: MTA472												
Work Order	Problem	Priority	Position	Reported Defect	Work Type	Component	Quantity	START CHAIN MARKER	CM START OFFSET	END CHAIN MARKER	CM END OFFSET	Report Date
2053299 (MONITOR)	MOW-R00	2	RIGHT	MOW-013	CM	MOW-T03	0	4	73	4	73	8/20/15
1 JHRA RH Switch Point Chipped / Pitted CC 3B	RAIL			CHIPPED / PITTED		SWITCH POINT						
2053301 (MONITOR)	MOW-R00	2	LEFT	MOW-069	CM	MOW-T03	0	4	73	4	73	8/20/15
1 JHRA LH Switch Point Chipped / Pitted CC 3B	RAIL			SIDE WEAR (RAIL)		SWITCH POINT						
2017699 (APPR)	MOW-M00	1	THIRD RAIL	MOW-046	CM	MOW-C03	0	7	50	7	50	7/24/15
1 JHRA 3rd Rail Side Approach Hardware Missing CC 1B 007+50	TRACK MISCELLANEOUS			MISSING		COVER BOARD BRACKET						
2514571 (APPR)	MOW-R00	4	BOTH	MOW-003	CM	MOW-T06	0	8	50	8	50	8/5/16
1 JHRA cc 008+50 frog point battered	RAIL			BATTERED		FROG						
2493075 (APPR)	MOW-Q00	2	BOTH	MOW-080	CM	MOW-B01	0	66	0	70	0	7/21/16
2 RAJH trash build up 070-066	RIGHT OF WAY			TRASH AND DEBRIS		TUNNEL DRAIN						
2030698 (MONITOR)	MOW-R00	2	SOUTH	MOW-062	CM	MOW-R08	0	66	80	66	80	8/3/15
1 JHRA IJ Battered BH-3B 066+80W	RAIL			PUMPING		INSULATED JOINT						
2014043 (HOLD)	MOW-X00	2	BOTH	MOW-062	CM	MOW-X00	0	67	70	68	50	7/21/15
2 RAJH Ties Pumping BH 068+50 - 067+70W	TIES					TIES						
2449048 (APPR)	MOW-M00	3	THIRD RAIL	MOW-017	CM	MOW-C03	0	68	70	68	70	6/15/16
2 RAJH switch point battered	TRACK MISCELLANEOUS			DAMAGED HARDWARE		COVER BOARD BRACKET						
2013791 (HOLD)	MOW-M00	2	SOUTH	MOW-046	CM	MOW-M09	0	69	0	69	0	7/21/15
2 RAJH Crosswalk Missing BH 3A 069+00W	TRACK MISCELLANEOUS			MISSING		SAFETY WALK						
2030709 (MONITOR)	MOW-R00	2	RIGHT	MOW-013	CM	MOW-T03	0	69	30	69	30	8/3/15
1 JHRA Switch Point Chipped BH-1B 069+30W	RAIL			CHIPPED / PITTED		SWITCH POINT						



Maryland Department of Transportation
 Maryland Transit Administration
 Right Of Way Inspectors Report



Site: METRO
 Workgroup: MTA472
 START_CHAIN_MARKER: 0
 END_CHAIN_MARKER: 333
 Include History: N

THWX (TRACK METRO WEST CROSSOVERS) - Workgroup: MTA472													
Work Order	Problem	Priority	Position	Reported Defect	Work Type	Component	Quantity	START CHAIN MARKER	CM START OFFSET	END CHAIN MARKER	CM END OFFSET	Report Date	
2549819 (APPR)	MOW-R00 RAIL	2	BOTH	MOW-003 BATTERED	PM	MOW-T06 FROG	0	230	0	230	0	8/23/16	
1 JHRA frog 1B needs grinding 230													
Number of Records:							11						



Maryland Department of Transportation
 Maryland Transit Administration
 Right Of Way Inspectors Report

Site: METRO
 Workgroup: MTA472
 START_CHAIN_MARKER: 0
 END_CHAIN_MARKER: 333
 Include History: N



Inspection Completed? Yes No If No Why? _____

Item	Exception Chain Marker No.		Track No.	Position N/S	Switch No.	Comp.	Codes		Priority	Alias
	From	To					Defect			
1	CH# 79	—	2	S	1B		BRACE PLATE		1	TMWX
2	075	—	2		1D		BLOCKS LOOSE		2	TMWX
3	008	—	1				LIFES OUT		2	TMWX
4										
5										
6										
7										
8										

Notes: 1- BRACE PLATE LOOSE
 2- BLOCKS MISSING ON WEST WING OF FROG
 3- LIFES OUT AT CHARLES CT. INTERLOCKING

Track Walker: John Collins Sign: [Signature] Date: 9-7-16
 Print: Joseph Anthony Joseph Brachman Sign: [Signature] Date: 9-7-16
 Watchman: _____ Sign: _____ Date: _____
 Track Inspection: _____ Sign: [Signature] Date: 9-21-16
 Supervisor: _____ Sign: _____ Date: _____