

Work Order Tracking (Tr)

Find Work Order

Select Action

- List
- Work Order**
- Plans
- Actuals
- Activities
- Measurements
- Axle Configuration
- Related Records
- Safety Plan
- Log

Work Order: 2600308 (1JH-RA) METRO MOW WEEKLY TRACK INSPECTION WA

Classification: MTA \ METRO

Classification Description: MTA - METRO

Asset: >>>

Alias:

Location: CHAIN_MARK >>> Metro Chain Markers

Work Location: >>>

Work Type: PM

Status: WSCH

Status Date: 09/30/16 04:21:13 AM

Reported By: MTACRON >>>

Phone:

Reported Date: 09/30/16 04:21:13 AM

On Behalf Of: >>>

Consist: >>>

Asset Details

Year:

Manufacturer: >>>

Model: >>>

Serial #:

Type: >>>

Status:

Asset Condition:

Address Information

Service Address: 1206 >>> 6301 Wabash Ave Reisterstown Plaza Baltimore

Formatted Address:

Street Address: 6301 Wabash Ave

Multiple Assets, Locations and Cls Filter

0 - 0 of 0



Maryland Department of Transportation
 Maryland Transit Administration
 Right Of Way Inspectors Report



Site: METRO
 Workgroup: MTA472
 START_CHAIN_MARKER: 0
 END_CHAIN_MARKER: 333
 Include History: N

TME1 (TRACK METRO EAST 1) - Workgroup: MTA472

Work Order	Problem	Priority	Position	Reported Defect	Work Type	Component	Quantity	START CHAIN MARKER	CM START OFFSET	END CHAIN MARKER	CM END OFFSET	Report Date
2469281 (APPR) 1 JHRA frog point battered 1A	MOW-R00 RAIL	4	BOTH	MOW-003 BATTERED	CM	MOW-T06 FROG	0	7	0	7	0	7/1/16
2015100 (APPR) 1 JHRA Coverboard Broken / Bracket Missing 036+65E	MOW-M00 TRACK MISCELLANEOUS	1	THIRD RAIL	MOW-046 MISSING	CM	MOW-C02 COVERBOARD	0	36	65	36	65	7/22/15
2033296 (MONITOR) 1 JHRA Curve Closure Rail Chipped 067+60E JH 1B	MOW-R00 RAIL	2	SOUTH	MOW-013 CHIPPED / PITTED	CM	MOW-T02 LEAD OR CLOSURE RAIL	0	67	60	67	60	8/5/15
2013865 (APPR) 1 JHRA Restraining Rail IJ Bolts Loose 067+70E	MOW-M00 TRACK MISCELLANEOUS	1	NORTH	MOW-044 LOOSE / SLACK	CM	MOW-R08 INSULATED JOINT	0	67	70	67	70	7/21/15

Number of Records: 4



Maryland Department of Transportation
 Maryland Transit Administration
 Right Of Way Inspectors Report
 Site: METRO
 Workgroup: MTA472
 START_CHAIN_MARKER: 0
 END_CHAIN_MARKER: 333
 Include History: N



TMEX (TRACK METRO EAST CROSSOVERS) - Workgroup: MTA472												
Work Order	Problem	Priority	Position	Reported Defect	Work Type	Component	Quantity	START MARKER	CM START OFFSET	END CHAIN MARKER	CM END OFFSET	Report Date
<u>2552817</u> (APPR)	MOW-R00	3	BOTH	MOW-003	CM	MOW-T06	0	65	0	65	0	8/25/16
1 JHRA diamond frog mushroomed over 65+00	RAIL			BATTERED		FROG						
<u>2493058</u> (APPR)	MOW-R00	4	BOTH	MOW-003	CM	MOW-T06	0	67	0	67	0	7/21/16
1 JHRA frog point 1b pitted/battered	RAIL			BATTERED		FROG						
<u>2083379</u> (APPR)	MOW-M00	1	BOTH	MOW-044	CM	MOW-T11	0	68	40	68	40	9/12/15
TRACK MISCELLANEOUS				LOOSE / SLACK		FROG BOLT						
<u>2449051</u> (APPR)	MOW-R00	3	BOTH	MOW-013	CM	MOW-T06	0	68	40	68	40	6/15/16
2 RAJH Frog Bolt Loose West Diamond 068+40E												
<u>2449070</u> (APPR)	MOW-R00	4	BOTH	MOW-003	CM	MOW-T06	0	69	0	69	0	6/15/16
2 RAJH frog point chipped 3A	RAIL			CHIPPED / PITTED		FROG						
<u>2254506</u> (APPR)	MOW-M00	1	BOTH	MOW-044	CM	MOW-T11	0	69	25	69	25	1/16/16
2 RAJH frog point battered 1A	RAIL			BATTERED		FROG						
<u>2043020</u> (MONITOR)	MOW-R00	2	RIGHT	MOW-069	CM	MOW-T01	0	70	0	70	0	8/12/15
2 RAJH RH Stock Rail Side Worn (25 Deg) JH 1A	RAIL			SIDE WEAR (RAIL)		STOCK RAIL						
<u>2059899</u> (COMP)	MOW-M00	2	BOTH	MOW-016	CM	MOW-T09	0	70	0	70	0	8/26/15
1 JHRA Frog Riser Cracked	TRACK MISCELLANEOUS			CRACKED / SPLIT		FROG GUARD						
<u>2493055</u> (APPR)	MOW-R00	3	BOTH	MOW-003	CM	MOW-T06	0	70	6	70	6	7/21/16
1 JHRA JH 3B frog point battered	RAIL			BATTERED		FROG						
<u>2014923</u> (APPR)	MOW-M00	1	LEFT	MOW-044	CM	MOW-T12	0	70	20	70	30	7/22/15
2 RAJH LH Switch Point Fastener Blocks Loose (4) JH 1A	TRACK MISCELLANEOUS			LOOSE / SLACK		SPACER BLOCK BOLT						
<u>2573519</u> (WAPPR)	MOW-M00	2	WEST	MOW-T06	CM	MOW-T06	0	75	0	75	0	9/8/16
1 JHRA blocks missing wing of frog	TRACK MISCELLANEOUS			FROG		FROG						



Maryland Department of Transportation
 Maryland Transit Administration
 Right Of Way Inspectors Report
 Site: METRO
 Workgroup: MTA472
 START_CHAIN_MARKER: 0
 END_CHAIN_MARKER: 333
 Include History: N



TMEX (TRACK METRO EAST CROSSOVERS) - Workgroup: MTA472												
Work Order	Problem	Priority	Position	Reported Defect	Work Type	Component	Quantity	START CHAIN MARKER	CM START OFFSET	END CHAIN MARKER	CM END OFFSET	Report Date
2573518 (APPR)	MOW-M00	1	SOUTH	MOW-044	CM	MOW-R09	0	79	0	79	0	9/8/16
1 JHRA brace plate loose 1B 079	TRACK MISCELLANEOUS			LOOSE / SLACK		RESTRAINING RAIL BRACE						
Number of Records:							12					



Site: METRO

Workgroup: MTA472

START_CHAIN_MARKER: 0

END_CHAIN_MARKER: 333

Include History: N

TMWX (TRACK METRO WEST CROSSOVERS) - Workgroup: MTA472

Work Order	Problem	Priority	Position	Reported Defect	Work Type	Component	Quantity	START CHAIN MARKER	CM START OFFSET	END CHAIN MARKER	CM END OFFSET	Report Date
2030709 (MONITOR)	MOW-R00	2	RIGHT	MOW-013	CM	MOW-T03	0	69	30	69	30	8/3/15
1 JHRA Switch Point Chipped BH-1B 069+30W	RAIL			CHIPPED / PITTED		SWITCH POINT						
2549819 (APPR)	MOW-R00	2	BOTH	MOW-003	PM	MOW-T06	0	230	0	230	0	8/23/16
1 JHRA frog 1B needs grinding 230	RAIL			BATTERED		FROG						

Number of Records: 12



Workgroup: MTA472
START_CHAIN_MARKER: 0
END_CHAIN_MARKER: 333
Include History: N

Inspection Completed? Yes No If No Why? _____

Item	Exception Chain Marker No.		Track No.	Position N/S	Switch No.	Codes		Priority	Alias
	From	To				Comp.	Defect		
1	068480		1	N/S	1B	S03	038	1	
2									
3									
4									
5									
6									
7									
8									

Notes: 1. Water Leak

Track Walker: Joe Brackinyc Print Date: 10.3.16
 _____ Print Date: _____
 _____ Print Date: _____
 Watchman: [Signature] Print Date: 10/3/16
 _____ Print Date: _____
 Track Inspection Supervisor: [Signature] Print Date: _____

Work Order Tracking (Tr)

Find Work Order



Select Action



- List
- Work Order**
- Plans
- Actuals
- Activities
- Measurements
- Axle Configuration
- Related Records
- Safety Plan
- Log

Work Order: 2588031

VEHICLE METRO MOW WEEKLY TRACK INSPECTION

Classification: MTA \ METRO

Classification Description: MTA - METRO

Asset:

Alias:

Location: CHAIN_MARK Metro Chain Markers

Work Location:

Work Type: PM

Status: WSCH

Status Date: 09/21/16 04:14:30 AM

Reported By: MTACRON

Phone:

Reported Date: 09/21/16 04:14:29 AM

On Behalf Of:

Consist:

Asset Details

Year:

Manufacturer:

Model:

Serial #:

Type:

Status:

Asset Condition:

Address Information

Service Address: 1206

6301 Wabash Ave Reisterstown Plaza Baltimore

Formatted Address:

Street Address: 6301 Wabash Ave

Multiple Assets.Locations and Cls : Filter

0 - 0 of 0

VEHICLE TRACK INSPECTION REPORTING FORM

Name Joe Brookmeyer Date 10-8-16 Page 1 of 1
 (Please Print)

Inspected From JH To OM ML # 1&2 WO # 2588031

Item	Exception Chain Marker No.		Track No.	Rail N/S	Switch No.	Codes		Status S/Y/R	Repair Y/N	W. O. #
	From	To				Comp.	Defect			
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										
13.										
14.										
15.										
16.										
17.										
18.										
19.										
20.										

Item COMMENTS

	No New Defects

Joe Brookmeyer
Trackwalkers Signature

[Signature]
Supervisory Certification

