

Work Order Tracking (Tr)

Find Work Order



Select Action



- List
- Work Order**
- Plans
- Actuals
- Activities
- Measurements
- Axle Configuration
- Related Records
- Safety Plan
- Log

Work Order: 2669976

(1JH-RA) METRO MOW WEEKLY TRACK INSPECTION W

Classification: MTA \ METRO

Classification Description: MTA - METRO

Asset:

Alias:

Location: CHAIN\_MARK >> Metro Chain Markers

Work Location:

Work Type: PM

Status: WSCH

Status Date: 11/18/16 04:16:20 AM

Reported By: MTACRON

Phone:

Reported Date: 11/18/16 04:16:20 AM

On Behalf Of:

Consist:

Asset Details

Year:

Manufacturer:

Model:

Serial #:

Type:

Status:

Asset Condition:

Address Information

Service Address: 1206

>> 6301 Wabash Ave Relisterstown Plaza Baltimore

Formatted Address:

Street Address: 6301 Wabash Ave

Multiple Assets.Locations and Cls Filter

0 - 0 of 0





Maryland Department of Transportation  
Maryland Transit Administration  
Right Of Way Inspectors Report

Site: METRO  
Workgroup: MTA472  
START\_CHAIN\_MARKER: 0  
END\_CHAIN\_MARKER: 333  
Include History: N



Inspection Completed?  Yes  No If No Why? \_\_\_\_\_

Item	Exception Chain Marker No.		Track No.	Position N/S	Switch No.	Codes		Priority	Alias
	From	To				Comp.	Defect		
1									
2									
3									
4									
5									
6									
7									
8									

Notes: No New Defects

Track Walker: Joe Brackmyer Date: 11-21-16  
Print \_\_\_\_\_ Sign \_\_\_\_\_

Watchman: \_\_\_\_\_ Date: \_\_\_\_\_  
Print \_\_\_\_\_ Sign \_\_\_\_\_

Track Inspection Supervisor: \_\_\_\_\_ Date: 12.14.16  
Print \_\_\_\_\_ Sign \_\_\_\_\_





Maryland Department of Transportation  
 Maryland Transit Administration  
 Right Of Way Inspectors Report



Site: METRO  
 Workgroup: MTA472  
 START\_CHAIN\_MARKER: 0  
 END\_CHAIN\_MARKER: 333  
 Include History: N

TRAVEL (TRACK METRO WEST CROSSOVERS) - WOI KGROUP: MTA472

Work Order	Problem	Priority	Position	Reported Defect	Work Type	Component	Quantity	START CHAIN MARKER	CM START OFFSET	END CHAIN MARKER	CM END OFFSET	Report Date
2030709 (MONITOR)	MOW-R00	2	RIGHT	MOW-013	CM	MOW-T03	0	69	30	69	30	8/23/15
1 JHRA Switch Point Chipped BH-1B 069+30W	RAIL			CHIPPED / PITTED		SWITCH POINT						
2549819 (APPR)	MOW-R00	2	BOTH	MOW-003	PM	MOW-T06	0	230	0	230	0	8/23/15
1 JHRA frog 1B needs grinding 230	RAIL			BATTERED		FROG						
<b>Number of Records:</b>							12					



Work Order Tracking (Tr)

Find Work Order

Select Action



- List
- Work Order**
- Plans
- Actuals
- Activities
- Measurements
- Axle Configuration
- Related Records
- Safety Plan
- Log

Work Order: 2669964

(2RA-JH) METRO MOW WEEKLY TRACK INSPECTION W

Classification: MTA \ METRO

Classification Description: MTA - METRO

Asset

Alias:

Location: CHAIN\_MARK Metro Chain Markers

Work Location:

Work Type: PM

Status: WSCH

Status Date: 11/19/16 04:16:08 AM

Reported By: MTACRON

Phone:

Reported Date: 11/19/16 04:16:07 AM

On Behalf Of:

Consist:

Asset Details

Year:

Manufacturer:

Model:

Serial #:

Type:

Status:

Asset Condition:

Address Information

Service Address: 1206 6301 Wabash Ave Reisterstown Plaza Baltimore

Formatted Address:

Street Address: 6301 Wabash Ave

Multiple Assets, Locations and Cls Filter

0 - 0 of 0







Maryland Department of Transportation  
 Maryland Transit Administration  
 Right Of Way Inspectors Report

Site: METRO

Workgroup: MTA472

START\_CHAIN\_MARKER: 0  
 END\_CHAIN\_MARKER: 333

Include History: N



Inspection Completed?

Yes

No

If No Why?

Item	Exception Chain Marker No.		Track No.	Position N/S	Switch No.	Comp.	Codes		Defect	Priority	Alias
	From	To									
1											
2											
3											
4											
5											
6											
7											
8											

Notes:

Track Walker:

Print: *Alvin Jefferson*  
 Print: *Alvin*

Sign: *Alvin Jefferson*  
 Sign: \_\_\_\_\_

Date: *11-22-16*

Date: \_\_\_\_\_

Watchman:

Print: *Guest's Chaddock*  
 Print: \_\_\_\_\_

Sign: *Guest's Chaddock*  
 Sign: \_\_\_\_\_

Date: *11-22-16*

Date: *12.11.16*

Track Inspection Supervisor: Print





**Maryland Department of Transportation**  
**Maryland Transit Administration**  
**Right Of Way Inspectors Report**

Site: METRO  
 Workgroup: MTA472  
 START\_CHAIN\_MARKER: 0  
 END\_CHAIN\_MARKER: 333  
 Include History: N



STATION: CRACK (METRO WEST CROSSOVERS) - WORKGROUP: MTA472

Work Order	Problem	Priority	Position	Reported Defect	Work Type	Component	Quantity	START CHAIN MARKER	CM START OFFSET	END CHAIN MARKER	CM END OFFSET	Report Date
2030709 (MONITOR)	MOW-R00	2	RIGHT	MOW-013	CM	MOW-T03	0	69	30	69	30	8/3/15
1 JHRA Switch Point Chipped BH-1B 069+30W	RAIL			CHIPPED / PITTED		SWITCH POINT						
2549819 (APPR)	MOW-R00	2	BOTH	MOW-003	PM	MOW-T06	0	230	0	230	0	8/23/16
1 JHRA frog 1B needs grinding 230	RAIL			BATTERED		FROG						
<b>Number of Records:</b>							<b>12</b>					



Work Order Tracking (Tr)

Find Work Order

Select Action

- List
- Work Order
- Plans
- Actuals
- Activities
- Measurements
- Axle Configuration
- Related Records
- Safety Plan
- Log

Work Order: 2658403

VEHICLE METRO MOW WEEKLY TRACK INSPECTION

Classification: MTA \ METRO

Classification Description: MTA - METRO

Asset:

Alias:

Location: CHAIN\_MARK Metro Chain Markers

Work Location:

Work Type: PM

Status: WSCH

Status Date: 11/09/16 04:16:47 AM

Reported By: MTACRON

Phone:

Reported Date: 11/09/16 04:16:47 AM

On Behalf Of:

Consist:

Asset Details

Year:

Manufacturer:

Model:

Serial #:

Type:

Status:

Asset Condition:

Address Information

Service Address: 1206

6301 Wabash Ave Reisterstown Plaza Baltimore

Formatted Address:

Street Address: 6301 Wabash Ave

Multiple Assets, Locations and CIs Filter

0 - 0 of 0



Work Order Tracking (Tr)

Find Work Order



Select Action



- List
- Work Order**
- Plans
- Actuals
- Activities
- Measurements
- Axle Configuration
- Related Records
- Safety Plan
- Log

Work Order: 2646579

VEHICLE METRO MOW WEEKLY TRACK INSPECTION

Classification: MTA \ METRO

Classification Description: MTA - METRO

Asset:

Alias:

Location: CHAIN\_MARK Metro Chain Markers

Work Location:

Work Type: PM

Status: WSCH

Status Date: 11/02/16 04:14:42 AM

Reported By: MTACRON

Phone:

Reported Date: 11/02/16 04:14:41 AM

On Behalf Of:

Consist:

Asset Details

Year:

Manufacturer:

Model:

Serial #:

Type:

Status:

Asset Condition:

Address Information

Service Address: 1206

6301 Wabash Ave Reisterstown Plaza Baltimore

Formatted Address:

Street Address: 6301 Wabash Ave

Multiple Assets.Locations and Cls : Filter

0 - 0 of 0





# VEHICLE TRACK INSPECTION REPORTING FORM

Name DANIEL BYRD Date 11/26/2016 Page 1 of 1  
 (Please Print)

Inspected From JH To OM ML # 2 WO # 2646579

Item	Exception Chain Marker No.		Track No.	Rail N/S	Switch No.	Codes		Status S/Y/R	Repair Y/N	W. O. #
	From	To				Comp.	Defect			
1.	66.2	66.2	2	S		J01	Low	S	N	
2.	57.8	57.8	2	S		C03	Missing	S	N	
3.	47.8	47.2	2	S		M06	Light	S	N	
4.	46.	46.	2	S		C03	Missing	S	N	
5.	38.	28.	2	S		C03	Missing	S	N	
6.	24.4	34	2	S		C03	Missing	S	N	
7.	23.4	24.4	2	S		C03	Missing	S	N	
8.	22.2	22.2	2	S		M06	Light	S	N	
9.	18.2	18.4	2	S		C03	Missing	S	N	
10.	16.4	16.2	2	S		C03	Missing	S	N	
11.	09.6	09.6	2	S		C03	Missing	S	N	
12.	05.6	05.6	2	S		C03	Missing	S	N	
13.	04.0	04.0	2	S		C03	Missing	S	N	
14.										
15.										
16.										
17.										
18.										
19.										
20.										

Item **COMMENTS**

The Coverboard is Missing / Light and out in Tunnel Low IJ at McDonough Rd RA and CS Station need cleaning in the track area

  
 Trackwalkers Signature

  
 Supervisory Certification

11/26/2016



Work Order Tracking (Tr)

Find Work Order



Select Action



- List
- Work Order
- Plans
- Actuals
- Activities
- Measurements
- Axle Configuration
- Related Records
- Safety Plan
- Log

Work Order: 2667146

VEHICLE METRO MOW WEEKLY TRACK INSPECTION

Asset:

Children of Work Order 2667146

Filter

0 - 0 of 0

Sequence Work Order Summary Location Asset Failure

Tasks for Work Order 2667146

Filter

1 - 4 of 4

Sequence Task Summary

▶	10	10	Perform inspection according to SOP	🔗
▶	20	20	Inspect from hi -rail 20mph	🔗
▶	30	30	Complete Report Form	🔗
▶	40	40	Repeat Walking in lieu of Riding	🔗

Labor Materials Services Tools Repair Orders

Labor

Filter

0 - 0 of 0

Task Labor Approved? Start Date Start Time End Time



# VEHICLE TRACK INSPECTION REPORTING FORM

Name Daniel Byrd M Date 11-27-2016 Page 1 of 1  
 (Please Print)

Inspected From JH To OM ML # 1 WO # 2667.146

Item	Exception Chain Marker No.		Track No.	Rail N/S	Switch No.	Codes		Status S/Y/R	Repair Y/N	W. O. #
	From	To				Comp.	Defect			
1.	66.2	66.2	1	S		SOL	LOW	Y	N	
2.	59.8	59.8	1	S/N		C03	MISSING	S	N	
3.	59.2	59.2	1	S/N		C10	INSULATED JOINT	S	N	
4.	57.0	57.0	1	S/N		D 26	OUT OF SURFACE	S	N	
5.	52.0	52.0	1	S		D 26	LOW PROFILE TAIL	S	N	
6.	46.4	41.2	1	S/N		D 26	CONVUP	S	N	
7.	36.6	36.6	1	N		C03	MISSING	S	N	
8.	20.2	20.2	1	N		C03	MISSING	S	N	
9.	18.6	18.4	1	N		C03	MISSING	S	N	
10.	16.2	16.2	1	N		C03	MISSING	S	N	
11.	15.8	15.8	1	S		C03	MISSING	S	N	
12.										
13.										
14.										
15.										
16.										
17.										
18.										
19.										
20.										

Item COMMENTS

*Coverboard is missing - IS Joint and CONVUP need to be surface - RA - CST MOND - PN - UPT - IEX - CC - JH - Stations - Trackway need to be clean*

*Daniel Byrd*  
Trackwalkers Signature

*[Signature]*  
Supervisory Certification

