

Work Order Tracking (Tr)

Find Work Order



Select Action



- List
- Work Order**
- Plans
- Actuals
- Activities
- Measurements
- Axle Configuration
- Related Records
- Safety Plan
- Log

Work Order: 2677393

(1JH-RA) METRO MOW WEEKLY TRACK INSPECTION W/

Classification: MTA \ METRO

Classification Description: MTA - METRO

Asset:

Alias:

Location: CHAIN\_MARK Metro Chain Markers

Work Location:

Work Type: PM

Status: WSCH

Status Date: 11/25/16 04:17:39 AM

Reported By: MTACRON

Phone:

Reported Date: 11/25/16 04:17:38 AM

On Behalf Of:

Consist:

Asset Details

Year:

Manufacturer:

Model:

Serial #:

Type:

Status:

Asset Condition:

Address Information

Service Address: 1206

6301 Wabash Ave Reisterstown Plaza Baltimore

Formatted Address:

Street Address: 6301 Wabash Ave

Multiple Assets, Locations and CIs Filter

0 - 0 of 0





Maryland Department of Transportation  
 Maryland Transit Administration  
 Right Of Way Inspectors Report

Site: METRO  
 Workgroup: MTA472  
 START\_CHAIN\_MARKER: 0  
 END\_CHAIN\_MARKER: 333  
 Include History: N

TME1 (TRACK METRO EAST 1) - Workgroup: MTA472

Work Order	Problem	Priority	Position	Reported Defect	Work Type	Component	Quantity	START CHAIN MARKER	START OFFSET	END CHAIN MARKER	END OFFSET	Report Date
<a href="#">2469281</a> (APPR)	MOW-R00	4	BOTH	MOW-003	CM	MOW-T06	0	7	0	7	0	7/1/16
1 JHRA frog point battered 1A	RAIL			BATTERED		FROG						
<a href="#">2651904</a> (APPR)	MOW-B00	5	BOTH	MOW-065	CM	MOW-B00	0	8	0	8	0	11/3/16
1 JHRA lites out 008+00	TUNNEL			SAFETY HAZARD		TUNNEL						
<a href="#">2015100</a> (APPR)	MOW-M00	1	THIRD RAIL	MOW-046	CM	MOW-C02	0	36	65	36	65	7/22/15
1 JHRA Coverboard Broken / Bracket Missing 036+65E	TRACK MISCELLANEOUS			MISSING		COVERBOARD						
<a href="#">2651902</a> (APPR)	MOW-L00	1	SOUTH	MOW-042	CM	MOW-L02	0	45	0	45	0	11/3/16
1 JHRA water leak on rail 45+00	LEAKS			LEAKING		TUNNEL LEAK						
<a href="#">2033296</a> (MONITOR)	MOW-R00	2	SOUTH	MOW-013	CM	MOW-T02	0	67	60	67	60	8/5/15
1 JHRA Curve Closure Rail Chipped 067+60E JH 1B	RAIL			CHIPPED / PITTED		LEAD OR CLOSURE RAIL						
<a href="#">2013865</a> (APPR)	MOW-M00	1	NORTH	MOW-044	CM	MOW-R08	0	67	70	67	70	7/21/15
1 JHRA Restraining Rail IJ Bolts Loose 067+70E	TRACK MISCELLANEOUS			LOOSE / SLACK		INSULATED JOINT						
<a href="#">2665961</a> (APPR)	MOW-R00	2	NORTH	MOW-003	CM	MOW-R08	0	68	0	68	0	11/15/16
1 JHRA IJ battered chipped and pitted 68+00	RAIL			BATTERED		INSULATED JOINT						
<b>Number of Records:</b>							7					



Maryland Department of Transportation  
 Maryland Transit Administration  
 Right Of Way Inspectors Report



Site: METRO  
 Workgroup: MTA472  
 START\_CHAIN\_MARKER: 0  
 END\_CHAIN\_MARKER: 333  
 Include History: N

TMEX (TRACK METRO EAST CROSSOVERS) - Workgroup: MTA472

Work Order	Problem	Priority	Position	Reported Defect	Work Type	Component	Quantity	START CHAIN MARKER	CM START OFFSET	END CHAIN MARKER	CM END OFFSET	Report Date
<a href="#">2493058</a> (APPR)	MOW-R00	4	BOTH	MOW-003	CM	MOW-T06	0	67	0	67	0	7/21/16
1 JHRA frog point 1b pitted/battered RAIL				BATTERED		FROG						
<a href="#">2665965</a> (APPR)	MOW-R00	2	G5	MOW-013	CM	MOW-T09	0	67	0	67	0	11/15/16
1 JHRA point in diamond chipped and pitted 67+00				CHIPPED / PITTED		FROG GUARD						
<a href="#">2449051</a> (APPR)	MOW-R00	3	BOTH	MOW-013	CM	MOW-T06	0	68	40	68	40	6/15/16
2 RAJH frog point chipped 3A				CHIPPED / PITTED		FROG						
<a href="#">2449070</a> (APPR)	MOW-R00	4	BOTH	MOW-003	CM	MOW-T06	0	69	0	69	0	6/15/16
2 RAJH frog point battered 1A				BATTERED		FROG						
<a href="#">2043020</a> (MONITOR)	MOW-R00	2	RIGHT	MOW-069	CM	MOW-T01	0	70	0	70	0	8/12/15
2 RAJH RH Stock Rail Side Worn (25 Deg) JH 1A				SIDE WEAR (RAIL)		STOCK RAIL						
<a href="#">2059899</a> (COMP)	MOW-M00	2	BOTH	MOW-016	CM	MOW-T09	0	70	0	70	0	8/26/15
1 JHRA Frog Riser Cracked JH 3B				CRACKED / SPLIT		FROG GUARD						
<a href="#">2493055</a> (APPR)	MOW-R00	3	BOTH	MOW-003	CM	MOW-T06	0	70	6	70	6	7/21/16
1 JHRA JH 3B frog point battered				BATTERED		FROG						
<a href="#">2014923</a> (APPR)	MOW-M00	1	LEFT	MOW-044	CM	MOW-T12	0	70	20	70	30	7/22/15
2 RAJH LH Switch Point Fastener Blocks Loose (4) JH 1A				LOOSE / SLACK		SPACER BLOCK BOLT						
<a href="#">2573519</a> (WAPPR)	MOW-M00	2	WEST	MOW-016	CM	MOW-T06	0	75	0	75	0	9/8/16
1 JHRA blocks missing wing of frog				FROG		FROG						
<a href="#">2573518</a> (APPR)	MOW-M00	1	SOUTH	MOW-044	CM	MOW-R09	0	79	0	79	0	9/8/16
1 JHRA brace plate loose 1B 079				LOOSE / SLACK		RESTRAINING RAIL BRACE						
<b>Number of Records:</b>							10					



Maryland Department of Transportation  
 Maryland Transit Administration  
 Right Of Way Inspectors Report



Site: METRO  
 Workgroup: MTA472  
 START\_CHAIN\_MARKER: 0  
 END\_CHAIN\_MARKER: 333  
 Include History: N

TMW1 (TRACK METRO WEST 1) - Workgroup: MTA472												
Work Order	Problem	Priority	Position	Reported Defect	Work Type	Component	Quantity	START CHAIN MARKER	CM START OFFSET	END CHAIN MARKER	CM END OFFSET	Report Date
<a href="#">2043305</a> (INPRG)	MOW-X00	2	BOTH	MOW-022	CM	MOW-X00	0	13	85	13	85	8/12/15
1 JHRA Two Block Tie Deteriorating (N) 013+85W	TIES			DETERIORATING		TIES						
<a href="#">2043299</a> (INPRG)	MOW-X00	2	BOTH	MOW-022	CM	MOW-X00	0	15	75	15	75	8/12/15
1 JHRA Two Block Tie Deteriorating (N) 015+75W	TIES			DETERIORATING		TIES						
<a href="#">2013812</a> (HOLD)	MOW-G00	2	BOTH	MOW-016	CM	MOW-X08	0	18	60	18	60	7/21/15
1 JHRA Fastener Pad Cracked/Broken (6) 018+60W	GROUT PADS			CRACKED / SPLIT		CONCRETE G10 PAD						
<a href="#">2469642</a> (APPR)	MOW-X00	2	BOTH	MOW-016	CM	MOW-X00	0	18	85	18	85	7/1/16
1 JHRA	TIES			CRACKED / SPLIT		TIES						
<a href="#">2106086</a> (APPR)	MOW-L00	1	BOTH	MOW-004	CM	MOW-B01	0	53	0	59	0	9/30/15
1 JHRA Drain Clogged/Fouled (600') 053W-059W	LEAKS			BLOCKAGE		TUNNEL DRAIN						
<a href="#">2668041</a> (APPR)	MOW-M00	2	BOTH	MOW-065	CM	MOW-M02	0	68	0	68	0	11/16/16
1 JHRA lites in tunnel 068	TRACK MISCELLANEOUS			SAFETY HAZARD		ETS BOX / LIGHT						
<a href="#">2080337</a> (APPR)	MOW-C00	3	THIRD RAIL	MOW-014	CM	MOW-C05	0	68	70	68	90	9/10/15
1 JHRA 3rd Rail Severely Corroded 068+70 - 068+90	CONTACT RAIL			CORRODED		THIRD RAIL						
<a href="#">2618075</a> (APPR)	MOW-B00	1	BOTH	MOW-042	CM	MOW-L02	0	68	80	68	80	10/12/16
1 JHRA water leak 068+80	TUNNEL			LEAKING		TUNNEL LEAK						
<a href="#">2030720</a> (APPR)	MOW-R00	1	NORTH	MOW-003	CM	MOW-R08	0	69	35	69	35	8/3/15
1 JHRA IJ Battered BH 1B 069+35W	RAIL			BATTERED		INSULATED JOINT						
<a href="#">2468951</a> (APPR)	MOW-C00	2	THIRD RAIL	MOW-014	CM	MOW-C05	0	73	0	73	0	7/1/16
1 JHRA Third rail corrosion	CONTACT RAIL			CORRODED		THIRD RAIL						



Maryland Department of Transportation  
 Maryland Transit Administration  
 Right Of Way Inspectors Report



Site: METRO  
 Workgroup: MTA472  
 START\_CHAIN\_MARKER: 0  
 END\_CHAIN\_MARKER: 333  
 Include History: N

TMW1 (TRACK METRO WEST 1) - Workgroup: MTA472

Work Order	Problem	Priority	Position	Reported Defect	Work Type	Component	Quantity	START CHAIN MARKER	CM START OFFSET	END CHAIN MARKER	CM END OFFSET	Report Date
<a href="#">2106102</a> (APPR)	MOW-M00	1	THIRD RAIL	MOW-017	CM	MOW-C03	0	107	15	107	15	9/30/15
1 JHRA Coverboard Bracket Broken 107+15	TRACK MISCELLANEOUS			DAMAGED HARDWARE		COVER BOARD BRACKET						
<a href="#">2014921</a> (APPR)	MOW-M00	3	THIRD RAIL	MOW-010	CM	MOW-C01	0	140	70	140	90	7/22/15
1 JHRA Insulator Cup Burnt (4) 140+70 -140+90	TRACK MISCELLANEOUS			BURNT (LUMBER)		INSULATOR						
<a href="#">2015378</a> (APPR)	MOW-R00	1	SOUTH	MOW-014	CM	MOW-R01	0	141	0	141	0	7/22/15
1 JHRA Rail Web/Base Deteriorated (S) 141+00	RAIL			CORRODED		RUNNING RAIL						
<a href="#">2015388</a> (APPR)	MOW-R00	1	THIRD RAIL	MOW-014	CM	MOW-C05	0	141	0	141	0	7/22/15
1 JHRA 3rd Rail Corroded 141+00	RAIL			CORRODED		THIRD RAIL						
<a href="#">2106112</a> (APPR)	MOW-C00	1	THIRD RAIL	MOW-061	CM	MOW-C05	0	148	0	148	0	9/30/15
1 JHRA 3rd Rail Unseated/Out of Insulator Cups 148+00	CONTACT RAIL			POOR SUPPORT		THIRD RAIL						
<a href="#">2106126</a> (APPR)	MOW-R00	2	NORTH	MOW-014	CM	MOW-R00	0	154	0	165	0	9/30/15
1 JHRA Rail Web/Base Corroded (N) 154-165	RAIL			CORRODED		RAIL						
<a href="#">2051473</a> (MONITOR)	MOW-C00	2	THIRD RAIL	MOW-014	CM	MOW-C05	0	158	0	166	0	8/19/15
1 JHRA 3rd Rail Deteriorated 158-166+00	CONTACT RAIL			CORRODED		THIRD RAIL						
<a href="#">2208896</a> (APPR)	MOW-X00	2	BOTH	MOW-016	CM	MOW-X17	0	158	40	158	40	12/10/15
1 JHRA Two Block Tie Broken 158+40W	TIES			CRACKED / SPLIT		CONCRETE TIE RAIL SEAT PAD						
<a href="#">2208897</a> (APPR)	MOW-M00	1	SOUTH	MOW-044	CM	MOW-M01	0	160	0	160	0	12/10/15
1 JHRA Chain Marker Sign 160NW Loose/Hanging	TRACK MISCELLANEOUS			LOOSE / SLACK		CHAIN MARKER						
<a href="#">2212343</a> (APPR)	MOW-F00	3	BOTH	MOW-022	CM	MOW-F05	0	160	0	170	0	12/12/15
1 JHRA Pandrol Clips Broken/Deteriorating 160W-170W	FASTENERS			DETERIORATING		CLIP						



Maryland Department of Transportation  
 Maryland Transportation Administration  
 Right Of Way Inspectors Report



Site: METRO  
 Workgroup: MTA472  
 START\_CHAIN\_MARKER: 0  
 END\_CHAIN\_MARKER: 333  
 Include History: N

TMW1 (TRACK METRO WEST 1) - Workgroup: MTA472

Work Order	Problem	Priority	Position	Reported Defect	Work Type	Component	Quantity	START CHAIN MARKER	CM START OFFSET	END CHAIN MARKER	CM END OFFSET	Report Date
<a href="#">2106138</a> (APPR) 1 JHRA Two Block Tie Broken 161+25	MOW-X00 TIES	1	BOTH	MOW-016 CRACKED / SPLIT	CM	MOW-X00 TIES	0	161	25	161	25	9/30/15
<a href="#">2015101</a> (APPR) 1 JHRA Coverboard Brackets Missing 194+90 & 195+25	MOW-M00 TRACK MISCELLANEOUS	1	THIRD RAIL	MOW-046 MISSING	CM	MOW-C03 COVER BOARD BRACKET	0	194	90	195	25	7/22/15
<a href="#">2043013</a> (MONITOR) 1 JHRA Rail Corrugation (N) 202 - 214+00	MOW-R00 RAIL	2	NORTH	MOW-015 CORRUGATED	CM	MOW-R01 RUNNING RAIL	0	202	0	214	0	8/12/15
<a href="#">2013741</a> (APPR) 1 JHRA Shim Plate Loose 237+50	MOW-P00 PLATES	1	BOTH	MOW-044 LOOSE / SLACK	CM	MOW-P00 PLATES	0	237	50	237	50	7/21/15
<a href="#">2017722</a> (APPR) 1 JHRA LB Foster Plates Deteriorating 238 - 268	MOW-P00 PLATES	2	BOTH	MOW-018 DEFECTIVE - NO LONGER FUNCTIONING	CM	MOW-P00 PLATES	0	238	0	268	0	7/24/15
<a href="#">2030745</a> (APPR) 1 JHRA Shim Plate Missing 248+10W	MOW-P00 PLATES	1	SOUTH	MOW-046 MISSING	CM	MOW-P00 PLATES	0	248	10	248	10	8/3/15
<a href="#">2549815</a> (APPR) 1 JHRA coverboard bent 262-272	MOW-M00 TRACK MISCELLANEOUS	3	SOUTH	MOW-044 LOOSE / SLACK	PM	MOW-C02 COVERBOARD	0	262	0	272	0	8/23/16
<a href="#">2014064</a> (APPR) 1 JHRA Coverboard Brackets Bent 267+50 - 272	MOW-M00 TRACK MISCELLANEOUS	1	THIRD RAIL	MOW-017 DAMAGED HARDWARE	CM	MOW-C03 COVER BOARD BRACKET	0	267	50	272	0	7/21/15
<a href="#">2030747</a> (MONITOR) 1 JHRA Rail Side Worn (22 Deg) 274+00	MOW-R00 RAIL	2	SOUTH	MOW-046 MISSING	CM	MOW-R01 RUNNING RAIL	0	274	0	274	0	8/3/15
<b>Number of Records:</b>		29										





Maryland Department of Transportation  
 Maryland Transit Administration  
 Right Of Way Inspectors Report



Site: METRO  
 Workgroup: MTA472  
 START\_CHAIN\_MARKER: 0  
 END\_CHAIN\_MARKER: 333  
 Include History: N

TMWX (TRACK METRO WEST CROSSOVERS) - Workgroup: MTA472

Work Order	Problem	Priority	Position	Reported Defect	Work Type	Component	Quantity	START CHAIN MARKER	CM START OFFSET	END CHAIN MARKER	CM END OFFSET	Report Date
<a href="#">2053299</a> (MONITOR)	MOW-R00	2	RIGHT	MOW-013	CM	MOW-T03	0	4	73	4	73	8/20/15
1 JHRA RH Switch Point Chipped / Pitted CC 3B	RAIL			CHIPPED / PITTED		SWITCH POINT						
<a href="#">2053301</a> (MONITOR)	MOW-R00	2	LEFT	MOW-069	CM	MOW-T03	0	4	73	4	73	8/20/15
1 JHRA LH Switch Point Chipped / Pitted CC 3B	RAIL			SIDE WEAR (RAIL)		SWITCH POINT						
<a href="#">2017699</a> (APPR)	MOW-M00	1	THIRD RAIL	MOW-046	CM	MOW-C03	0	7	50	7	50	7/24/15
1 JHRA 3rd Rail Side Approach Hardware Missing CC 1B 007+50	TRACK MISCELLANEOUS			MISSING		COVER BOARD BRACKET						
<a href="#">2573520</a> (APPR)	MOW-M00	2	BOTH	MOW-018	CM	MOW-M02	0	8	0	8	0	9/9/16
1 JHRA flights out charles interlocking 008	TRACK MISCELLANEOUS			DEFECTIVE - NO LONGER FUNCTIONING		ETS BOX / LIGHT						
<a href="#">2571333</a> (APPR)	MOW-M00	3	BOTH	MOW-080	CM	MOW-B01	0	10	0	14	0	9/7/16
2 RAJH trash 10-14	TRACK MISCELLANEOUS			TRASH AND DEBRIS		TUNNEL DRAIN						
<a href="#">2493075</a> (APPR)	MOW-Q00	2	BOTH	MOW-080	CM	MOW-B01	0	66	0	70	0	7/21/16
2 RAJH trash build up 070-066	RIGHT OF WAY			TRASH AND DEBRIS		TUNNEL DRAIN						
<a href="#">2030698</a> (MONITOR)	MOW-R00	2	SOUTH		CM	MOW-R08	0	66	80	56	80	8/3/15
1 JHRA IJ Battered BH-3B 066+80W	RAIL					INSULATED JOINT						
<a href="#">2014043</a> (HOLD)	MOW-X00	2	BOTH	MOW-062	CM	MOW-X00	0	67	70	68	50	7/21/15
2 RAJH Ties Pumping BH 068+50 - 067+70W	TIES			PUMPING		TIES						
<a href="#">2449048</a> (APPR)	MOW-M00	3	THIRD RAIL	MOW-017	CM	MOW-C03	0	68	70	68	70	6/15/16
2 RAJH switch point battered	TRACK MISCELLANEOUS			DAMAGED HARDWARE		COVER BOARD BRACKET						
<a href="#">2013791</a> (HOLD)	MOW-M00	2	SOUTH	MOW-046	CM	MOW-M09	0	69	0	69	0	7/21/15
2 RAJH Crosswalk Missing BH 3A 069+00W	TRACK MISCELLANEOUS			MISSING		SAFETY WALK						





Maryland Department of Transportation  
 Maryland Transportation Administration  
 Right Of Way Inspectors Report



Site: METRO

Workgroup: MTA472

START\_CHAIN\_MARKER: 0

END\_CHAIN\_MARKER: 333

Include History: N

TMWX (TRACK METRO WEST CROSSOVERS) - Workgroup: MTA472

Work Order	Problem	Priority	Position	Reported Defect	Work Type	Component	Quantity	START CHAIN MARKER	CM START OFFSET	END CHAIN MARKER	CM END OFFSET	Report Date
<a href="#">2030709</a> (MONITOR)	MOW-R00 RAIL	2	RIGHT	MOW-013 CHIPPED / PITTED	CM	MOW-T03 SWITCH POINT	0	69	30	69	30	8/3/15
<a href="#">2549819</a> (APPR)	MOW-R00 RAIL	2	BOTH	MOW-003 BATTERED	PM	MOW-T06 FROG	0	230	0	230	0	8/23/16

Number of Records: 12



Maryland Department of Transportation  
 Maryland Transit Administration  
 Right Of Way Inspectors Report



Site: METRO  
 Workgroup: MTA472  
 START\_CHAIN\_MARKER: 0  
 END\_CHAIN\_MARKER: 333  
 Include History: N

Inspection Completed?  Yes  No If No Why? \_\_\_\_\_

Item	Exception Chain Marker No.		Track No.	Position N/S	Switch No.	Codes		Defect	Priority	Alias
	From	To				Comp.				
1	069+50		1	N	JH3B	SOS		PO9	3	TMEY
2	068+40		1	Diamond	JH Diamond	SOS		PO9	5	TMEY
3										
4										
5										
6										
7										
8										

Notes: 1. JH3B frog point cracked. 2. West end point on diamond cracked

Track Walker: Joe Brockmeyer  
Print  
 Watchman: John Williams  
Print  
 Track Inspection  
 Supervisor: [Signature]  
Print

Sign: [Signature]  
 Date: 11-29-16  
 Sign: [Signature]  
 Date: 11-29-16  
 Sign: [Signature]  
 Date: 11-29-16  
 Sign: [Signature]  
 Date: 11-29-16