

Work Order Tracking (Tr)

Find Work Order



Select Action



- List
- Work Order**
- Plans
- Actuals
- Activities
- Measurements
- Axle Configuration
- Related Records
- Safety Plan
- Log

Work Order: 2563772

AREA #1(OM-OC) MOW MONTHLY MAINLINE SWITCH IN

Classification: MTA \ METRO

Classification Description: MTA - METRO

Asset:

Alias:

Location: OLDCOURTF/ Old Court Maintenance Facility

Work Location:

Work Type: PM

Status: WSCH

Status Date: 09/01/16 04:39:29 AM

Reported By: MTACRON

Phone:

Reported Date: 09/01/16 04:39:28 AM

On Behalf Of:

Consist:

Asset Details

Year:

Manufacturer:

Model:

Serial #:

Type:

Status:

Asset Condition:

Address Information

Service Address: 1206

6301 Wabash Ave Reisterstown Plaza Baltimore

Formatted Address:

Street Address: 6301 Wabash Ave

Multiple Assets.Locations and Cls Filter

0 - 0 of 0

# MOW MONTHLY MANILINE SWITCH INSPECTION AREA #1 OM-OC

Track	Switch I.D.	Location	Inspection Date	The Condition	Switch Pnts L/R	Closure S/C	Frog	Stock Rail	Plates	Lags/Clips	Standard Joints	Insulated Joints	Welds	Ballast
OM TO RA	CM#	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S
1	OM-5A	704+10	9-1-16	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
2	OM-7A	704+10		Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
2	OM-3A	688+30		Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
2	OM-1A	682+36		Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
1	OM-1B	682+36		Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
1	OM-3B	688+30		Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
1	OC-5A	525+65		Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
1	OC-1B	525+75		Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
1	OC-3B	632+26		Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
2	OC-3A	632+26		Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
2	OC-1A	525+75	9-1-16	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y

COMMENTS All Ties are deteriorated in switches At  
 Old Coust Interlocking  
 Loose Shoulder Bolts IA Tracky

WORK ORDER #

Inspectors *[Signature]* Date 9-1-16 Supervisor *[Signature]*

Work Order Tracking (Tr)

Find Work Order

Select Action



- List
- Work Order**
- Plans
- Actuals
- Activities
- Measurements
- Axle Configuration
- Related Records
- Safety Plan
- Log

Work Order: 2563776

AREA #2(MM-RP) MOW MONTHLY MAINLINE SWITCH IN

Classification: MTA \ METRO

Classification Description: MTA - METRO

Asset:

Alias:

Location: OLDCOURTF/ Old Court Maintenance Facility

Work Location:

Work Type: PM

Status: WSCH

Status Date: 09/01/16 04:39:31 AM

Reported By: MTACRON

Phone:

Reported Date: 09/01/16 04:39:30 AM

On Behalf Of:

Consist:

Asset Details

Year:

Manufacturer:

Model:

Serial #:

Type:

Status:

Asset Condition:

Address Information

Service Address: 1206 6301 Wabash Ave Reisterstown Plaza Baltimore

Formatted Address:

Street Address: 6301 Wabash Ave

Multiple Assets.Locations and Cls Filter

0 - 0 of 0

# MOW MONTHLY MANILINE SWITCH INSPECTION AREA #2 MM-RP

Track	Switch I.D.	Location	Inspection Date	Tie Condition	Switch Pnts L/R	Closure S/C	Frog	Stock Rail	Plates	Lags/Clips	Standard Joints	Insulated Joints	Welds	Ballast
OM TO RA	CM#			R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S
1	MM-3	439+35	9-4-16	R	S	S	Y	S	S	R	S	S	S	S
2	MM-1A	439+35	9-4-16	Y	S	S	Y	Y	S	S	Y	S	S	S
1	RP-3B	389+35	9-4-16	S	S	S	S	S	S	S	S	S	S	S
1	RP-1B	391+05	9-4-16	S	S	S	S	S	S	S	S	S	S	S
2	RP-3A	391+05	9-4-16	S	S	S	S	S	S	S	S	S	S	S
2	RP-1A	389+35	9-4-16	S	S	S	S	S	S	S	S	S	S	S
2	RP-17	376+60	9-4-16	R	S	S	Y	S	Y	S	S	S	S	N/A
1	RP-21	376+80	9-4-16	R	Y	S	S	S	Y	S	S	Y	S	N/A
1	RP-19B	376+60	9-4-16	R	S	S	Y	S	S	Y	Y	Y	S	N/A

**COMMENTS**

MM 1-A Risee checked out north rail broken nails

**WORK ORDER #**

Inspectors Arash Chaudhry

Date 9/4/16

Supervisor 

Work Order Tracking (Tr)

Find Work Order



Select Action



- List
- Work Order**
- Plans
- Actuals
- Activities
- Measurements
- Axle Configuration
- Related Records
- Safety Plan
- Log

Work Order: 2563780

AREA #3(RA-PO) MOW MONTHLY MAINLINE SWITCH INS

Classification: MTA \ METRO

Classification Description: MTA - METRO

Asset:

Alias:

Location: OLDCOURTF/ Old Court Maintenance Facility

Work Location:

Work Type: PM

Status: WSCH

Status Date: 09/01/16 04:39:33 AM

Reported By: MTACRON

Phone:

Reported Date: 09/01/16 04:39:33 AM

On Behalf Of:

Consist:

Asset Details

Year:

Manufacturer:

Model:

Serial #:

Type:

Status:

Asset Condition:

Address Information

Service Address: 1206

6301 Wabash Ave Reisterstown Plaza Baltimore

Formatted Address:

Street Address: 6301 Wabash Ave

Multiple Assets.Locations and Cls Filter

0 - 0 of 0

# MOW MONTHLY MANILINE SWITCH INSPECTION AREA #3 RA-PO

Track	Switch I.D.	Location	Inspection Date	Tie Condition	Switch Pnts L/R	Closure S/C	Frog	Stock Rail	Plates	Lags/Clips	Standard Joints	Insulated Joints	Welds	Ballast
RA TO OM	CM#	CM#	Date	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S
1	RA-3B	351+25	9-5-16	S	S	S	S	S	S	S	S	S	S	S
1	RA-1B	344+15	9-5-16	S	Y	S	S	S	S	S	S	S	S	S
1	RA-5A	348+55	9-5-16	S	S	S	S	S	S	S	S	S	S	Y
1	RA-7B	349+10	9-5-16	S	S	S	S	S	S	S	S	S	S	Y
2	RA-9A	348+10	9-5-16	S	S	S	Y	S	S	S	S	S	S	Y
2	RA-3A	344+15	9-5-16	S	S	S	S	S	S	S	S	S	S	S
2	RA-1A	341+25	9-5-16	S	S	S	S	S	S	S	S	S	S	S
1	PO-3B	229+10	9-5-16	S	S	S	S	S	S	S	S	S	S	S
1	PO-1B	230+80	9-5-16	S	S	S	S	S	S	S	S	S	S	S
2	PO-7B	332+46	9-5-16	S	S	S	S	S	S	S	S	S	S	S
2	PO-3A	230+80	9-5-16	S	S	S	S	S	S	S	S	S	S	S
2	PO-1A	229+10	9-5-16	S	S	S	S	S	S	S	S	S	S	S
2	PO-5B	227+40	9-5-16	S	S	S	S	S	S	S	S	S	S	S

**COMMENTS:**

1-B north switch point chipped and south guard rail missing bolt  
 3-A switch pump out  
 3-B north guard rail missing bolt  
 2-A north switch point needs a little grinding

WORK ORDER #

Inspectors

*Paul J. Chandler*

Date

*9/5/16*

Supervisor

