

Work Order Tracking (Tr)

Find Work Order

Select Action



- List
- Work Order**
- Plans
- Actuals
- Activities
- Measurements
- Axle Configuration
- Related Records
- Safety Plan
- Log

Work Order: 2645307

AREA #1(OM-OC) MOW MONTHLY MAINLINE SWITCH IN:

Classification: MTA \ METRO

Classification Description: MTA - METRO

Asset:

Alias:

Location: OLDCOURTF/ Old Court Maintenance Facility

Work Location:

Work Type: PM

Status: WSCH

Status Date: 11/01/16 04:36:49 AM

Reported By: MTACRON

Phone:

Reported Date: 11/01/16 04:36:49 AM

On Behalf Of:

Consist:

Asset Details

Year:

Manufacturer:

Model:

Serial #:

Type:

Status:

Asset Condition:

Address Information

Service Address: 1206

6301 Wabash Ave Reisterstown Plaza Baltimore

Formatted Address:

Street Address: 6301 Wabash Ave

Multiple Assets.Locations and Cls Filter

0 - 0 of 0


MOW MONTHLY MANILINE SWITCH INSPECTION AREA #1 OM-OC

Track	Switch I.D.	Location	Inspection Date	Tie Condition	Switch Pnts L/R	Closure S/C	Frog	Stock Rail	Plates	Lags/Clips	Standard Joints	Insulated Joints	Welds	Ballast
OM TO RA	CM#			R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S
1	OM-5A	704+10	11/14/16	R	S	S	S	S	S	Y	S	S	S	S
2	OM-7A	704+10	11/14/16	R	S	S	S	S	S	Y	S	S	S	Y
2	OM-3A	688+30	11/14/16	S	S	S	Y	S	S	S	S	S	S	S
2	OM-1A	682+36	11/14/16	S	S	S	Y	S	S	S	S	S	S	S
1	OM-1B	682+36	11/16/16	S	Y	S	S	S	S	S	S	S	S	S
1	OM-3B	688+30	11/16/16	S	Y	S	Y	S	S	S	S	S	S	S
1	OC-5A	525+65	11/16/16	S	S	S	S	S	S	S	S	S	S	S
1	OC-1B	525+75	11/16/16	R	Y	S	S	S	S	Y	S	S	S	S
1	OC-3B	632+26	11/16/16	R	Y	S	S	S	S	Y	S	S	S	S
2	OC-3A	632+26	11/16/16	Y	S	S	S	S	S	S	S	S	S	Y
2	OC-1A	525+75	11/16/16	R	S	S	Y	Y	S	Y	S	S	S	Y

COMMENTS

1B out of surface road lateral movement
 OM 1A road 3A is battered
 OM 1B south switch point worn
 OM 3B frog power chipped and p-tied
 OM 3B south switch point worn

WORK ORDER # 2645307

Inspectors Chadler / Johnson Date 11/16/16 Supervisor 

Work Order Tracking (Tr)

Find Work Order



Select Action



- List
- Work Order**
- Plans
- Actuals
- Activities
- Measurements
- Axle Configuration
- Related Records
- Safety Plan
- Log

Work Order: 2645311

AREA #2(MM-RP) MOW MONTHLY MAINLINE SWITCH IN

Classification: MTA \ METRO

Classification Description: MTA - METRO

Asset:

Alias:

Location: OLDCOURTFA Old Court Maintenance Facility

Work Location:

Work Type: PM

Status: WSCH

Status Date: 11/01/16 04:36:52 AM

Reported By: MTACRON

Phone:

Reported Date: 11/01/16 04:36:51 AM

On Behalf Of:

Consist:

Asset Details

Year:

Manufacturer:

Model:

Serial #:

Type:

Status:

Asset Condition:

Address Information

Service Address: 1206 6301 Wabash Ave Reisterstown Plaza Baltimore

Formatted Address:

Street Address: 6301 Wabash Ave

Multiple Assets.Locations and Cls Filter

0 - 0 of 0

MOW MONTHLY MANILINE SWITCH INSPECTION AREA #2 MM-RP

Track	Switch I.D.	Location	Inspection Date	Tie Condition	Switch Pnts L/R	Closure S/C	Frog	Stock Rail	Plates	Lags/Clips	Standard Joints	Insulated Joints	Welds	Ballast
OM TO RA	CM#			R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S
1	MM-3	439+35	11-14-16	R	S	S	Y	S	S	Y	S	S	S	S
2	MM-1A	439+35	11-14-16	S	S	Y	Y	S	S	S	S	S	S	S
1	RP-3B	389+35	11-14-16	S	S	S	S	S	S	S	S	S	S	S
1	RP-1B	391+05	11-14-16	S	S	S	S	S	S	S	S	S	S	S
2	RP-3A	391+05	11-14-16	S	S	S	S	S	S	S	S	S	S	S
2	RP-1A	389+35	11-14-16	S	S	S	S	S	S	S	S	S	S	S
2	RP-17	376+60	11-14-16	S	S	S	S	S	S	S	S	S	S	N/A
1	RP-21	376+80	11-14-16	S	S	S	Y	Y	S	S	S	S	S	N/A
1	RP-19B	376+60	11-14-16	S	S	S	Y	Y	S	S	S	S	S	N/A

COMMENTS

WORK ORDER # 2645311

Inspectors *Alvin J. ...*
Andria Chandler

Date 11-14-16

Supervisor *[Signature]*

Work Order Tracking (Tr)

Find Work Order

Select Action



- List
- Work Order**
- Plans
- Actuals
- Activities
- Measurements
- Axle Configuration
- Related Records
- Safety Plan
- Log

Work Order: 2645315

AREA #3(RA-PO) MOW MONTHLY MAINLINE SWITCH INS

Classification: MTA \ METRO

Classification Description: MTA - METRO

Asset:

Alias:

Location: OLDCOURTF/ Old Court Maintenance Facility

Work Locatlon:

Work Type: PM

Status: WSCH

Status Date: 11/01/16 04:36:54 AM

Reported By: MTACRON

Phone:

Reported Date: 11/01/16 04:36:53 AM

On Behalf Of:

Consist:

Asset Details

Year:

Manufacturer:

Model:

Serial #:

Type:

Status:

Asset Condition:

Address Information

Service Address: 1206 6301 Wabash Ave Reisterstown Plaza Baltimore

Formatted Address:

Street Address: 6301 Wabash Ave

Multiple Assets.Locatlons and Cls Filter

0 - 0 of 0

MOW MONTHLY MANILINE SWITCH INSPECTION AREA #3 RA-PO

Track	Switch I.D.	Location	Inspection Date	Tie Condition	Switch Pnts L/R	Closure S/C	Frog	Stock Rail	Plates	Lags/Clips	Standard Joints	Insulated Joints	Welds	Ballast
RA TO OM	CM#	Date	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S
1	RA-3B	351+25	11-14-16	S	S	S	S	S	S	S	S	S	S	S
1	RA-1B	344+15	11-14-16	S	S	S	S	S	S	S	S	S	S	S
1	RA-5A	348+55	11-14-16	S	S	S	S	S	S	S	S	S	S	S
1	RA-7B	349+10	11-14-16	S	S	S	S	S	S	S	S	S	S	S
2	RA-9A	348+10	11-14-16	S	S	S	S	S	S	S	S	S	S	S
2	RA-3A	344+15	11-14-16	S	S	S	S	S	S	S	S	S	S	S
2	RA-1A	341+25	11-14-16	S	S	S	S	S	S	S	S	S	S	S
1	PO-3B	229+10	11-14-16	S	S	S	S	S	S	S	S	S	S	S
1	PO-1B	230+80	11-14-16	S	S	S	S	S	S	S	S	S	S	S
2	PO-7B	332+46	11-14-16	S	S	S	S	S	S	S	S	S	S	S
2	PO-3A	230+80	11-14-16	S	S	S	S	S	S	S	S	S	S	S
2	PO-1A	229+10	11-14-16	S	S	S	S	S	S	S	S	S	S	S
2	PO-5B	227+40	11-14-16	S	S	S	S	S	S	S	S	S	S	S
<p>COMMENTS: RA-9A battery chipped RA-1A switch rods rubbing tie PO-1B - Needs grinding PO-7B - needs grinding PO-3A needs grinding PO-1A needs grinding</p>														

WORK ORDER # 2645315

Inspectors *Joe Barbary*

Date 11-14-16

Supervisor 