

Work Order Tracking (Tr)

Bull

Find Work Order

Select Action

List

Work Order

Plans

Actuals

Activities

Measurements

Axle Configuration

Related Records

Safety Plan

Log

Work Order: 2432908

AREA #1(OM-OC) MOW MONTHLY MAINLINE SWITCH IN

Classification: MTA \ METRO

Classification Description: MTA - METRO

Asset: >>

Alias:

Location: OLDCOURTF/ >> Old Court Maintenance Facility

Work Location: >>

Work Type: PM

Status: WSCH

Status Date: 06/01/16 04:39:16 AM

Reported By: MTACRON >>

Phone:

Reported Date: 06/01/16 04:39:15 AM

On Behalf Of: >>

Consist: >>

Asset Details

Year:

Manufacturer: >>

Model: >>

Serial #:

Type: >>

Status:

Asset Condition:

Address Information

Service Address: 1206 >> 6301 Wabash Ave Reisterstown Plaza Baltimore

City: BALTIMOF

Formatted Address:

State/Province: MD

MOW MONTHLY MANILINE SWITCH INSPECTION AREA #1 OM-OC

Track	Switch I.D.	Location	Inspection Date	Tie Condition	Switch Pnts L/R	Closure S/C	Frog	Stock Rail	Plates	Lags/Clips	Standard Joints	Insulated Joints	Welds	Ballast
OM TO RA	CM#			R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S
1	OM-5A	704+10	6-12-16	Y	Y	Y	S	Y	S	S	S	S	S	S
2	OM-7A	704+10	6-12-16	Y	Y	Y	S	S	S	S	S	S	S	S
2	OM-3A	688+30	6-12-16	S	S	S	Y	S	S	S	S	S	S	S
2	OM-1A	682+36	6-12-16	S	S	S	S	S	S	S	S	S	S	S
1	OM-1B	682+36	6-12-16	S	Y	S	S	Y	S	S	S	S	S	S
1	OM-3B	688+30	6-12-16	S	Y	S	Y	S	S	S	S	S	S	S
1	OC-5A	525+65	6-12-16	S	S	S	S	S	S	S	S	S	S	S
1	OC-1B	525+75	6-12-16	R	Y	Y	S	S	S	Y	S	S	S	S
1	OC-3B	632+26	6-12-16	R	Y	Y	S	S	S	Y	S	S	S	S
2	OC-3A	632+26	6-12-16	S	S	S	S	S	S	S	S	S	S	S
2	OC-1A	525+75	6-12-16	R	Y	Y	Y	Y	Y	Y	S	S	S	S

COMMENTS

WORK ORDER #

Inspectors A. JEFFERSON J. WILLIAMS Date 6-12-16 Supervisor 

Work Order Tracking (Tr)

Bull

Find Work Order

Select Action

- List
- Work Order**
- Plans
- Actuals
- Activities
- Measurements
- Axle Configuration
- Related Records
- Safety Plan
- Log

Work Order: 2432912

AREA #2(MM-RP) MOW MONTHLY MAINLINE SWITCH IN: 

Classification: MTA \ METRO

Classification Description: MTA - METRO

Asset:  

Alias:

Location: OLDCOURTF/ 

Work Location:

Work Type: PM

Status: WSCH

Status Date: 06/01/16 04:39:1


Reported By: MTACRON

Phone:

Reported Date: 06/01/16 04:39:1

On Behalf Of:

Consist:



Asset Details

Year:

Manufacturer:  

Model: 

Serial #:

Type: 

Status:

Asset Condition:

Address Information

Service Address: 1206

 6301 Wabash Ave Reisterstown Plaza Baltimore 

City: BALTIMOF

Formatted Address:

State/Province: MD

MOW MONTHLY MANILINE SWITCH INSPECTION AREA #2 MM-RP

Track	Switch I.D.	Location	Inspection Date	Tie Condition	Switch Pnts L/R	Closure S/C	Frog	Stock Rail	Plates	Lags/Clips	Standard Joints	Insulated Joints	Welds	Ballast
OM TO RA	CM#			R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S
1	MM-3	439+35	6-5-16	R ✓	S	S	Y	S	S	R	S	S	S	S
2	MM-1A	439+35	6-5-14	Y	S	S	Y	S	S	S	Y	S	S	S
1	RP-3B	389+35	6-5-16	Y	Y	S	Y	Y	S	R	Y	S	S	S
1	RP-1B	391+05	6-5-16	R	Y	Y	R	Y	S	R	Y	Y	S	S
2	RP-3A	391+05	6-5-16	R	Y	Y	S	Y	S	R	Y	Y	S	S
2	RP-1A	389+35	6-5-16	R	Y	Y	R	Y	S	R	S	S	S	S
2	RP-17	376+60	6-5-16	R	S	S	Y	S	S	S	S	S	S	N/A
1	RP-21	376+80	6-5-16	R	S	S	R	S	S	S	S	Y	S	N/A
1	RP-19B	376+60	6-5-16	R	S	S	Y	S	S	S	Y	S	S	M/A

COMMENTS RP 3A on the turn out rail the ties are spike killed and loose lags
 RP 1-A on the turn out rails and straight closure rail the lags are loose and the ties is spike killed
 RP 17 - Frog point is battered and broken concrete pads
 RP - 19B, 21 broken concrete pads (2) in ~~at~~ now under closure rail and west end of frog wing

WORK ORDER #

Inspectors Chandler / Johnson Date 6-5-16 Supervisor 

Work Order Tracking (Tr)

Bull

Find Work Order



Select Action



- List
- Work Order**
- Plans
- Actuals
- Activities
- Measurements
- Axle Configuration
- Related Records
- Safety Plan
- Log

Work Order: 2432916

AREA #3(RA-PO) MOW MONTHLY MAINLINE SWITCH INS

Classification: MTA \ METRO



Classification Description: MTA - METRO

Asset: >>



Alias:

Location: OLDCOURTF/ >> Old Court Maintenance Facility



Work Location: >>



Work Type: PM

Status: WSCH

Status Date: 06/01/16 04:39:20 AM

Reported By: MTACRON



Phone:

Reported Date: 06/01/16 04:39:20 AM



On Behalf Of:



Consist: >>



Asset Details

Year:

Manufacturer: >>



Model: >>

Serial #: >>

Type: >>

Status:

Asset Condition:

Address Information

Service Address: 1206 >> 6301 Wabash Ave Reisterstown Plaza Baltimore



City: BALTIMOF

Formatted Address:

State/Province: MD

MOW MONTHLY MANILINE SWITCH INSPECTION AREA #3 RA-PO

Track	Switch I.D.	Location	Inspection Date	Tie Condition	Switch Pnts L/R	Closure S/C	Frog	Stock Rail	Plates	Lags/Clips	Standard Joints	Insulated Joints	Welds	Ballast
RA TO OM	CM#	Date	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S
1	RA-3B	351+25	06-08-16	Y	Y	Y	S	Y	S	Y	S	S	S	S
1	RA-1B	344+15	06-08-16	R	S	S	Y	S	S	Y	S	S	S	S
1	RA-5A	348+55	06-08-16	S	S	S	S	S	S	S	S	S	S	Y
1	RA-7B	349+10	06-08-16	S	S	S	S	S	S	S	S	S	S	Y
2	RA-9A	348+10	06-08-16	S	S	S	Y	S	S	S	S	S	S	S
2	RA-3A	344+15	06-08-16	Y	Y	R	S	Y	S	Y	Y	S	S	S
2	RA-1A	341+25	06-08-16	Y	Y	R	Y	R	S	Y	S	S	S	S
1	PO-3B	229+10	06-08-16	S	Y	Y	S	R	S	R	S	Y	S	S
1	PO-1B	230+80	06-08-16	S	Y	Y	S	R	S	Y	S	Y	S	S
2	PO-7B	332+46	06-08-16	Y	Y	S	S	Y	Y	Y	Y	Y	S	S
2	PO-3A	230+80	06-08-16	S	Y	R	S	R	Y	Y	Y	S	S	S
2	PO-1A	229+10	06-08-16	S	Y	Y	Y	Y	S	S	Y	S	S	S
2	PO-5B	227+40	06-08-16	S	R	Y	S	R	Y	Y	Y	S	S	S

COMMENTS:

WORK ORDER #

[Signature]

Inspectors

Date 6/8/2016

Supervisor

[Signature]