

Work Order Tracking (Tr)

Bull

Find Work Order



Select Action



List

Work Order

Plans

Actuals

Activities

Measurements

Axle Configuration

Related Records

Safety Plan

Log

Work Order: 2510273

AREA #1(OM-OC) MOW MONTHLY MAINLINE SWITCH IN

Classification: MTA \ METRO



Classification Description: MTA - METRO

Asset:



Alias:

Location: OLDCOURTF/ >> Old Court Maintenance Facility



Work Location:



* Work Type: PM



Status: WSCH

Status Date: 08/02/16 04:14:06 AM

Reported By: MTACRON



Phone:

Reported Date: 08/02/16 04:14:05 AM



On Behalf Of:



Consist:



Asset Details

Year:

Manufacturer:



Model:



Serial #:

Type:



Status:

Asset Condition:

Address Information

Service Address: 1206

>> 6301 Wabash Ave Reisterstown Plaza Baltimore



City: BALTIMOF

Formatted Address:

State/Province: MD

MOW MONTHLY MANILINE SWITCH INSPECTION AREA #1 OM-OC

Track	Switch I.D.	Location	Inspection Date	Tie Condition	Switch Pnts L/R	Closure S/C	Frog	Stock Rail	Plates	Lags/Clips	Standard Joints	Insulated Joints	Welds	Ballast
OM TO RA	CM#			R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S
1	OM-5A	704+10	8-5-16	R	S	S	S	S	S	Y	S	S	S	S
2	OM-7A	704+10	8-5-16	R	S	S	S	S	S	Y	S	S	S	S
2	OM-3A	688+30	8-5-16	S	S	S	S	S	S	S	S	S	S	S
2	OM-1A	682+36	8-5-16	S	S	S	S	S	S	S	S	S	S	S
1	OM-1B	682+36	8-5-16	S	S	S	S	S	S	S	S	S	S	S
1	OM-3B	688+30	8-5-16	S	S	S	S	S	S	S	S	S	S	S
1	OC-5A	525+65	8-5-16	S	S	S	S	S	S	S	S	S	S	S
1	OC-1B	525+75	8-5-16	R	S	S	S	S	S	Y	S	S	S	S
1	OC-3B	632+26	8-5-16	R	Y	Y	S	S	S	S	S	S	S	S
2	OC-3A	632+26	8-5-16	Y	S	S	S	S	S	S	S	S	S	S
2	OC-1A	525+75	8-5-16	Y	Y	S	Y	Y	S	S	S	S	S	S

COMMENTS 3-B shoulder Bolts needs Replaced And TIES Pumping
 And RAIL MOVEMENT
 3-A LOW BALLAST FROG PUMPIE
 5-A DETERIORATING TIES AND RAIL MOVEMENT
 7-A DETERIORATING TIES AND RAIL MOVEMENT

WORK ORDER #

Inspectors A. Jefferson J. Williams Date 8-5-16 Supervisor 

Work Order Tracking (Tr)

Bull

Find Work Order



Select Action



- List
- Work Order**
- Plans
- Actuals
- Activities
- Measurements
- Axle Configuration
- Related Records
- Safety Plan
- Log

Work Order: 2510277

AREA #2(MM-RP) MOW MONTHLY MAINLINE SWITCH IN:

Classification: MTA \ METRO



Classification Description: MTA - METRO

Asset:



Allas:

Location: OLDCOURTF/ Old Court Maintenance Facility



Work Location:



Work Type: PM

Status: WSCH

Status Date: 08/02/16 04:14:08 AM

Reported By: MTACRON



Phone:

Reported Date: 08/02/16 04:14:08 AM

On Behalf Of:



Consist:



Asset Details

Year:

Manufacturer:



Model:

Serial #:

Type:

Status:

Asset Condition:

Address Information

Service Address: 1206 6301 Wabash Ave Reisterstown Plaza Baltimore



City: BALTIMOF

Formatted Address:

State/Province: MD



MOW MONTHLY MANILINE SWITCH INSPECTION AREA #2 MM-RP

Track	Switch I.D.	Location	Inspection Date	Tie Condition	Switch Pnts L/R	Closure S/C	Frog	Stock Rail	Plates	Lags/Clips	Standard Joints	Insulated Joints	Welds	Ballast
OM TO RA	CM#			R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S
1	MM-3	439+35	8-18-16	R	S	S	S	S	S	Y	S	S	S	S
2	MM-1A	439+35	8-18-16	R	S	S	Y	S	S	Y	S	S	S	S
1	RP-3B	389+35	8-18-16	R	S	S	Y	S	S	Y	S	S	S	S
1	RP-1B	391+05	8-18-16	S	S	S	Y	S	S	Y	S	S	S	S
2	RP-3A	391+05	8-18-16	S	S	S	Y	S	S	Y	S	S	S	S
2	RP-1A	389+35	8-18-16	S	S	S	Y	S	S	Y	S	S	S	S
2	RP-17	376+60	8-18-16	Y	S	S	Y	S	S	S	S	S	S	N/A
1	RP-21	376+80	8-18-16	R	S	S	Y	S	S	S	S	S	S	N/A
1	RP-19B	376+60	8-18-16	R	S	S	Y	S	S	S	S	S	S	N/A

COMMENTS

WORK ORDER #

Inspectors A. JEFFERSON C. Charden Date 8-18-16 Supervisor 

Work Order Tracking (Tr)

Bull

Find Work Order

Select Action

List

Work Order

Plans

Actuals

Activities

Measurements

Axle Configuration

Related Records

Safety Plan

Log

Work Order: 2510281

AREA #3(RA-PO) MOW MONTHLY MAINLINE SWITCH INS

Classification: MTA \ METRO

Classification Description: MTA - METRO

Asset: >>

Alias:

Location: OLDCOURTF/ >> Old Court Maintenance Facility

Work Location: >>

Work Type: PM

Status: WSCH

Status Date: 08/02/16 04:14:10 AM

Reported By: MTACRON >>

Phone:

Reported Date: 08/02/16 04:14:10 AM

On Behalf Of: >>

Consist: >>

Asset Details

Year:

Manufacturer: >>

Model: >>

Serial #:

Type: >>

Status:

Asset Condition:

Address Information

Service Address: 1206 >> 6301 Wabash Ave Reisterstown Plaza Baltimore

City: BALTIMOR

Formatted Address:

State/Province: MD

MOW MONTHLY MANILINE SWITCH INSPECTION AREA #3 RA-PO

Track	Switch I.D.	Location	Inspection Date	Tie Condition	Switch Pnts L/R	Closure S/C	Frog	Stock Rail	Plates	Lags/Clips	Standard Joints	Insulated Joints	Welds	Ballast
RA TO OM	CM#	Date	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S
1	RA-3B	351+25	8-15-16	S	S	S	S	S	S	S	S	S	S	S
1	RA-1B	344+15	8-15-16	S	S	S	S	S	S	S	S	S	S	S
1	RA-5A	348+55	8-15-16	S	S	S	S	S	S	S	S	S	S	S
1	RA-7B	349+10	8-15-16	S	S	S	S	S	S	S	S	S	S	S
2	RA-9A	348+10	8-15-16	S	S	S	X	S	S	S	S	S	S	S
2	RA-3A	344+15	8-15-16	S	S	S	S	S	S	S	S	S	S	S
2	RA-1A	341+25	8-15-16	S	S	S	S	S	S	S	S	S	S	S
1	PO-3B	229+10	8-15-16	S	S	S	S	S	S	S	S	S	S	S
1	PO-1B	230+80	8-15-16	S	S	S	S	S	S	S	S	S	S	S
2	PO-7B	332+46	8-15-16	S	S	S	S	S	S	S	S	S	S	S
2	PO-3A	230+80	8-15-16	S	S	S	S	S	S	S	S	S	S	S
2	PO-1A	229+10	8-15-16	S	S	S	S	S	S	S	S	S	S	S
2	PO-5B	227+40	8-15-16	S	S	S	S	S	S	S	S	S	S	S

COMMENTS:

WORK ORDER #

Inspectors A. JEFFERSON C. CHANDLER Date 8-15-16 Supervisor 