

Work Order Tracking (Tr)

Bull

Find Work Order

Select Action

List

Work Order

Plans

Actuals

Activities

Measurements

Axle Configuration

Related Records

Safety Plan

Log

Work Order: 2331545

(1JH-RA) METRO MOW WEEKLY TRACK INSPECTION W/

Classification: MTA \ METRO

Classification Description: MTA - METRO

Asset: >>

Alias:

Location: CHAIN_MARK >> Metro Chain Markers

Work Location: >>

* Work Type: PM

Status: WSCH

Status Date: 03/18/16 04:16:50 AM

Reported By: MTACRON >>

Phone:

Reported Date: 03/18/16 04:16:49 AM

On Behalf Of: >>

Consist: >>

Asset Details

Year:

Manufacturer: >>

Model: >>

Serial #:

Type: >>

Status:

Asset Condition:

Address Information

Service Address: >>

Formatted Address:

City:

State/Province:

WEEKLY TRACK WALKING INSPECTION REPORTING FORM

Name William Chandler Date 3/22/16 Page 1 of 1
 (Please Print)

Inspected From JH To RA ML # 1 WO# **2331545**

Item	Exception Chain Marker No.		Track No.	Rail N/S	Switch No.	Codes		Status S/Y/R	Repair Y/N	W. O. #
	From	To				Comp.	Defect			
1.	75+90		1		1A	S04	D01	Y	N	
2.	068+30		1	S		S04	D06	Y	N	
3.	230+90		1	N		R01	D01	Y	N	
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										
13.										
14.										
15.										
17.										
18.										
19.										
20.										

Item	COMMENTS
1	SWITCH # 3B POINT BATTERED
2	068+30 Diamond Point is Pitted To be Watched
3	230+90 Insulated Joint Battered
4	

J.W. C.C.
 Trackwalkers Signature

 Supervisory Certification

Work Order	Description	Status	Reported Date
2053299	1 JHRA RH Switch Point Chipped / Pitted CC 3B	MONITOR	08/20/15 07:55:47 AM
2053301	1 JHRA LH Switch Point Chipped / Pitted CC 3B	MONITOR	08/20/15 07:59:08 AM
2015114	1 JHRA Coverboard Missing (70') 162-162+50 & 162+70-162+90	WMATL	07/22/15 08:42:01 AM
2013812	1 JHRA Fastener Pad Cracked/Broken (6) 018+60W	HOLD	07/21/15 12:10:23 PM
2087957	1 JHRA Two Block Tie Broken/Unsupported 013+60W	COMP	09/16/15 07:38:35 AM
2087964	1 JHRA Running Rail Deteriorated (S) 154 -165	MONITOR	09/16/15 07:42:56 AM
2106086	1 JHRA Drain Clogged/Fouled (600') 053W-059W	APPR	09/30/15 07:26:22 AM
2106102	1 JHRA Coverboard Bracket Broken 107+15	APPR	09/30/15 07:30:42 AM
2106107	1 JHRA Station Concrete Wall/Ceiling Cracked 107+80	MONITOR	09/30/15 07:33:39 AM
2106112	1 JHRA 3rd Rail Unseated/Out of Insulator Cups 148+00	APPR	09/30/15 07:38:06 AM
2106121	1 JHRA Rail Web/Base Corroded (N) 151+50	MONITOR	09/30/15 07:47:48 AM
2106126	1 JHRA Rail Web/Base Corroded (N) 154-165	APPR	09/30/15 07:51:23 AM
2106133	1 JHRA Two Block Tie Broken 157+30	APPR	09/30/15 07:57:51 AM
2106138	1 JHRA Two Block Tie Broken 161+25	APPR	09/30/15 08:01:21 AM
1036885	1 JHRA Tunnel Leak CC 3B 005 NW	MONITOR	04/11/13 07:58:55 AM
2015112	1 JHRA Coverboard Missing 10' CC 007+10W	WMATL	07/22/15 08:38:35 AM
2013741	1 JHRA Shim Plate Loose 237+50	APPR	07/21/15 11:01:27 AM
2013746	1 JHRA Saddles Loose (5) Pandrols Missing PO1B	APPR	07/21/15 11:07:57 AM
2013748	1 JHRA Running Rail Wheel Burns (N) 230+00	APPR	07/21/15 11:15:10 AM
2013865	1 JHRA Restraining Rail IJ Bolts Loose 067+70E	APPR	07/21/15 01:07:32 PM
2014064	1 JHRA Coverboard Brackets Bent 267+50 - 272	APPR	07/21/15 03:40:25 PM
2014921	1 JHRA Insulator Cup Burnt (4) 140+70 -140+90	APPR	07/22/15 05:41:56 AM
2015100	1 JHRA Coverboard Broken / Bracket Missing 036+65E	APPR	07/22/15 08:15:11 AM
2015101	1 JHRA Coverboard Brackets Missing 194+90 & 195+25	APPR	07/22/15 08:17:16 AM
2015102	1 JHRA Coverboard Missing (60') 158 -158+60	WMATL	07/22/15 08:19:25 AM
2015104	1 JHRA Coverboard Missing 069+10E - 068+40E	WMATL	07/22/15 08:28:23 AM
2015107	1 JHRA Coverboard Missing (60') 078W	WMATL	07/22/15 08:31:45 AM
2015388	1 JHRA 3rd Rail Corroded 141+00	APPR	07/22/15 02:54:07 PM
2017678	1 JHRA Adjustable Brace Plate Missing 229+70 PO-3B	APPR	07/24/15 08:18:26 AM
2017699	1 JHRA 3rd Rail Side Approach Hardware Missing CC 1B 007+50	APPR	07/24/15 09:01:09 AM
2017722	1 JHRA LB Foster Plates Deteriorating 238 - 268	APPR	07/24/15 09:46:52 AM
2017696	1 JHRA Guard Rail Screw Spikes Missing PO 3B	APPR	07/24/15 08:54:29 AM
2017716	1 JHRA Guard Rail Screw Spikes Missing PO 1B	APPR	07/24/15 09:34:45 AM
2017718	1 JHRA Insulated Joint Chipped (S) 230+90 ✓	MONITOR	07/24/15 09:41:36 AM
2013896	1 JHRA Gage Tight (56 3/8") 236 - 242+00	APPR	07/21/15 01:49:09 PM
2021953	1 JHRA LB Foster Anchor Bolts Loose 235-332	APPR	07/28/15 10:15:42 AM
2030698	1 JHRA IJ Battered BH-3B 066+80W	MONITOR	08/03/15 06:16:38 AM
2030709	1 JHRA Switch Point Chipped BH-1B 069+30W	MONITOR	08/03/15 06:34:06 AM
2030745	1 JHRA Shim Plate Missing 248+10W	APPR	08/03/15 06:55:13 AM
2041954	1 JHRA RH Switch Point Wheel Burns PO 3B 229	MONITOR	08/11/15 03:06:34 PM
2043013	1 JHRA Rail Corrugation (N) 202 - 214+00	MONITOR	08/12/15 07:55:00 AM

2051473	1 JHRA 3rd Rail Deteriorated 158 -166+00	MONITOR	08/19/15 07:34:44 AM
2033296	1 JHRA Curve Closure Rail Chipped 067+60E JH 1B	MONITOR	08/05/15 03:16:44 PM
2058572	1 JHRA Front Rod Nut Loose PO 3B 229+00	APPR	08/25/15 06:33:08 AM
2059899	1 JHRA Frog Riser Cracked JH 3B	APPR	08/26/15 05:42:36 AM
2050074	1 JHRA Frog Point/Riser Worn PO 1B	APPR	08/18/15 04:32:57 AM
2080337	1 JHRA 3rd Rail Severely Corroded 068+70 - 068+90	APPR	09/10/15 07:56:55 AM
2061165	1 JHRA Coverboard Missing 184-186	WMATL	08/27/15 07:52:38 AM
2077038	1 JHRA #3 Switch Rod Striking Timber PO 1B 230+70	APPR	09/08/15 03:56:49 PM
2080383	1 JHRA Insulated Tie Plate Missing 230+15	APPR	09/10/15 08:08:32 AM
2030720	1 JHRA IJ Battered BH 1B 069+35W	APPR	08/03/15 06:40:43 AM
2014045	1 JHRA Interlocking Out of Surface PO 228-232+00	HOLD	07/21/15 03:19:37 PM
2030726	1 JHRA RH Stock Rail Wheel Burns PO 1B 230+90	MONITOR	08/03/15 06:47:19 AM
2030747	1 JHRA Rail Side Worn (22 Deg) 274+00	MONITOR	08/03/15 06:59:44 AM
1042501	1 JHRA Rail Side Worn (N) (26-28 deg) 248 - 256+00	REVIEW	04/16/13 03:18:04 PM
2015378	1 JHRA Rail Web/Base Deteriorated (S) 141+00	APPR	07/22/15 02:44:48 PM
2089704	1 JHRA Stock Rail Wheel Burns/Top Worn/Chipped PO 3B 229+10	MONITOR	09/17/15 07:50:57 AM
2013893	1 JHRA Running Rail Wheel Burns (N/S) 234+90	APPR	07/21/15 01:46:12 PM
2106039	1 JHRA 4 Gauge Rods / 2 Block Ties 071W - 071+15	MONITOR	09/30/15 06:34:11 AM
2106077	1 JHRA Rail Corrugation/Pitted/Gouged (S) 053W-059W	MONITOR	09/30/15 07:21:19 AM
2194899	1 JHRA Expansion Joint Burnt / Arching 305+80	INPRG	12/01/15 04:03:10 AM
2204233	1 JHRA Warp (-1.83"-13') cm#330+41 (Holland Report) URGENT	MONITOR	12/07/15 05:32:08 AM
2204238	1 JHRA Warp (-1.96"-37') cm#330+13 (Holland Report) URGENT	MONITOR	12/07/15 05:42:50 AM
2204242	1 JHRA Warp (-1.94"-26') cm#231+07 (Holland Report) URGENT	MONITOR	12/07/15 05:49:24 AM
2204247	1 JHRA Warp (-2.13"-24') cm#230+74 (Holland Report) URGENT	MONITOR	12/07/15 06:03:04 AM
2204253	1 JHRA Unbl. (25.38 - 938') cm#018+87 (Holland Report) URGENT	MONITOR	12/07/15 06:42:41 AM
2204266	1 JHRA Vmax. (40.71-938') cm#019+09 (Holland Report) URGENT	MONITOR	12/07/15 06:53:10 AM
2205671	1 JHRA Two Block Tie Broken 018+25W	COMP	12/08/15 06:54:55 AM
2208897	1 JHRA Chain Marker Sign 160NW Loose/Hanging	APPR	12/10/15 04:02:28 PM
2208896	1 JHRA Two Block Tie Broken 158+40W	APPR	12/10/15 03:58:16 PM
2106032	1 JHRA Defective Lord Pads / Gauge Rods Installed 062E - 057E	MONITOR	09/30/15 06:13:49 AM
2212343	1 JHRA Pandrol Clips Broken/Deteriorating 160W-170W	APPR	12/12/15 07:36:37 AM
2058584	1 JHRA Track Bolt Loose/ Worn (Replace) 229+80	APPR	08/25/15 06:40:59 AM
2220227	1 JHRA Rail Wheel Burn 229+90	MONITOR	12/18/15 11:19:01 AM
2212359	1 JHRA Rail Side Worn 3/8" (30 Deg) 211 - 227	MONITOR	12/12/15 08:11:20 AM
2220221	1 JHRA Closure Rail Wheel Burns (4) PO 3B 229+40	MONITOR	12/18/15 11:06:09 AM
2220224	1 JHRA Standard Joint / Frog Heel Wing Rail Chipped 229+85 PO 3 B	MONITOR	12/18/15 11:11:21 AM
2212324	1 JHRA Rail Base Corroded (N) 045+70-046+30	MONITOR	12/12/15 07:15:13 AM
2212327	1 JHRA Rail Head Pitted (S) 070W - 081W	MONITOR	12/12/15 07:19:51 AM

2212336	1 JHRA Rail Side Worn (Tangent) 084+10 - 084+30	MONITOR	12/12/15 07:25:20 AM
2212341	1 JHRA Rail Corrugation 089+00 - 089+20	MONITOR	12/12/15 07:29:55 AM
2212351	1 JHRA Rail Side Worn 3/8" (23 Deg) 163 - 171	MONITOR	12/12/15 07:44:51 AM
2212357	1 JHRA Rail Head Pitted (N) 163 - 171	MONITOR	12/12/15 07:58:26 AM
2212358	1 JHRA Rail Head Pitted (N) 181 - 186	MONITOR	12/12/15 08:06:50 AM
2208898	1 JHRA Rail Pitted / Water Condition 160+60W	MONITOR	12/10/15 04:07:28 PM
2212310	1 JHRA Rail Corroded (N) 037+20	MONITOR	12/12/15 07:08:21 AM
2043305	1 JHRA Two Block Tie Deteriorating (N) 013+85W	INPRG	08/12/15 03:07:39 PM
2043299	1 JHRA Two Block Tie Deteriorating (N) 015+75W	INPRG	08/12/15 03:03:16 PM
2220233	1 JHRA Closure Rail Battered/Wheel Burns (2) PO 1B 230+55	MONITOR	12/18/15 11:35:22 AM
2245860	1 JHRA LH Switch Point Worn PO 1B 230+80	MONITOR	01/08/16 09:43:10 AM
2246787	1 JHRA Front Rod Nut Loose PO 1B 230+80	APPR	01/09/16 07:22:51 AM
2274510	1 JHRA Two Heel Block Bolts Loose BH 1B 069+00W	COMP	02/03/16 03:07:18 PM

Work Order Tracking (Tr)

Bull

Find Work Order

Select Action



- List
- Work Order
- Plans
- Actuals
- Activities
- Measurements
- Axle Configuration
- Related Records
- Safety Plan
- Log

Work Order: 2340378

(2RA-JH) METRO MOW WEEKLY TRACK INSPECTION W/

Classification: MTA \ METRO

Classification Description: MTA - METRO

Asset: >>

Alias:

Location: CHAIN_MARK >> Metro Chain Markers

Work Location: >>

Work Type: PM

Status: WSCH

Status Date: 03/25/16 04:15:36 AM

Reported By: MTACRON >>

Phone:

Reported Date: 03/25/16 04:15:36 AM

On Behalf Of: >>

Consist: >>

Asset Details

Year:

Manufacturer: >>

Model: >>

Serial #:

Type: >>

Status:

Asset Condition:

Address Information

Service Address: >>

Formatted Address:

City:

State/Province: